

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/19/06	06BR0571-01	Southwest Area (sidewalk bridge level)	4/19/06	0.57	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST2-4/19/06	06BR0571-02	Southeast Area (sidewalk bridge level)	4/19/06	0.58	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST4-4/19/06	06BR0571-03	Northwest Area (street-level)	4/19/06	0.57	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST5-4/19/06	06BR0571-04	Firehouse #10 (roof level)	4/19/06	0.56	Mercury	EPA 324/1631	BRL	4/21/06	< 27.0	No	No	
TotalHg-ST10-4/19/06	06BR0571-05	North Side Sidewalk Bridge	4/19/06	0.57	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST11-4/19/06	06BR0571-06	90 Trinity Place (roof level)	4/19/06	0.57	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST12-4/19/06	06BR0571-07	110 Greenwich Street (roof level)	4/19/06	0.59	Mercury	EPA 324/1631	BRL	4/21/06	< 25.0	No	No	
TotalHg-ST13-4/19/06	06BR0571-08	Marriott Hotel, 38th Floor (roof level)	4/19/06	0.58	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST14-4/19/06	06BR0571-09	West Face - South end at corner (scaffolding level)	4/19/06	0.57	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST15-4/19/06	06BR0571-10	South Face - East end at corner (scaffolding level)	4/19/06	0.57	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST16-4/19/06	06BR0571-11	East Face - North end at corner (scaffolding level)	4/19/06	0.57	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
TotalHg-ST17-4/19/06	06BR0571-12	North Face - West end at corner (scaffolding level)	4/19/06	0.57	Mercury	EPA 324/1631	BRL	4/21/06	< 26.0	No	No	
Total Hg-ST1-4/20/06	06BR0575-01	Southwest Area (sidewalk bridge level)	4/20/06	0.57	Mercury	EPA 324/1631	BRL	4/22/06	< 26.0	No	No	
Total Hg-ST2-4/20/06	06BR0575-02	Southeast Area (sidewalk bridge level)	4/20/06	0.57	Mercury	EPA 324/1631	BRL	4/22/06	< 26.0	No	No	
Total Hg-ST4-4/20/06	06BR0575-03	Northwest Area (street-level)	4/20/06	0.58	Mercury	EPA 324/1631	BRL	4/22/06	< 26.0	No	No	
Total Hg-ST5-4/20/06	06BR0575-04	Firehouse #10 (roof level)	4/20/06	0.59	Mercury	EPA 324/1631	BRL	4/22/06	< 25.0	No	No	
Total Hg-ST10-4/20/06	06BR0575-05	North Side Sidewalk Bridge	4/20/06	0.59	Mercury	EPA 324/1631	BRL	4/22/06	< 25.0	No	No	
Total Hg-ST11-4/20/06	06BR0575-06	90 Trinity Place (roof level)	4/20/06	0.58	Mercury	EPA 324/1631	BRL	4/22/06	< 26.0	No	No	
Total Hg-ST12-4/20/06	06BR0575-07	110 Greenwich Street (roof level)	4/20/06	0.60	Mercury	EPA 324/1631	BRL	4/22/06	< 25.0	No	No	
Total Hg-ST13-4/20/06	06BR0575-08	Marriott Hotel, 38th Floor (roof level)	4/20/06	0.58	Mercury	EPA 324/1631	BRL	4/22/06	< 26.0	No	No	
Total Hg-ST14-4/20/06	06BR0575-09	West Face - South end at corner (scaffolding level)	4/20/06	0.59	Mercury	EPA 324/1631	BRL	4/22/06	< 25.0	No	No	
Total Hg-ST15-4/20/06	06BR0575-10	South Face - East end at corner (scaffolding level)	4/20/06	0.59	Mercury	EPA 324/1631	BRL	4/22/06	< 25.0	No	No	
Total Hg-ST16-4/20/06	06BR0575-11	East Face - North end at corner (scaffolding level)	4/20/06	0.59	Mercury	EPA 324/1631	BRL	4/22/06	< 25.0	No	No	
Total Hg-ST17-4/20/06	06BR0575-12	North Face - West end at corner (scaffolding level)	4/20/06	0.59	Mercury	EPA 324/1631	BRL	4/22/06	< 25.0	No	No	