

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
									300	Air Quality Levels	Site Specific Trigger Levels	
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-4/20/07	07BR0522-01	Southwest Area (sidewalk bridge level)	4/20/07	0.56	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST2-4/20/07	07BR0522-02	Southeast Area (sidewalk bridge level)	4/20/07	0.60	Mercury	EPA 324/1631	BRL	4/24/07	< 25.0	No	No	
TotalHg-ST4-4/20/07	07BR0522-03	Northwest Area (street-level)	4/20/07	0.55	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST5-4/20/07	07BR0522-04	Firehouse #10 (roof level)	4/20/07	0.54	Mercury	EPA 324/1631	BRL	4/24/07	< 28.0	No	No	
TotalHg-ST10-4/20/07	07BR0522-05	North Side Sidewalk Bridge	4/20/07	0.60	Mercury	EPA 324/1631	BRL	4/24/07	< 25.0	No	No	
TotalHg-ST11-4/20/07	07BR0522-06	90 Trinity Place (roof level)	4/20/07	0.58	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST12-4/20/07	07BR0522-07	110 Greenwich Street (roof level)	4/20/07	0.58	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST13-4/20/07	07BR0522-08	Marriott Hotel, 38th Floor (roof level)	4/20/07	0.56	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST14-4/20/07	07BR0522-09	West Face - South end at corner (scaffolding level)	4/20/07	0.56	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST15-4/20/07	07BR0522-10	South Face - East end at corner (scaffolding level)	4/20/07	0.57	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST16-4/20/07	07BR0522-11	East Face - North end at corner (scaffolding level)	4/20/07	0.54	Mercury	EPA 324/1631	BRL	4/24/07	< 28.0	No	No	
TotalHg-ST17-4/20/07	07BR0522-12	North Face - West end at corner (scaffolding level)	4/20/07	0.54	Mercury	EPA 324/1631	BRL	4/24/07	< 28.0	No	No	
TotalHg-ST1-4/21/07	07BR0523-01	Southwest Area (sidewalk bridge level)	4/21/07	0.59	Mercury	EPA 324/1631	BRL	4/24/07	< 25.0	No	No	
TotalHg-ST2-4/21/07	07BR0523-02	Southeast Area (sidewalk bridge level)	4/21/07	0.61	Mercury	EPA 324/1631	BRL	4/24/07	< 25.0	No	No	
TotalHg-ST4-4/21/07	07BR0523-03	Northwest Area (street-level)	4/21/07	0.55	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST5-4/21/07	07BR0523-04	Firehouse #10 (roof level)	4/21/07	0.57	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST10-4/21/07	07BR0523-05	North Side Sidewalk Bridge	4/21/07	0.58	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST11-4/21/07	07BR0523-06	90 Trinity Place (roof level)	4/21/07	0.59	Mercury	EPA 324/1631	BRL	4/24/07	< 25.0	No	No	
TotalHg-ST12-4/21/07	07BR0523-07	110 Greenwich Street (roof level)	4/21/07	0.56	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST13-4/21/07	07BR0523-08	Marriott Hotel, 38th Floor (roof level)	4/21/07	0.56	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST14-4/21/07	07BR0523-09	West Face - South end at corner (scaffolding level)	4/21/07	0.55	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST15-4/21/07	07BR0523-10	South Face - East end at corner (scaffolding level)	4/21/07	0.56	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST16-4/21/07	07BR0523-11	East Face - North end at corner (scaffolding level)	4/21/07	0.57	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST17-4/21/07	07BR0523-12	North Face - West end at corner (scaffolding level)	4/21/07	0.59	Mercury	EPA 324/1631	BRL	4/24/07	< 25.0	No	No	
TotalHg-ST1-4/22/07	07BR0524-01	Southwest Area (sidewalk bridge level)	4/22/07	0.53	Mercury	EPA 324/1631	BRL	4/24/07	< 28.0	No	No	
TotalHg-ST2-4/22/07	07BR0524-02	Southeast Area (sidewalk bridge level)	4/22/07	0.55	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST4-4/22/07	07BR0524-03	Northwest Area (street-level)	4/22/07	0.52	Mercury	EPA 324/1631	BRL	4/24/07	< 29.0	No	No	
TotalHg-ST5-4/22/07	07BR0524-04	Firehouse #10 (roof level)	4/22/07	0.58	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST10-4/22/07	07BR0524-05	North Side Sidewalk Bridge	4/22/07	0.63	Mercury	EPA 324/1631	BRL	4/24/07	< 24.0	No	No	
TotalHg-ST11-4/22/07	07BR0524-06	90 Trinity Place (roof level)	4/22/07	0.55	Mercury	EPA 324/1631	BRL	4/24/07	< 27.0	No	No	
TotalHg-ST12-4/22/07	07BR0524-07	110 Greenwich Street (roof level)	4/22/07	0.53	Mercury	EPA 324/1631	BRL	4/24/07	< 28.0	No	No	
TotalHg-ST13-4/22/07	07BR0524-08	Marriott Hotel, 38th Floor (roof level)	4/22/07	0.57	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST14-4/22/07	07BR0524-09	West Face - South end at corner (scaffolding level)	4/22/07	0.58	Mercury	EPA 324/1631	BRL	4/24/07	< 26.0	No	No	
TotalHg-ST15-4/22/07	07BR0524-10	South Face - East end at corner (scaffolding level)	4/22/07	0.61	Mercury	EPA 324/1631	BRL	4/24/07	< 25.0	No	No	
TotalHg-ST16-4/22/07	07BR0524-11	East Face - North end at corner (scaffolding level)	4/22/07	0.59	Mercury	EPA 324/1631	BRL	4/24/07	< 25.0	No	No	
TotalHg-ST17-4/22/07	07BR0524-12	North Face - West end at corner (scaffolding level)	4/22/07	0.63	Mercury	EPA 324/1631	BRL	4/24/07	< 24.0	No	No	