

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/26/08	0818007-01	Southwest Area (sidewalk bridge level)	4/26/08	0.55	Mercury	EPA 324/1631	BRL	4/29/08	< 27.0	No	No	
TotalHg-ST2-4/26/08	0818007-02	Southeast Area (sidewalk bridge level)	4/26/08	0.54	Mercury	EPA 324/1631	BRL	4/29/08	< 28.0	No	No	
TotalHg-ST4-4/26/08	0818007-03	Northwest Area (street-level)	4/26/08	0.56	Mercury	EPA 324/1631	BRL	4/29/08	< 27.0	No	No	
TotalHg-ST5-4/26/08	0818007-04	Firehouse #10 (roof level)	4/26/08	0.56	Mercury	EPA 324/1631	BRL	4/29/08	< 27.0	No	No	
TotalHg-ST10-4/26/08	0818007-05	North Side Sidewalk Bridge	4/26/08	0.55	Mercury	EPA 324/1631	BRL	4/29/08	< 27.0	No	No	
TotalHg-ST11-4/26/08	0818007-06	90 Trinity Place (roof level)	4/26/08	0.61	Mercury	EPA 324/1631	BRL	4/29/08	< 25.0	No	No	
TotalHg-ST12-4/26/08	0818007-07	110 Greenwich Street (roof level)	4/26/08	0.53	Mercury	EPA 324/1631	BRL	4/29/08	< 28.0	No	No	
TotalHg-ST13-4/26/08	0818007-08	Marriott Hotel, 38th Floor (roof level)	4/26/08	0.55	Mercury	EPA 324/1631	BRL	4/29/08	< 27.0	No	No	
TotalHg-ST14-4/26/08	0818007-09	West Face - South end at corner (scaffolding level)	4/26/08	0.56	Mercury	EPA 324/1631	BRL	4/29/08	< 27.0	No	No	
TotalHg-ST15-4/26/08	0818007-10	South Face - East end at corner (scaffolding level)	4/26/08	0.57	Mercury	EPA 324/1631	BRL	4/29/08	< 26.0	No	No	
TotalHg-ST16-4/26/08	0818007-11	East Face - North end at corner (scaffolding level)	4/26/08	0.56	Mercury	EPA 324/1631	BRL	4/29/08	< 27.0	No	No	
TotalHg-ST17-4/26/08	0818007-12	North Face - West end at corner (scaffolding level)	4/26/08	0.54	Mercury	EPA 324/1631	BRL	4/29/08	< 28.0	No	No	
TotalHg-ST1-4/27/08	0818008-01	Southwest Area (sidewalk bridge level)	4/27/08	0.60	Mercury	EPA 324/1631	BRL	4/29/08	< 25.0	No	No	
TotalHg-ST2-4/27/08	0818008-02	Southeast Area (sidewalk bridge level)	4/27/08	0.58	Mercury	EPA 324/1631	BRL	4/29/08	< 26.0	No	No	
TotalHg-ST4-4/27/08	0818008-03	Northwest Area (street-level)	4/27/08	0.60	Mercury	EPA 324/1631	BRL	4/29/08	< 25.0	No	No	
TotalHg-ST5-4/27/08	0818008-04	Firehouse #10 (roof level)	4/27/08	0.57	Mercury	EPA 324/1631	BRL	4/29/08	< 26.0	No	No	
TotalHg-ST10-4/27/08	0818008-05	North Side Sidewalk Bridge	4/27/08	0.56	Mercury	EPA 324/1631	BRL	4/29/08	< 27.0	No	No	
TotalHg-ST11-4/27/08	0818008-06	90 Trinity Place (roof level)	4/27/08	0.53	Mercury	EPA 324/1631	BRL	4/29/08	< 28.0	No	No	
TotalHg-ST12-4/27/08	0818008-07	110 Greenwich Street (roof level)	4/27/08	0.54	Mercury	EPA 324/1631	BRL	4/29/08	< 28.0	No	No	
TotalHg-ST13-4/27/08	0818008-08	Marriott Hotel, 38th Floor (roof level)	4/27/08	0.59	Mercury	EPA 324/1631	BRL	4/29/08	< 25.0	No	No	
TotalHg-ST14-4/27/08	0818008-09	West Face - South end at corner (scaffolding level)	4/27/08	0.60	Mercury	EPA 324/1631	BRL	4/29/08	< 25.0	No	No	
TotalHg-ST15-4/27/08	0818008-10	South Face - East end at corner (scaffolding level)	4/27/08	0.60	Mercury	EPA 324/1631	BRL	4/29/08	< 25.0	No	No	
TotalHg-ST16-4/27/08	0818008-11	East Face - North end at corner (scaffolding level)	4/27/08	0.57	Mercury	EPA 324/1631	BRL	4/29/08	< 26.0	No	No	
TotalHg-ST17-4/27/08	0818008-12	North Face - West end at corner (scaffolding level)	4/27/08	0.63	Mercury	EPA 324/1631	BRL	4/29/08	< 24.0	No	No	
TotalHg-ST1-4/28/08	0818027-01	Southwest Area (sidewalk bridge level)	4/28/08	0.61	Mercury	EPA 324/1631	BRL	4/30/08	< 25.0	No	No	
TotalHg-ST2-4/28/08	0818027-02	Southeast Area (sidewalk bridge level)	4/28/08	0.59	Mercury	EPA 324/1631	BRL	4/30/08	< 25.0	No	No	
TotalHg-ST4-4/28/08	0818027-03	Northwest Area (street-level)	4/28/08	0.62	Mercury	EPA 324/1631	BRL	4/30/08	< 24.0	No	No	
TotalHg-ST5-4/28/08	0818027-04	Firehouse #10 (roof level)	4/28/08	0.56	Mercury	EPA 324/1631	BRL	4/30/08	< 27.0	No	No	
TotalHg-ST10-4/28/08	0818027-05	North Side Sidewalk Bridge	4/28/08	0.57	Mercury	EPA 324/1631	BRL	4/30/08	< 26.0	No	No	
TotalHg-ST11-4/28/08	0818027-06	90 Trinity Place (roof level)	4/28/08	0.55	Mercury	EPA 324/1631	BRL	4/30/08	< 27.0	No	No	
TotalHg-ST12-4/28/08	0818027-07	110 Greenwich Street (roof level)	4/28/08	0.58	Mercury	EPA 324/1631	BRL	4/30/08	< 26.0	No	No	
TotalHg-ST13-4/28/08	0818027-08	Marriott Hotel, 38th Floor (roof level)	4/28/08	0.57	Mercury	EPA 324/1631	BRL	4/30/08	< 26.0	No	No	
TotalHg-ST14-4/28/08	0818027-09	West Face - South end at corner (scaffolding level)	4/28/08	0.56	Mercury	EPA 324/1631	BRL	4/30/08	< 27.0	No	No	
TotalHg-ST15-4/28/08	0818027-10	South Face - East end at corner (scaffolding level)	4/28/08	0.54	Mercury	EPA 324/1631	BRL	4/30/08	< 28.0	No	No	
TotalHg-ST16-4/28/08	0818027-11	East Face - North end at corner (scaffolding level)	4/28/08	0.58	Mercury	EPA 324/1631	BRL	4/30/08	< 26.0	No	No	
TotalHg-ST17-4/28/08	0818027-12	North Face - West end at corner (scaffolding level)	4/28/08	0.56	Mercury	EPA 324/1631	BRL	4/30/08	< 27.0	No	No	
TotalHg-ST1-4/29/08	0818036-01	Southwest Area (sidewalk bridge level)	4/29/08	0.61	Mercury	EPA 324/1631	BRL	5/1/08	< 25.0	No	No	
TotalHg-ST2-4/29/08	0818036-02	Southeast Area (sidewalk bridge level)	4/29/08	0.58	Mercury	EPA 324/1631	BRL	5/1/08	< 26.0	No	No	
TotalHg-ST4-4/29/08	0818036-03	Northwest Area (street-level)	4/29/08	0.57	Mercury	EPA 324/1631	BRL	5/1/08	< 26.0	No	No	
TotalHg-ST5-4/29/08	0818036-04	Firehouse #10 (roof level)	4/29/08	0.57	Mercury	EPA 324/1631	BRL	5/1/08	< 26.0	No	No	
TotalHg-ST10-4/29/08	0818036-05	North Side Sidewalk Bridge	4/29/08	0.54	Mercury	EPA 324/1631	BRL	5/1/08	< 28.0	No	No	
TotalHg-ST11-4/29/08	0818036-06	90 Trinity Place (roof level)	4/29/08	0.55	Mercury	EPA 324/1631	BRL	5/1/08	< 27.0	No	No	
TotalHg-ST12-4/29/08	0818036-07	110 Greenwich Street (roof level)	4/29/08	0.55	Mercury	EPA 324/1631	BRL	5/1/08	< 27.0	No	No	
TotalHg-ST13-4/29/08	0818036-08	Marriott Hotel, 38th Floor (roof level)	4/29/08	0.55	Mercury	EPA 324/1631	BRL	5/1/08	< 27.0	No	No	
TotalHg-ST14-4/29/08	0818036-09	West Face - South end at corner (scaffolding level)	4/29/08	0.59	Mercury	EPA 324/1631	BRL	5/1/08	< 25.0	No	No	
TotalHg-ST15-4/29/08	0818036-10	South Face - East end at corner (scaffolding level)	4/29/08	0.52	Mercury	EPA 324/1631	BRL	5/1/08	< 29.0	No	No	
TotalHg-ST16-4/29/08	0818036-11	East Face - North end at corner (scaffolding level)	4/29/08	0.56	Mercury	EPA 324/1631	BRL	5/1/08	< 27.0	No	No	
TotalHg-ST17-4/29/08	0818036-12	North Face - West end at corner (scaffolding level)	4/29/08	0.58	Mercury	EPA 324/1631	BRL	5/1/08	< 26.0	No	No	