

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-5/3/06	06BR0652-01	Southwest Area (sidewalk bridge level)	5/3/06	0.57	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST2-5/3/06	06BR0652-02	Southeast Area (sidewalk bridge level)	5/3/06	0.57	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST4-5/3/06	06BR0652-03	Northwest Area (street-level)	5/3/06	0.57	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST5-5/3/06	06BR0652-04	Firehouse #10 (roof level)	5/3/06	0.57	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST10-5/3/06	06BR0652-05	North Side Sidewalk Bridge	5/3/06	0.57	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST11-5/3/06	06BR0652-06	90 Trinity Place (roof level)	5/3/06	0.57	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST12-5/3/06	06BR0652-07	110 Greenwich Street (roof level)	5/3/06	0.57	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST13-5/3/06	06BR0652-08	Marriott Hotel, 38th Floor (roof level)	5/3/06	0.57	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST14-5/3/06	06BR0652-09	West Face - South end at corner (scaffolding level)	5/3/06	0.58	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST15-5/3/06	06BR0652-10	South Face - East end at corner (scaffolding level)	5/3/06	0.58	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST16-5/3/06	06BR0652-11	East Face - North end at corner (scaffolding level)	5/3/06	0.58	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST17-5/3/06	06BR0652-12	North Face - West end at corner (scaffolding level)	5/3/06	0.58	Mercury	EPA 324/1631	BRL	5/5/06	< 26.0	No	No	
TotalHg-ST1-5/4/06	06BR0658-01	Southwest Area (sidewalk bridge level)	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST2-5/4/06	06BR0658-02	Southeast Area (sidewalk bridge level)	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST4-5/4/06	06BR0658-03	Northwest Area (street-level)	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST5-5/4/06	06BR0658-04	Firehouse #10 (roof level)	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST10-5/4/06	06BR0658-05	North Side Sidewalk Bridge	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST11-5/4/06	06BR0658-06	90 Trinity Place (roof level)	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST12-5/4/06	06BR0658-07	110 Greenwich Street (roof level)	5/4/06	0.58	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST13-5/4/06	06BR0658-08	Marriott Hotel, 38th Floor (roof level)	5/4/06	0.58	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST14-5/4/06	06BR0658-09	West Face - South end at corner (scaffolding level)	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST15-5/4/06	06BR0658-10	South Face - East end at corner (scaffolding level)	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	
TotalHg-ST16-5/4/06	06BR0658-11	East Face - North end at corner (scaffolding level)	5/4/06	0.56	Mercury	EPA 324/1631	BRL	5/6/06	< 27.0	No	No	
TotalHg-ST17-5/4/06	06BR0658-12	North Face - West end at corner (scaffolding level)	5/4/06	0.57	Mercury	EPA 324/1631	BRL	5/6/06	< 26.0	No	No	