

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-5/16/09	0921004-01	Southwest Area (sidewalk bridge level)	5/16/09	0.57	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST2-5/16/09	0921004-02	Southeast Area (sidewalk bridge level)	5/16/09	0.58	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST4-5/16/09	0921004-03	Northwest Area (street-level)	5/16/09	0.56	Mercury	EPA 324/1631	BRL	5/19/09	< 27.0	No	No	
TotalHg-ST5-5/16/09	0921004-04	Firehouse #10 (roof level)	5/16/09	0.58	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST10-5/16/09	0921004-05	North Side Sidewalk Bridge	5/16/09	0.57	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST11-5/16/09	0921004-06	90 Trinity Place (roof level)	5/16/09	0.56	Mercury	EPA 324/1631	BRL	5/19/09	< 27.0	No	No	
TotalHg-ST12-5/16/09	0921004-07	110 Greenwich Street (roof level)	5/16/09	0.57	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST13-5/16/09	0921004-08	Marriott Hotel, 38th Floor (roof level)	5/16/09	0.59	Mercury	EPA 324/1631	BRL	5/19/09	< 25.0	No	No	
TotalHg-ST14-5/16/09	0921004-09	West Face - South end at corner (scaffolding level)	5/16/09	0.59	Mercury	EPA 324/1631	BRL	5/19/09	< 25.0	No	No	
TotalHg-ST15-5/16/09	0921004-10	South Face - East end at corner (scaffolding level)	5/16/09	0.59	Mercury	EPA 324/1631	BRL	5/19/09	< 25.0	No	No	
TotalHg-ST16-5/16/09	0921004-11	East Face - North end at corner (scaffolding level)	5/16/09	0.55	Mercury	EPA 324/1631	BRL	5/19/09	< 27.0	No	No	
TotalHg-ST17-5/16/09	0921004-12	North Face - West end at corner (scaffolding level)	5/16/09	0.56	Mercury	EPA 324/1631	BRL	5/19/09	< 27.0	No	No	
TotalHg-ST1-5/17/09	0921005-01	Southwest Area (sidewalk bridge level)	5/17/09	0.57	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST2-5/17/09	0921005-02	Southeast Area (sidewalk bridge level)	5/17/09	0.57	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST4-5/17/09	0921005-03	Northwest Area (street-level)	5/17/09	0.56	Mercury	EPA 324/1631	BRL	5/19/09	< 27.0	No	No	
TotalHg-ST5-5/17/09	0921005-04	Firehouse #10 (roof level)	5/17/09	0.59	Mercury	EPA 324/1631	BRL	5/19/09	< 25.0	No	No	
TotalHg-ST10-5/17/09	0921005-05	North Side Sidewalk Bridge	5/17/09	0.57	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST11-5/17/09	0921005-06	90 Trinity Place (roof level)	5/17/09	0.55	Mercury	EPA 324/1631	BRL	5/19/09	< 27.0	No	No	
TotalHg-ST12-5/17/09	0921005-07	110 Greenwich Street (roof level)	5/17/09	0.57	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST13-5/17/09	0921005-08	Marriott Hotel, 38th Floor (roof level)	5/17/09	0.60	Mercury	EPA 324/1631	BRL	5/19/09	< 25.0	No	No	
TotalHg-ST14-5/17/09	0921005-09	West Face - South end at corner (scaffolding level)	5/17/09	0.59	Mercury	EPA 324/1631	BRL	5/19/09	< 25.0	No	No	
TotalHg-ST15-5/17/09	0921005-10	South Face - East end at corner (scaffolding level)	5/17/09	0.63	Mercury	EPA 324/1631	BRL	5/19/09	< 24.0	No	No	
TotalHg-ST16-5/17/09	0921005-11	East Face - North end at corner (scaffolding level)	5/17/09	0.58	Mercury	EPA 324/1631	BRL	5/19/09	< 26.0	No	No	
TotalHg-ST17-5/17/09	0921005-12	North Face - West end at corner (scaffolding level)	5/17/09	0.66	Mercury	EPA 324/1631	BRL	5/19/09	< 23.0	No	No	
TotalHg-ST1-5/18/09	0921011-01	Southwest Area (sidewalk bridge level)	5/18/09	0.57	Mercury	EPA 324/1631	BRL	5/20/09	< 26.0	No	No	
TotalHg-ST2-5/18/09	0921011-02	Southeast Area (sidewalk bridge level)	5/18/09	0.58	Mercury	EPA 324/1631	BRL	5/20/09	< 26.0	No	No	
TotalHg-ST4-5/18/09	0921011-03	Northwest Area (street-level)	5/18/09	0.56	Mercury	EPA 324/1631	BRL	5/20/09	< 27.0	No	No	
TotalHg-ST5-5/18/09	0921011-04	Firehouse #10 (roof level)	5/18/09	0.58	Mercury	EPA 324/1631	BRL	5/20/09	< 26.0	No	No	
TotalHg-ST10-5/18/09	0921011-05	North Side Sidewalk Bridge	5/18/09	0.57	Mercury	EPA 324/1631	BRL	5/20/09	< 26.0	No	No	
TotalHg-ST11-5/18/09	0921011-06	90 Trinity Place (roof level)	5/18/09	0.55	Mercury	EPA 324/1631	BRL	5/20/09	< 27.0	No	No	
TotalHg-ST12-5/18/09	0921011-07	110 Greenwich Street (roof level)	5/18/09	0.57	Mercury	EPA 324/1631	BRL	5/20/09	< 26.0	No	No	
TotalHg-ST13-5/18/09	0921011-08	Marriott Hotel, 38th Floor (roof level)	5/18/09	0.56	Mercury	EPA 324/1631	BRL	5/20/09	< 27.0	No	No	
TotalHg-ST14-5/18/09	0921011-09	West Face - South end at corner (scaffolding level)	5/18/09	0.57	Mercury	EPA 324/1631	BRL	5/20/09	< 26.0	No	No	
TotalHg-ST15-5/18/09	0921011-10	South Face - East end at corner (scaffolding level)	5/18/09	0.56	Mercury	EPA 324/1631	BRL	5/20/09	< 27.0	No	No	
TotalHg-ST16-5/18/09	0921011-11	East Face - North end at corner (scaffolding level)	5/18/09	0.54	Mercury	EPA 324/1631	BRL	5/20/09	< 28.0	No	No	
TotalHg-ST17-5/18/09	0921011-12	North Face - West end at corner (scaffolding level)	5/18/09	0.55	Mercury	EPA 324/1631	BRL	5/20/09	< 27.0	No	No	