

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-5/23/06	06BR0770-01	Southwest Area (sidewalk bridge level)	5/23/06	0.58	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST2-5/23/06	06BR0770-02	Southeast Area (sidewalk bridge level)	5/23/06	0.58	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST4-5/23/06	06BR0770-03	Northwest Area (street-level)	5/23/06	0.57	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST5-5/23/06	06BR0770-04	Firehouse #10 (roof level)	5/23/06	0.59	Mercury	EPA 324/1631	BRL	5/25/06	< 25.0	No	No	
TotalHg-ST10-5/23/06	06BR0770-05	North Side Sidewalk Bridge	5/23/06	0.58	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST11-5/23/06	06BR0770-06	90 Trinity Place (roof level)	5/23/06	0.57	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST12-5/23/06	06BR0770-07	110 Greenwich Street (roof level)	5/23/06	0.58	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST13-5/23/06	06BR0770-08	Marriott Hotel, 38th Floor (roof level)	5/23/06	0.57	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST14-5/23/06	06BR0770-09	West Face - South end at corner (scaffolding level)	5/23/06	0.57	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST15-5/23/06	06BR0770-10	South Face - East end at corner (scaffolding level)	5/23/06	0.58	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST16-5/23/06	06BR0770-11	East Face - North end at corner (scaffolding level)	5/23/06	0.58	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST17-5/23/06	06BR0770-12	North Face - West end at corner (scaffolding level)	5/23/06	0.58	Mercury	EPA 324/1631	BRL	5/25/06	< 26.0	No	No	
TotalHg-ST1-5/24/06	06BR0776-01	Southwest Area (sidewalk bridge level)	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	
TotalHg-ST2-5/24/06	06BR0776-02	Southeast Area (sidewalk bridge level)	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	
TotalHg-ST4-5/24/06	06BR0776-03	Northwest Area (street-level)	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	
TotalHg-ST5-5/24/06	06BR0776-04	Firehouse #10 (roof level)	5/24/06	0.56	Mercury	EPA 324/1631	BRL	5/26/06	< 27.0	No	No	
TotalHg-ST10-5/24/06	06BR0776-05	North Side Sidewalk Bridge	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	
TotalHg-ST100-5/24/06FD	06BR0776-13	Station 10 Field Duplicate	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	
TotalHg-ST11-5/24/06	06BR0776-06	90 Trinity Place (roof level)	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	
TotalHg-ST12-5/24/06	06BR0776-07	110 Greenwich Street (roof level)	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	
TotalHg-ST13-5/24/06	06BR0776-08	Marriott Hotel, 38th Floor (roof level)	5/24/06	0.55	Mercury	EPA 324/1631	BRL	5/26/06	< 27.0	No	No	
TotalHg-ST14-5/24/06	06BR0776-09	West Face - South end at corner (scaffolding level)	5/24/06	0.56	Mercury	EPA 324/1631	BRL	5/26/06	< 27.0	No	No	
TotalHg-ST15-5/24/06	06BR0776-10	South Face - East end at corner (scaffolding level)	5/24/06	0.56	Mercury	EPA 324/1631	BRL	5/26/06	< 27.0	No	No	
TotalHg-ST16-5/24/06	06BR0776-11	East Face - North end at corner (scaffolding level)	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	
TotalHg-ST17-5/24/06	06BR0776-12	North Face - West end at corner (scaffolding level)	5/24/06	0.57	Mercury	EPA 324/1631	BRL	5/26/06	< 26.0	No	No	