

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-5/26/06	06BR0811-01	Southwest Area (sidewalk bridge level)	5/26/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST2-5/26/06	06BR0811-02	Southeast Area (sidewalk bridge level)	5/26/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST4-5/26/06	06BR0811-03	Northwest Area (street-level)	5/26/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST5-5/26/06	06BR0811-04	Firehouse #10 (roof level)	5/26/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST10-5/26/06	06BR0811-05	North Side Sidewalk Bridge	5/26/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST11-5/26/06	06BR0811-06	90 Trinity Place (roof level)	5/26/06	0.59	Mercury	EPA 324/1631	BRL	5/31/06	< 25.0	No	No	
TotalHg-ST12-5/26/06	06BR0811-07	110 Greenwich Street (roof level)	5/26/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST13-5/26/06	06BR0811-08	Marriott Hotel, 38th Floor (roof level)	5/26/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST14-5/26/06	06BR0811-09	West Face - South end at corner (scaffolding level)	5/26/06	0.54	Mercury	EPA 324/1631	BRL	5/31/06	< 28.0	No	No	
TotalHg-ST15-5/26/06	06BR0811-10	South Face - East end at corner (scaffolding level)	5/26/06	0.55	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST16-5/26/06	06BR0811-11	East Face - North end at corner (scaffolding level)	5/26/06	0.54	Mercury	EPA 324/1631	BRL	5/31/06	< 28.0	No	No	
TotalHg-ST17-5/26/06	06BR0811-12	North Face - West end at corner (scaffolding level)	5/26/06	0.54	Mercury	EPA 324/1631	BRL	5/31/06	< 28.0	No	No	
TotalHg-ST1-5/27/06	06BR0812-01	Southwest Area (sidewalk bridge level)	5/27/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST2-5/27/06	06BR0812-02	Southeast Area (sidewalk bridge level)	5/27/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST4-5/27/06	06BR0812-03	Northwest Area (street-level)	5/27/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST5-5/27/06	06BR0812-04	Firehouse #10 (roof level)	5/27/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST10-5/27/06	06BR0812-05	North Side Sidewalk Bridge	5/27/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST11-5/27/06	06BR0812-06	90 Trinity Place (roof level)	5/27/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST12-5/27/06	06BR0812-07	110 Greenwich Street (roof level)	5/27/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST13-5/27/06	06BR0812-08	Marriott Hotel, 38th Floor (roof level)	5/27/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST14-5/27/06	06BR0812-09	West Face - South end at corner (scaffolding level)	5/27/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST15-5/27/06	06BR0812-10	South Face - East end at corner (scaffolding level)	5/27/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST16-5/27/06	06BR0812-11	East Face - North end at corner (scaffolding level)	5/27/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST17-5/27/06	06BR0812-12	North Face - West end at corner (scaffolding level)	5/27/06	0.56	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST1-5/28/06	06BR0814-01	Southwest Area (sidewalk bridge level)	5/28/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST2-5/28/06	06BR0814-02	Southeast Area (sidewalk bridge level)	5/28/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST4-5/28/06	06BR0814-03	Northwest Area (street-level)	5/28/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST5-5/28/06	06BR0814-04	Firehouse #10 (roof level)	5/28/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST10-5/28/06	06BR0814-05	North Side Sidewalk Bridge	5/28/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST11-5/28/06	06BR0814-06	90 Trinity Place (roof level)	5/28/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST12-5/28/06	06BR0814-07	110 Greenwich Street (roof level)	5/28/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST13-5/28/06	06BR0814-08	Marriott Hotel, 38th Floor (roof level)	5/28/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST14-5/28/06	06BR0814-09	West Face - South end at corner (scaffolding level)	5/28/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST15-5/28/06	06BR0814-10	South Face - East end at corner (scaffolding level)	5/28/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST16-5/28/06	06BR0814-11	East Face - North end at corner (scaffolding level)	5/28/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST17-5/28/06	06BR0814-12	North Face - West end at corner (scaffolding level)	5/28/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST1-5/29/06	06BR0815-01	Southwest Area (sidewalk bridge level)	5/29/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST2-5/29/06	06BR0815-02	Southeast Area (sidewalk bridge level)	5/29/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST4-5/29/06	06BR0815-03	Northwest Area (street-level)	5/29/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST5-5/29/06	06BR0815-04	Firehouse #10 (roof level)	5/29/06	0.57	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST10-5/29/06	06BR0815-05	North Side Sidewalk Bridge	5/29/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST11-5/29/06	06BR0815-06	90 Trinity Place (roof level)	5/29/06	0.55	Mercury	EPA 324/1631	BRL	5/31/06	< 27.0	No	No	
TotalHg-ST12-5/29/06	06BR0815-07	110 Greenwich Street (roof level)	5/29/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST13-5/29/06	06BR0815-08	Marriott Hotel, 38th Floor (roof level)	5/29/06	0.58	Mercury	EPA 324/1631	BRL	5/31/06	< 26.0	No	No	
TotalHg-ST14-5/29/06	06BR0815-09	West Face - South end at corner (scaffolding level)	5/29/06	0.61	Mercury	EPA 324/1631	BRL	5/31/06	< 25.0	No	No	
TotalHg-ST15-5/29/06	06BR0815-10	South Face - East end at corner (scaffolding level)	5/29/06	0.61	Mercury	EPA 324/1631	BRL	5/31/06	< 25.0	No	No	
TotalHg-ST16-5/29/06	06BR0815-11	East Face - North end at corner (scaffolding level)	5/29/06	0.60	Mercury	EPA 324/1631	BRL	5/31/06	< 25.0	No	No	
TotalHg-ST17-5/29/06	06BR0815-12	North Face - West end at corner (scaffolding level)	5/29/06	0.61	Mercury	EPA 324/1631	BRL	5/31/06	< 25.0	No	No	