

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-6/7/06	06BR0877-01	Southwest Area (sidewalk bridge level)	6/7/06	0.58	Mercury	EPA 324/1631	BRL	6/9/06	< 26.0	No	No	
TotalHg-ST2-6/7/06	06BR0877-02	Southeast Area (sidewalk bridge level)	6/7/06	0.57	Mercury	EPA 324/1631	BRL	6/9/06	< 26.0	No	No	
TotalHg-ST4-6/7/06	06BR0877-03	Northwest Area (street-level)	6/7/06	0.55	Mercury	EPA 324/1631	BRL	6/9/06	< 27.0	No	No	
TotalHg-ST5-6/7/06	06BR0877-04	Firehouse #10 (roof level)	6/7/06	0.58	Mercury	EPA 324/1631	BRL	6/9/06	< 26.0	No	No	
TotalHg-ST10-6/7/06	06BR0877-05	North Side Sidewalk Bridge	6/7/06	0.55	Mercury	EPA 324/1631	BRL	6/9/06	< 27.0	No	No	
TotalHg-ST11-6/7/06	06BR0877-06	90 Trinity Place (roof level)	6/7/06	0.57	Mercury	EPA 324/1631	BRL	6/9/06	< 26.0	No	No	
TotalHg-ST12-6/7/06	06BR0877-07	110 Greenwich Street (roof level)	6/7/06	0.57	Mercury	EPA 324/1631	BRL	6/9/06	< 26.0	No	No	
TotalHg-ST13-6/7/06	06BR0877-08	Marriott Hotel, 38th Floor (roof level)	6/7/06	0.53	Mercury	EPA 324/1631	BRL	6/9/06	< 28.0	No	No	
TotalHg-ST14-6/7/06	06BR0877-09	West Face - South end at corner (scaffolding level)	6/7/06	0.53	Mercury	EPA 324/1631	BRL	6/9/06	< 28.0	No	No	
TotalHg-ST15-6/7/06	06BR0877-10	South Face - East end at corner (scaffolding level)	6/7/06	0.53	Mercury	EPA 324/1631	BRL	6/9/06	< 28.0	No	No	
TotalHg-ST16-6/7/06	06BR0877-11	East Face - North end at corner (scaffolding level)	6/7/06	0.54	Mercury	EPA 324/1631	BRL	6/9/06	< 28.0	No	No	
TotalHg-ST17-6/7/06	06BR0877-12	North Face - West end at corner (scaffolding level)	6/7/06	0.54	Mercury	EPA 324/1631	BRL	6/9/06	< 28.0	No	No	
TotalHg-ST1-6/8/06	06BR0902-01	Southwest Area (sidewalk bridge level)	6/8/06	0.57	Mercury	EPA 324/1631	BRL	6/10/06	< 26.0	No	No	
TotalHg-ST2-6/8/06	06BR0902-02	Southeast Area (sidewalk bridge level)	6/8/06	0.57	Mercury	EPA 324/1631	BRL	6/10/06	< 26.0	No	No	
TotalHg-ST4-6/8/06	06BR0902-03	Northwest Area (street-level)	6/8/06	0.60	Mercury	EPA 324/1631	BRL	6/10/06	< 25.0	No	No	
TotalHg-ST5-6/8/06	06BR0902-04	Firehouse #10 (roof level)	6/8/06	0.57	Mercury	EPA 324/1631	BRL	6/10/06	< 26.0	No	No	
TotalHg-ST10-6/8/06	06BR0902-05	North Side Sidewalk Bridge	6/8/06	0.58	Mercury	EPA 324/1631	BRL	6/10/06	< 26.0	No	No	
TotalHg-ST11-6/8/06	06BR0902-06	90 Trinity Place (roof level)	6/8/06	0.58	Mercury	EPA 324/1631	BRL	6/10/06	< 26.0	No	No	
TotalHg-ST12-6/8/06	06BR0902-07	110 Greenwich Street (roof level)	6/8/06	0.58	Mercury	EPA 324/1631	BRL	6/10/06	< 26.0	No	No	
TotalHg-ST13-6/8/06	06BR0902-08	Marriott Hotel, 38th Floor (roof level)	6/8/06	0.58	Mercury	EPA 324/1631	BRL	6/10/06	< 26.0	No	No	
TotalHg-ST14-6/8/06	06BR0902-09	West Face - South end at corner (scaffolding level)	6/8/06	0.63	Mercury	EPA 324/1631	BRL	6/10/06	< 24.0	No	No	
TotalHg-ST15-6/8/06	06BR0902-10	South Face - East end at corner (scaffolding level)	6/8/06	0.63	Mercury	EPA 324/1631	BRL	6/10/06	< 24.0	No	No	
TotalHg-ST16-6/8/06	06BR0902-11	East Face - North end at corner (scaffolding level)	6/8/06	0.62	Mercury	EPA 324/1631	BRL	6/10/06	< 24.0	No	No	
TotalHg-ST17-6/8/06	06BR0902-12	North Face - West end at corner (scaffolding level)	6/8/06	0.63	Mercury	EPA 324/1631	BRL	6/10/06	< 24.0	No	No	