

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-6/16/06	06BR0932-01	Southwest Area (sidewalk bridge level)	6/16/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST2-6/16/06	06BR0932-02	Southeast Area (sidewalk bridge level)	6/16/06	0.60	Mercury	EPA 324/1631	BRL	6/20/06	< 25.0	No	No	
TotalHg-ST4-6/16/06	06BR0932-03	Northwest Area (street-level)	6/16/06	0.53	Mercury	EPA 324/1631	BRL	6/20/06	< 28.0	No	No	
TotalHg-ST5-6/16/06	06BR0932-04	Firehouse #10 (roof level)	6/16/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST10-6/16/06	06BR0932-05	North Side Sidewalk Bridge	6/16/06	0.55	Mercury	EPA 324/1631	BRL	6/20/06	< 27.0	No	No	
TotalHg-ST11-6/16/06	06BR0932-06	90 Trinity Place (roof level)	6/16/06	0.59	Mercury	EPA 324/1631	BRL	6/20/06	< 25.0	No	No	
TotalHg-ST12-6/16/06	06BR0932-07	110 Greenwich Street (roof level)	6/16/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST13-6/16/06	06BR0932-08	Marriott Hotel, 38th Floor (roof level)	6/16/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST14-6/16/06	06BR0932-09	West Face - South end at corner (scaffolding level)	6/16/06	0.56	Mercury	EPA 324/1631	BRL	6/20/06	< 27.0	No	No	
TotalHg-ST15-6/16/06	06BR0932-10	South Face - East end at corner (scaffolding level)	6/16/06	0.55	Mercury	EPA 324/1631	BRL	6/20/06	< 27.0	No	No	
TotalHg-ST17-6/16/06	06BR0932-11	North Face - West end at corner (scaffolding level)	6/16/06	0.56	Mercury	EPA 324/1631	BRL	6/20/06	< 27.0	No	No	
TotalHg-ST1-6/17/06	06BR0935-01	Southwest Area (sidewalk bridge level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST2-6/17/06	06BR0935-02	Southeast Area (sidewalk bridge level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST4-6/17/06	06BR0935-03	Northwest Area (street-level)	6/17/06	0.58	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST5-6/17/06	06BR0935-04	Firehouse #10 (roof level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST10-6/17/06	06BR0935-05	North Side Sidewalk Bridge	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST11-6/17/06	06BR0935-06	90 Trinity Place (roof level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST12-6/17/06	06BR0935-07	110 Greenwich Street (roof level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST13-6/17/06	06BR0935-08	Marriott Hotel, 38th Floor (roof level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST14-6/17/06	06BR0935-09	West Face - South end at corner (scaffolding level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST15-6/17/06	06BR0935-10	South Face - East end at corner (scaffolding level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST16-6/17/06	06BR0935-11	East Face - North end at corner (scaffolding level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST17-6/17/06	06BR0935-12	North Face - West end at corner (scaffolding level)	6/17/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST1-6/18/06	06BR0936-01	Southwest Area (sidewalk bridge level)	6/18/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST2-6/18/06	06BR0936-02	Southeast Area (sidewalk bridge level)	6/18/06	0.55	Mercury	EPA 324/1631	BRL	6/20/06	< 27.0	No	No	
TotalHg-ST4-6/18/06	06BR0936-03	Northwest Area (street-level)	6/18/06	0.61	Mercury	EPA 324/1631	BRL	6/20/06	< 25.0	No	No	
TotalHg-ST5-6/18/06	06BR0936-04	Firehouse #10 (roof level)	6/18/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST10-6/18/06	06BR0936-05	North Side Sidewalk Bridge	6/18/06	0.57	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST11-6/18/06	06BR0936-06	90 Trinity Place (roof level)	6/18/06	0.56	Mercury	EPA 324/1631	BRL	6/20/06	< 27.0	No	No	
TotalHg-ST12-6/18/06	06BR0936-07	110 Greenwich Street (roof level)	6/18/06	0.58	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST13-6/18/06	06BR0936-08	Marriott Hotel, 38th Floor (roof level)	6/18/06	0.58	Mercury	EPA 324/1631	BRL	6/20/06	< 26.0	No	No	
TotalHg-ST14-6/18/06	06BR0936-09	West Face - South end at corner (scaffolding level)	6/18/06	0.60	Mercury	EPA 324/1631	BRL	6/20/06	< 25.0	No	No	
TotalHg-ST15-6/18/06	06BR0936-10	South Face - East end at corner (scaffolding level)	6/18/06	0.59	Mercury	EPA 324/1631	BRL	6/20/06	< 25.0	No	No	
TotalHg-ST16-6/18/06	06BR0936-11	East Face - North end at corner (scaffolding level)	6/18/06	0.60	Mercury	EPA 324/1631	BRL	6/20/06	< 25.0	No	No	
TotalHg-ST17-6/18/06	06BR0936-12	North Face - West end at corner (scaffolding level)	6/18/06	0.60	Mercury	EPA 324/1631	BRL	6/20/06	< 25.0	No	No	
TotalHg-ST1-6/19/06	06BR0939-01	Southwest Area (sidewalk bridge level)	6/19/06	0.56	Mercury	EPA 324/1631	BRL	6/21/06	< 27.0	No	No	
TotalHg-ST2-6/19/06	06BR0939-02	Southeast Area (sidewalk bridge level)	6/19/06	0.56	Mercury	EPA 324/1631	BRL	6/21/06	< 27.0	No	No	
TotalHg-ST4-6/19/06	06BR0939-03	Northwest Area (street-level)	6/19/06	0.56	Mercury	EPA 324/1631	BRL	6/21/06	< 27.0	No	No	
TotalHg-ST5-6/19/06	06BR0939-04	Firehouse #10 (roof level)	6/19/06	0.56	Mercury	EPA 324/1631	BRL	6/21/06	< 27.0	No	No	
TotalHg-ST10-6/19/06	06BR0939-05	North Side Sidewalk Bridge	6/19/06	0.56	Mercury	EPA 324/1631	BRL	6/21/06	< 27.0	No	No	
TotalHg-ST11-6/19/06	06BR0939-06	90 Trinity Place (roof level)	6/19/06	0.57	Mercury	EPA 324/1631	BRL	6/21/06	< 26.0	No	No	
TotalHg-ST12-6/19/06	06BR0939-07	110 Greenwich Street (roof level)	6/19/06	0.57	Mercury	EPA 324/1631	BRL	6/21/06	< 26.0	No	No	
TotalHg-ST13-6/19/06	06BR0939-08	Marriott Hotel, 38th Floor (roof level)	6/19/06	0.58	Mercury	EPA 324/1631	BRL	6/21/06	< 26.0	No	No	
TotalHg-ST14-6/19/06	06BR0939-09	West Face - South end at corner (scaffolding level)	6/19/06	0.56	Mercury	EPA 324/1631	BRL	6/21/06	< 27.0	No	No	
TotalHg-ST15-6/19/06	06BR0939-10	South Face - East end at corner (scaffolding level)	6/19/06	0.57	Mercury	EPA 324/1631	BRL	6/21/06	< 26.0	No	No	
TotalHg-ST16-6/19/06	06BR0939-11	East Face - North end at corner (scaffolding level)	6/19/06	0.57	Mercury	EPA 324/1631	BRL	6/21/06	< 26.0	No	No	
TotalHg-ST17-6/19/06	06BR0939-12	North Face - West end at corner (scaffolding level)	6/19/06	0.56	Mercury	EPA 324/1631	BRL	6/21/06	< 27.0	No	No	

Note:

1. Mercury sample at Station 16 (East Face - North end at corner [scaffolding level]) on June 16, 2006 was not available for analysis on account of pump failure.