

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-6/21/06	06BR0974-01	Southwest Area (sidewalk bridge level)	6/21/06	0.57	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST2-6/21/06	06BR0974-02	Southeast Area (sidewalk bridge level)	6/21/06	0.57	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST4-6/21/06	06BR0974-03	Northwest Area (street-level)	6/21/06	0.58	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST5-6/21/06	06BR0974-04	Firehouse #10 (roof level)	6/21/06	0.57	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST10-6/21/06	06BR0974-05	North Side Sidewalk Bridge	6/21/06	0.57	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST11-6/21/06	06BR0974-06	90 Trinity Place (roof level)	6/21/06	0.57	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST12-6/21/06	06BR0974-07	110 Greenwich Street (roof level)	6/21/06	0.57	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST13-6/21/06	06BR0974-08	Marriott Hotel, 38th Floor (roof level)	6/21/06	0.58	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST14-6/21/06	06BR0974-09	West Face - South end at corner (scaffolding level)	6/21/06	0.58	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST15-6/21/06	06BR0974-10	South Face - East end at corner (scaffolding level)	6/21/06	0.57	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST16-6/21/06	06BR0974-11	East Face - North end at corner (scaffolding level)	6/21/06	0.58	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST17-6/21/06	06BR0974-12	North Face - West end at corner (scaffolding level)	6/21/06	0.57	Mercury	EPA 324/1631	BRL	6/23/06	< 26.0	No	No	
TotalHg-ST1-6/22/06	06BR0978-01	Southwest Area (sidewalk bridge level)	6/22/06	0.57	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	
TotalHg-ST2-6/22/06	06BR0978-02	Southeast Area (sidewalk bridge level)	6/22/06	0.56	Mercury	EPA 324/1631	BRL	6/24/06	< 27.0	No	No	
TotalHg-ST4-6/22/06	06BR0978-03	Northwest Area (street-level)	6/22/06	0.56	Mercury	EPA 324/1631	BRL	6/24/06	< 27.0	No	No	
TotalHg-ST5-6/22/06	06BR0978-04	Firehouse #10 (roof level)	6/22/06	0.56	Mercury	EPA 324/1631	BRL	6/24/06	< 27.0	No	No	
TotalHg-ST10-6/22/06	06BR0978-05	North Side Sidewalk Bridge	6/22/06	0.57	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	
TotalHg-ST11-6/22/06	06BR0978-06	90 Trinity Place (roof level)	6/22/06	0.57	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	
TotalHg-ST12-6/22/06	06BR0978-07	110 Greenwich Street (roof level)	6/22/06	0.58	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	
TotalHg-ST13-6/22/06	06BR0978-08	Marriott Hotel, 38th Floor (roof level)	6/22/06	0.57	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	
TotalHg-ST14-6/22/06	06BR0978-09	West Face - South end at corner (scaffolding level)	6/22/06	0.57	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	
TotalHg-ST15-6/22/06	06BR0978-10	South Face - East end at corner (scaffolding level)	6/22/06	0.58	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	
TotalHg-ST16-6/22/06	06BR0978-11	East Face - North end at corner (scaffolding level)	6/22/06	0.57	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	
TotalHg-ST17-6/22/06	06BR0978-12	North Face - West end at corner (scaffolding level)	6/22/06	0.57	Mercury	EPA 324/1631	BRL	6/24/06	< 26.0	No	No	