

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300	3,000			
									Target Air Quality Levels EPA Site Specific Trigger Levels				
TotalHg-ST1-6/23/06	06BR0980-01	Southwest Area (sidewalk bridge level)	6/23/06	0.55	Mercury	EPA 324/1631	BRL	6/27/06	< 27.0	No	No		
TotalHg-ST2-6/23/06	06BR0980-02	Southeast Area (sidewalk bridge level)	6/23/06	0.57	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST4-6/23/06	06BR0980-03	Northwest Area (street-level)	6/23/06	0.57	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST5-6/23/06	06BR0980-04	Firehouse #10 (roof level)	6/23/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST10-6/23/06	06BR0980-05	North Side Sidewalk Bridge	6/23/06	0.57	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST11-6/23/06	06BR0980-06	90 Trinity Place (roof level)	6/23/06	0.59	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		
TotalHg-ST12-6/23/06	06BR0980-07	110 Greenwich Street (roof level)	6/23/06	0.59	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		
TotalHg-ST13-6/23/06	06BR0980-08	Marriott Hotel, 38th Floor (roof level)	6/23/06	0.56	Mercury	EPA 324/1631	BRL	6/27/06	< 27.0	No	No		
TotalHg-ST14-6/23/06	06BR0980-09	West Face - South end at corner (scaffolding level)	6/23/06	0.54	Mercury	EPA 324/1631	BRL	6/27/06	< 28.0	No	No		
TotalHg-ST15-6/23/06	06BR0980-10	South Face - East end at corner (scaffolding level)	6/23/06	0.53	Mercury	EPA 324/1631	BRL	6/27/06	< 28.0	No	No		
TotalHg-ST16-6/23/06	06BR0980-11	East Face - North end at corner (scaffolding level)	6/23/06	0.53	Mercury	EPA 324/1631	BRL	6/27/06	< 28.0	No	No		
TotalHg-ST17-6/23/06	06BR0980-12	North Face - West end at corner (scaffolding level)	6/23/06	0.54	Mercury	EPA 324/1631	BRL	6/27/06	< 28.0	No	No		
TotalHg-ST1-6/24/06	06BR0982-01	Southwest Area (sidewalk bridge level)	6/24/06	0.59	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		
TotalHg-ST2-6/24/06	06BR0982-02	Southeast Area (sidewalk bridge level)	6/24/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST4-6/24/06	06BR0982-03	Northwest Area (street-level)	6/24/06	0.57	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST5-6/24/06	06BR0982-04	Firehouse #10 (roof level)	6/24/06	0.56	Mercury	EPA 324/1631	BRL	6/27/06	< 27.0	No	No		
TotalHg-ST10-6/24/06	06BR0982-05	North Side Sidewalk Bridge	6/24/06	0.57	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST11-6/24/06	06BR0982-06	90 Trinity Place (roof level)	6/24/06	0.57	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST12-6/24/06	06BR0982-07	110 Greenwich Street (roof level)	6/24/06	0.57	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST14-6/24/06	06BR0982-08	West Face - South end at corner (scaffolding level)	6/24/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST15-6/24/06	06BR0982-09	South Face - East end at corner (scaffolding level)	6/24/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST16-6/24/06	06BR0982-10	East Face - North end at corner (scaffolding level)	6/24/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST17-6/24/06	06BR0982-11	North Face - West end at corner (scaffolding level)	6/24/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST1-6/25/06	06BR0983-01	Southwest Area (sidewalk bridge level)	6/25/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST2-6/25/06	06BR0983-02	Southeast Area (sidewalk bridge level)	6/25/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST4-6/25/06	06BR0983-03	Northwest Area (street-level)	6/25/06	0.60	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		
TotalHg-ST5-6/25/06	06BR0983-04	Firehouse #10 (roof level)	6/25/06	0.58	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST10-6/25/06	06BR0983-05	North Side Sidewalk Bridge	6/25/06	0.60	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		
TotalHg-ST11-6/25/06	06BR0983-06	90 Trinity Place (roof level)	6/25/06	0.56	Mercury	EPA 324/1631	BRL	6/27/06	< 27.0	No	No		
TotalHg-ST12-6/25/06	06BR0983-07	110 Greenwich Street (roof level)	6/25/06	0.57	Mercury	EPA 324/1631	BRL	6/27/06	< 26.0	No	No		
TotalHg-ST13-6/25/06	06BR0983-08	Marriott Hotel, 38th Floor (roof level)	6/25/06	0.56	Mercury	EPA 324/1631	BRL	6/27/06	< 27.0	No	No		
TotalHg-ST14-6/25/06	06BR0983-09	West Face - South end at corner (scaffolding level)	6/25/06	0.61	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		
TotalHg-ST15-6/25/06	06BR0983-10	South Face - East end at corner (scaffolding level)	6/25/06	0.61	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		
TotalHg-ST16-6/25/06	06BR0983-11	East Face - North end at corner (scaffolding level)	6/25/06	0.61	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		
TotalHg-ST17-6/25/06	06BR0983-12	North Face - West end at corner (scaffolding level)	6/25/06	0.61	Mercury	EPA 324/1631	BRL	6/27/06	< 25.0	No	No		

Note:

- Mercury sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on June 24, 2006 was not available for analysis on account of pump failure.