

| TRC Field Sample No. | Sample No.  | Sampling Location                                   | Collection Start Date | Sample Volume (m <sup>3</sup> ) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3)     | Exceeds Target<br>Air Quality<br>Levels | Exceeds EPA<br>Site Specific<br>Trigger Levels | Comments |
|----------------------|-------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---|---|--|----------|
|                      |             |   |                       |                                 |         |                   |     |                         | 300                                       |   |  |          |
|                      |             |   |                       |                                 |         |                   |     |                         | EPA Site Specific Trigger Levels<br>3,000 |   |  |          |
| TotalHg-ST1-7/5/06   | 06BR1022-01 | Southwest Area (sidewalk bridge level)              | 7/5/06                | 0.59                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 25.0                                    | No                                      | No   |          |
| TotalHg-ST2-7/5/06   | 06BR1022-02 | Southeast Area (sidewalk bridge level)              | 7/5/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST4-7/5/06   | 06BR1022-03 | Northwest Area (street-level)                       | 7/5/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST5-7/5/06   | 06BR1022-04 | Firehouse #10 (roof level)                          | 7/5/06                | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST10-7/5/06  | 06BR1022-05 | North Side Sidewalk Bridge                          | 7/5/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST11-7/5/06  | 06BR1022-06 | 90 Trinity Place (roof level)                       | 7/5/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST12-7/5/06  | 06BR1022-07 | 110 Greenwich Street (roof level)                   | 7/5/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST13-7/5/06  | 06BR1022-08 | Marriott Hotel, 38th Floor (roof level)             | 7/5/06                | 0.59                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 25.0                                    | No                                      | No   |          |
| TotalHg-ST14-7/5/06  | 06BR1022-09 | West Face - South end at corner (scaffolding level) | 7/5/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST15-7/5/06  | 06BR1022-10 | South Face - East end at corner (scaffolding level) | 7/5/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST16-7/5/06  | 06BR1022-11 | East Face - North end at corner (scaffolding level) | 7/5/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/7/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST1-7/6/06   | 06BR1027-01 | Southwest Area (sidewalk bridge level)              | 7/6/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST2-7/6/06   | 06BR1027-02 | Southeast Area (sidewalk bridge level)              | 7/6/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST4-7/6/06   | 06BR1027-03 | Northwest Area (street-level)                       | 7/6/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST5-7/6/06   | 06BR1027-04 | Firehouse #10 (roof level)                          | 7/6/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST6-7/6/06   | 06BR1028-01 | Southwest Area (roof level)                         | 7/6/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST7-7/6/06   | 06BR1028-02 | Southeast Area (roof level)                         | 7/6/06                | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST8-7/6/06   | 06BR1028-03 | Northeast Area (roof level)                         | 7/6/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST9-7/6/06   | 06BR1028-04 | Northwest Area (roof level)                         | 7/6/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST10-7/6/06  | 06BR1027-05 | North Side Sidewalk Bridge                          | 7/6/06                | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST11-7/6/06  | 06BR1027-06 | 90 Trinity Place (roof level)                       | 7/6/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 26.0                                    | No                                      | No   |          |
| TotalHg-ST12-7/6/06  | 06BR1027-07 | 110 Greenwich Street (roof level)                   | 7/6/06                | 0.48                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 31.0                                    | No                                      | No   |          |
| TotalHg-ST13-7/6/06  | 06BR1027-08 | Marriott Hotel, 38th Floor (roof level)             | 7/6/06                | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST14-7/6/06  | 06BR1027-09 | West Face - South end at corner (scaffolding level) | 7/6/06                | 0.54                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 28.0                                    | No                                      | No   |          |
| TotalHg-ST16-7/6/06  | 06BR1027-10 | East Face - North end at corner (scaffolding level) | 7/6/06                | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 27.0                                    | No                                      | No   |          |
| TotalHg-ST17-7/6/06  | 06BR1027-11 | North Face - West end at corner (scaffolding level) | 7/6/06                | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/8/06                  | < 27.0                                    | No                                      | No   |          |

Note:

1. Mercury sample at Station 17 (North Face - West end at corner [scaffolding level]) on July 5, 2006 and Station 15 (South Face - East end at corner [scaffolding level]) on July 6, 2006 were not available for analysis on account of pump failure.