

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-7/08/09	0928032-01	Southwest Area (sidewalk bridge level)	7/8/09	0.56	Mercury	EPA 324/1631	BRL	7/10/09	< 26.8	No	No	
TotalHg-ST2-7/08/09	0928032-02	Southeast Area (sidewalk bridge level)	7/8/09	0.57	Mercury	EPA 324/1631	BRL	7/10/09	< 26.3	No	No	
TotalHg-ST4-7/08/09	0928032-03	Northwest Area (street-level)	7/8/09	0.60	Mercury	EPA 324/1631	BRL	7/10/09	< 25.0	No	No	
TotalHg-ST5-7/08/09	0928032-04	Firehouse #10 (roof level)	7/8/09	0.61	Mercury	EPA 324/1631	BRL	7/10/09	< 24.6	No	No	
TotalHg-ST10-7/08/09	0928032-05	North Side Sidewalk Bridge	7/8/09	0.57	Mercury	EPA 324/1631	BRL	7/10/09	< 26.3	No	No	
TotalHg-ST11-7/08/09	0928032-06	90 Trinity Place (roof level)	7/8/09	0.58	Mercury	EPA 324/1631	BRL	7/10/09	< 25.9	No	No	
TotalHg-ST12-7/08/09	0928032-07	110 Greenwich Street (roof level)	7/8/09	0.58	Mercury	EPA 324/1631	BRL	7/10/09	< 25.9	No	No	
TotalHg-ST13-7/08/09	0928032-08	Marriott Hotel, 38th Floor (roof level)	7/8/09	0.54	Mercury	EPA 324/1631	BRL	7/10/09	< 27.8	No	No	
TotalHg-ST1-7/9/09	0928035-01	Southwest Area (sidewalk bridge level)	7/9/09	0.59	Mercury	EPA 324/1631	BRL	7/11/09	< 25.4	No	No	
TotalHg-ST2-7/9/09	0928035-02	Southeast Area (sidewalk bridge level)	7/9/09	0.56	Mercury	EPA 324/1631	BRL	7/11/09	< 26.8	No	No	
TotalHg-ST4-7/9/09	0928035-03	Northwest Area (street-level)	7/9/09	0.61	Mercury	EPA 324/1631	BRL	7/11/09	< 24.6	No	No	
TotalHg-ST5-7/9/09	0928035-04	Firehouse #10 (roof level)	7/9/09	0.61	Mercury	EPA 324/1631	BRL	7/11/09	< 24.6	No	No	
TotalHg-ST10-7/9/09	0928035-05	North Side Sidewalk Bridge	7/9/09	0.55	Mercury	EPA 324/1631	BRL	7/11/09	< 27.3	No	No	
TotalHg-ST11-7/9/09	0928035-06	90 Trinity Place (roof level)	7/9/09	0.57	Mercury	EPA 324/1631	BRL	7/11/09	< 26.3	No	No	
TotalHg-ST12-7/9/09	0928035-07	110 Greenwich Street (roof level)	7/9/09	0.53	Mercury	EPA 324/1631	BRL	7/11/09	< 28.3	No	No	
TotalHg-ST13-7/9/09	0928035-08	Marriott Hotel, 38th Floor (roof level)	7/9/09	0.54	Mercury	EPA 324/1631	BRL	7/11/09	< 27.8	No	No	
TotalHg-ST1-7/10/09	0929001-01	Southwest Area (sidewalk bridge level)	7/10/09	0.54	Mercury	EPA 324/1631	BRL	7/13/09	< 27.8	No	No	
TotalHg-ST2-7/10/09	0929001-02	Southeast Area (sidewalk bridge level)	7/10/09	0.57	Mercury	EPA 324/1631	BRL	7/13/09	< 26.3	No	No	
TotalHg-ST4-7/10/09	0929001-03	Northwest Area (street-level)	7/10/09	0.59	Mercury	EPA 324/1631	BRL	7/13/09	< 25.4	No	No	
TotalHg-ST5-7/10/09	0929001-04	Firehouse #10 (roof level)	7/10/09	0.58	Mercury	EPA 324/1631	BRL	7/13/09	< 25.9	No	No	
TotalHg-ST10-7/10/09	0929001-05	North Side Sidewalk Bridge	7/10/09	0.56	Mercury	EPA 324/1631	BRL	7/13/09	< 26.8	No	No	
TotalHg-ST11-7/10/09	0929001-06	90 Trinity Place (roof level)	7/10/09	0.56	Mercury	EPA 324/1631	BRL	7/13/09	< 26.8	No	No	
TotalHg-ST12-7/10/09	0929001-07	110 Greenwich Street (roof level)	7/10/09	0.57	Mercury	EPA 324/1631	BRL	7/13/09	< 26.3	No	No	
TotalHg-ST13-7/10/09	0929001-08	Marriott Hotel, 38th Floor (roof level)	7/10/09	0.56	Mercury	EPA 324/1631	BRL	7/13/09	< 26.8	No	No	