

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>									<b>300</b>			
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-7/14/08	0829016-01	Southwest Area (sidewalk bridge level)	7/14/08	0.57	Mercury	EPA 324/1631	BRL	7/16/08	< 26.0	No	No	
TotalHg-ST2-7/14/08	0829016-02	Southeast Area (sidewalk bridge level)	7/14/08	0.55	Mercury	EPA 324/1631	BRL	7/16/08	< 27.0	No	No	
TotalHg-ST4-7/14/08	0829016-03	Northwest Area (street-level)	7/14/08	0.56	Mercury	EPA 324/1631	BRL	7/16/08	< 27.0	No	No	
TotalHg-ST5-7/14/08	0829016-04	Firehouse #10 (roof level)	7/14/08	0.56	Mercury	EPA 324/1631	BRL	7/16/08	< 27.0	No	No	
TotalHg-ST10-7/14/08	0829016-05	North Side Sidewalk Bridge	7/14/08	0.58	Mercury	EPA 324/1631	BRL	7/16/08	< 26.0	No	No	
TotalHg-ST11-7/14/08	0829016-06	90 Trinity Place (roof level)	7/14/08	0.55	Mercury	EPA 324/1631	BRL	7/16/08	< 27.0	No	No	
TotalHg-ST12-7/14/08	0829016-07	110 Greenwich Street (roof level)	7/14/08	0.56	Mercury	EPA 324/1631	BRL	7/16/08	< 27.0	No	No	
TotalHg-ST13-7/14/08	0829016-08	Marriott Hotel, 38th Floor (roof level)	7/14/08	0.48	Mercury	EPA 324/1631	BRL	7/16/08	< 31.0	No	No	
TotalHg-ST14-7/14/08	0829016-09	West Face - South end at corner (scaffolding level)	7/14/08	0.58	Mercury	EPA 324/1631	BRL	7/16/08	< 26.0	No	No	
TotalHg-ST15-7/14/08	0829016-10	South Face - East end at corner (scaffolding level)	7/14/08	0.60	Mercury	EPA 324/1631	BRL	7/16/08	< 25.0	No	No	
TotalHg-ST16-7/14/08	0829016-11	East Face - North end at corner (scaffolding level)	7/14/08	0.59	Mercury	EPA 324/1631	BRL	7/16/08	< 25.0	No	No	
TotalHg-ST17-7/14/08	0829016-12	North Face - West end at corner (scaffolding level)	7/14/08	0.57	Mercury	EPA 324/1631	BRL	7/16/08	< 26.0	No	No	
TotalHg-ST1-7/15/08	0829025-01	Southwest Area (sidewalk bridge level)	7/15/08	0.54	Mercury	EPA 324/1631	BRL	7/17/08	< 28.0	No	No	
TotalHg-ST2-7/15/08	0829025-02	Southeast Area (sidewalk bridge level)	7/15/08	0.55	Mercury	EPA 324/1631	BRL	7/17/08	< 27.0	No	No	
TotalHg-ST4-7/15/08	0829025-03	Northwest Area (street-level)	7/15/08	0.54	Mercury	EPA 324/1631	BRL	7/17/08	< 28.0	No	No	
TotalHg-ST5-7/15/08	0829025-04	Firehouse #10 (roof level)	7/15/08	0.56	Mercury	EPA 324/1631	BRL	7/17/08	< 27.0	No	No	
TotalHg-ST10-7/15/08	0829025-05	North Side Sidewalk Bridge	7/15/08	0.58	Mercury	EPA 324/1631	BRL	7/17/08	< 26.0	No	No	
TotalHg-ST11-7/15/08	0829025-06	90 Trinity Place (roof level)	7/15/08	0.53	Mercury	EPA 324/1631	BRL	7/17/08	< 28.0	No	No	
TotalHg-ST12-7/15/08	0829025-07	110 Greenwich Street (roof level)	7/15/08	0.56	Mercury	EPA 324/1631	BRL	7/17/08	< 27.0	No	No	
TotalHg-ST13-7/15/08	0829025-08	Marriott Hotel, 38th Floor (roof level)	7/15/08	0.57	Mercury	EPA 324/1631	BRL	7/17/08	< 26.0	No	No	
TotalHg-ST14-7/15/08	0829025-09	West Face - South end at corner (scaffolding level)	7/15/08	0.57	Mercury	EPA 324/1631	BRL	7/17/08	< 26.0	No	No	
TotalHg-ST15-7/15/08	0829025-10	South Face - East end at corner (scaffolding level)	7/15/08	0.56	Mercury	EPA 324/1631	BRL	7/17/08	< 27.0	No	No	
TotalHg-ST16-7/15/08	0829025-11	East Face - North end at corner (scaffolding level)	7/15/08	0.56	Mercury	EPA 324/1631	BRL	7/17/08	< 27.0	No	No	
TotalHg-ST17-7/15/08	0829025-12	North Face - West end at corner (scaffolding level)	7/15/08	0.54	Mercury	EPA 324/1631	BRL	7/17/08	< 28.0	No	No	
TotalHg-ST1-7/16/08	0829032-01	Southwest Area (sidewalk bridge level)	7/16/08	0.58	Mercury	EPA 324/1631	BRL	7/18/08	< 26.0	No	No	
TotalHg-ST2-7/16/08	0829032-02	Southeast Area (sidewalk bridge level)	7/16/08	0.56	Mercury	EPA 324/1631	BRL	7/18/08	< 27.0	No	No	
TotalHg-ST4-7/16/08	0829032-03	Northwest Area (street-level)	7/16/08	0.56	Mercury	EPA 324/1631	BRL	7/18/08	< 27.0	No	No	
TotalHg-ST5-7/16/08	0829032-04	Firehouse #10 (roof level)	7/16/08	0.58	Mercury	EPA 324/1631	BRL	7/18/08	< 26.0	No	No	
TotalHg-ST10-7/16/08	0829032-05	North Side Sidewalk Bridge	7/16/08	0.54	Mercury	EPA 324/1631	BRL	7/18/08	< 28.0	No	No	
TotalHg-ST11-7/16/08	0829032-06	90 Trinity Place (roof level)	7/16/08	0.56	Mercury	EPA 324/1631	BRL	7/18/08	< 27.0	No	No	
TotalHg-ST12-7/16/08	0829032-07	110 Greenwich Street (roof level)	7/16/08	0.54	Mercury	EPA 324/1631	BRL	7/18/08	< 28.0	No	No	
TotalHg-ST13-7/16/08	0829032-08	Marriott Hotel, 38th Floor (roof level)	7/16/08	0.57	Mercury	EPA 324/1631	BRL	7/18/08	< 26.0	No	No	
TotalHg-ST14-7/16/08	0829032-09	West Face - South end at corner (scaffolding level)	7/16/08	0.59	Mercury	EPA 324/1631	BRL	7/18/08	< 25.0	No	No	
TotalHg-ST15-7/16/08	0829032-10	South Face - East end at corner (scaffolding level)	7/16/08	0.52	Mercury	EPA 324/1631	BRL	7/18/08	< 29.0	No	No	
TotalHg-ST16-7/16/08	0829032-11	East Face - North end at corner (scaffolding level)	7/16/08	0.53	Mercury	EPA 324/1631	BRL	7/18/08	< 28.0	No	No	
TotalHg-ST17-7/16/08	0829032-12	North Face - West end at corner (scaffolding level)	7/16/08	0.60	Mercury	EPA 324/1631	BRL	7/18/08	< 25.0	No	No	