

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-8/2/06	06BR1202-01	Southwest Area (sidewalk bridge level)	8/2/06	0.56	Mercury	EPA 324/1631	BRL	8/4/06	< 27.0	No	No	
TotalHg-ST2-8/2/06	06BR1202-02	Southeast Area (sidewalk bridge level)	8/2/06	0.56	Mercury	EPA 324/1631	BRL	8/4/06	< 27.0	No	No	
TotalHg-ST4-8/2/06	06BR1202-03	Northwest Area (street-level)	8/2/06	0.56	Mercury	EPA 324/1631	BRL	8/4/06	< 27.0	No	No	
TotalHg-ST5-8/2/06	06BR1202-04	Firehouse #10 (roof level)	8/2/06	0.57	Mercury	EPA 324/1631	BRL	8/4/06	< 26.0	No	No	
TotalHg-ST6-8/2/06	06BR1203-01	Southwest Area (roof level)	8/2/06	0.57	Mercury	EPA 324/1631	BRL	8/4/06	< 26.0	No	No	
TotalHg-ST7-8/2/06	06BR1203-02	Southeast Area (roof level)	8/2/06	0.58	Mercury	EPA 324/1631	BRL	8/4/06	< 26.0	No	No	
TotalHg-ST8-8/2/06	06BR1203-03	Northeast Area (roof level)	8/2/06	0.57	Mercury	EPA 324/1631	BRL	8/4/06	< 26.0	No	No	
TotalHg-ST9-8/2/06	06BR1203-04	Northwest Area (roof level)	8/2/06	0.58	Mercury	EPA 324/1631	BRL	8/4/06	< 26.0	No	No	
TotalHg-ST10-8/2/06	06BR1202-05	North Side Sidewalk Bridge	8/2/06	0.55	Mercury	EPA 324/1631	BRL	8/4/06	< 27.0	No	No	
TotalHg-ST11-8/2/06	06BR1202-06	90 Trinity Place (roof level)	8/2/06	0.58	Mercury	EPA 324/1631	BRL	8/4/06	< 26.0	No	No	
TotalHg-ST12-8/2/06	06BR1202-07	110 Greenwich Street (roof level)	8/2/06	0.61	Mercury	EPA 324/1631	BRL	8/4/06	< 25.0	No	No	
TotalHg-ST13-8/2/06	06BR1202-08	Marriott Hotel, 38th Floor (roof level)	8/2/06	0.55	Mercury	EPA 324/1631	BRL	8/4/06	< 27.0	No	No	
TotalHg-ST14-8/2/06	06BR1202-09	West Face - South end at corner (scaffolding level)	8/2/06	0.56	Mercury	EPA 324/1631	BRL	8/4/06	< 27.0	No	No	
TotalHg-ST15-8/2/06	06BR1202-10	South Face - East end at corner (scaffolding level)	8/2/06	0.55	Mercury	EPA 324/1631	BRL	8/4/06	< 27.0	No	No	
TotalHg-ST16-8/2/06	06BR1202-11	East Face - North end at corner (scaffolding level)	8/2/06	0.56	Mercury	EPA 324/1631	BRL	8/4/06	< 27.0	No	No	
TotalHg-ST1-8/3/06	06BR1208-01	Southwest Area (sidewalk bridge level)	8/3/06	0.59	Mercury	EPA 324/1631	BRL	8/5/06	< 25.0	No	No	
TotalHg-ST2-8/3/06	06BR1208-02	Southeast Area (sidewalk bridge level)	8/3/06	0.59	Mercury	EPA 324/1631	BRL	8/5/06	< 25.0	No	No	
TotalHg-ST4-8/3/06	06BR1208-03	Northwest Area (street-level)	8/3/06	0.58	Mercury	EPA 324/1631	BRL	8/5/06	< 26.0	No	No	
TotalHg-ST5-8/3/06	06BR1208-04	Firehouse #10 (roof level)	8/3/06	0.55	Mercury	EPA 324/1631	BRL	8/5/06	< 27.0	No	No	
TotalHg-ST6-8/3/06	06BR1209-01	Southwest Area (roof level)	8/3/06	0.57	Mercury	EPA 324/1631	BRL	8/5/06	< 26.0	No	No	
TotalHg-ST8-8/3/06	06BR1209-02	Northeast Area (roof level)	8/3/06	0.57	Mercury	EPA 324/1631	BRL	8/5/06	< 26.0	No	No	
TotalHg-ST9-8/3/06	06BR1209-03	Northwest Area (roof level)	8/3/06	0.57	Mercury	EPA 324/1631	BRL	8/5/06	< 26.0	No	No	
TotalHg-ST10-8/3/06	06BR1208-05	North Side Sidewalk Bridge	8/3/06	0.58	Mercury	EPA 324/1631	BRL	8/5/06	< 26.0	No	No	
TotalHg-ST11-8/3/06	06BR1208-06	90 Trinity Place (roof level)	8/3/06	0.55	Mercury	EPA 324/1631	BRL	8/5/06	< 27.0	No	No	
TotalHg-ST12-8/3/06	06BR1208-07	110 Greenwich Street (roof level)	8/3/06	0.56	Mercury	EPA 324/1631	BRL	8/5/06	< 27.0	No	No	
TotalHg-ST13-8/3/06	06BR1208-08	Marriott Hotel, 38th Floor (roof level)	8/3/06	0.58	Mercury	EPA 324/1631	BRL	8/5/06	< 26.0	No	No	
TotalHg-ST14-8/3/06	06BR1208-09	West Face - South end at corner (scaffolding level)	8/3/06	0.59	Mercury	EPA 324/1631	BRL	8/5/06	< 25.0	No	No	
TotalHg-ST15-8/3/06	06BR1208-10	South Face - East end at corner (scaffolding level)	8/3/06	0.59	Mercury	EPA 324/1631	BRL	8/5/06	< 25.0	No	No	
TotalHg-ST16-8/3/06	06BR1208-11	East Face - North end at corner (scaffolding level)	8/3/06	0.58	Mercury	EPA 324/1631	BRL	8/5/06	< 26.0	No	No	

Note:

- Mercury samples at Station 17 (North Face - West end at corner [scaffolding level]) on August 2 and 3, 2006 were not available for analysis on account of temporary power failures.
- Mercury sample at Station 7 (Southeast Area [roof level]) on August 3, 2006 was not available for analysis on account of media damage.