

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-8/9/06	06BR1233-01	Southwest Area (sidewalk bridge level)	8/9/06	0.57	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST2-8/9/06	06BR1233-02	Southeast Area (sidewalk bridge level)	8/9/06	0.57	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST4-8/9/06	06BR1233-03	Northwest Area (street-level)	8/9/06	0.61	Mercury	EPA 324/1631	BRL	8/11/06	< 25.0	No	No	
TotalHg-ST5-8/9/06	06BR1233-04	Firehouse #10 (roof level)	8/9/06	0.55	Mercury	EPA 324/1631	BRL	8/11/06	< 27.0	No	No	
TotalHg-ST6-8/9/06	06BR1234-01	Southwest Area (roof level)	8/9/06	0.57	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST7-8/9/06	06BR1234-02	Southeast Area (roof level)	8/9/06	0.57	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST8-8/9/06	06BR1234-03	Northeast Area (roof level)	8/9/06	0.57	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST9-8/9/06	06BR1234-04	Northwest Area (roof level)	8/9/06	0.57	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST10-8/9/06	06BR1233-05	North Side Sidewalk Bridge	8/9/06	0.57	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST11-8/9/06	06BR1233-06	90 Trinity Place (roof level)	8/9/06	0.56	Mercury	EPA 324/1631	BRL	8/11/06	< 27.0	No	No	
TotalHg-ST12-8/9/06	06BR1233-07	110 Greenwich Street (roof level)	8/9/06	0.55	Mercury	EPA 324/1631	BRL	8/11/06	< 27.0	No	No	
TotalHg-ST13-8/9/06	06BR1233-08	Marriott Hotel, 38th Floor (roof level)	8/9/06	0.55	Mercury	EPA 324/1631	BRL	8/11/06	< 27.0	No	No	
TotalHg-ST14-8/9/06	06BR1233-09	West Face - South end at corner (scaffolding level)	8/9/06	0.57	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST15-8/9/06	06BR1233-10	South Face - East end at corner (scaffolding level)	8/9/06	0.56	Mercury	EPA 324/1631	BRL	8/11/06	< 27.0	No	No	
TotalHg-ST16-8/9/06	06BR1233-11	East Face - North end at corner (scaffolding level)	8/9/06	0.56	Mercury	EPA 324/1631	BRL	8/11/06	< 27.0	No	No	
TotalHg-ST17-8/9/06	06BR1233-12	North Face - West end at corner (scaffolding level)	8/9/06	0.58	Mercury	EPA 324/1631	BRL	8/11/06	< 26.0	No	No	
TotalHg-ST1-8/10/06	06BR1243-01	Southwest Area (sidewalk bridge level)	8/10/06	0.58	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST2-8/10/06	06BR1243-02	Southeast Area (sidewalk bridge level)	8/10/06	0.56	Mercury	EPA 324/1631	BRL	8/12/06	< 27.0	No	No	
TotalHg-ST4-8/10/06	06BR1243-03	Northwest Area (street-level)	8/10/06	0.58	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST5-8/10/06	06BR1243-04	Firehouse #10 (roof level)	8/10/06	0.58	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST6-8/10/06	06BR1244-01	Southwest Area (roof level)	8/10/06	0.57	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST7-8/10/06	06BR1244-02	Southeast Area (roof level)	8/10/06	0.58	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST8-8/10/06	06BR1244-03	Northeast Area (roof level)	8/10/06	0.57	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST9-8/10/06	06BR1244-04	Northwest Area (roof level)	8/10/06	0.57	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST10-8/10/06	06BR1243-05	North Side Sidewalk Bridge	8/10/06	0.61	Mercury	EPA 324/1631	BRL	8/12/06	< 25.0	No	No	
TotalHg-ST13-8/10/06	06BR1243-06	Marriott Hotel, 38th Floor (roof level)	8/10/06	0.53	Mercury	EPA 324/1631	BRL	8/12/06	< 28.0	No	No	
TotalHg-ST14-8/10/06	06BR1243-07	West Face - South end at corner (scaffolding level)	8/10/06	0.57	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST15-8/10/06	06BR1243-08	South Face - East end at corner (scaffolding level)	8/10/06	0.57	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST16-8/10/06	06BR1243-09	East Face - North end at corner (scaffolding level)	8/10/06	0.57	Mercury	EPA 324/1631	BRL	8/12/06	< 26.0	No	No	
TotalHg-ST17-8/10/06	06BR1243-10	North Face - West end at corner (scaffolding level)	8/10/06	0.56	Mercury	EPA 324/1631	BRL	8/12/06	< 27.0	No	No	

Note:

1. Mercury samples at Station 11 (90 Trinity Place [roof level]) and Station 12 (110 Greenwich Street [roof level]) on August 10, 2006 were not available for analysis on account of pump failures.