

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-8/20/08	0834048-01	Southwest Area (sidewalk bridge level)	8/20/08	0.57	Mercury	EPA 324/1631	BRL	8/22/08	< 26.0	No	No	
TotalHg-ST2-8/20/08	0834048-02	Southeast Area (sidewalk bridge level)	8/20/08	0.56	Mercury	EPA 324/1631	BRL	8/22/08	< 27.0	No	No	
TotalHg-ST4-8/20/08	0834048-03	Northwest Area (street-level)	8/20/08	0.56	Mercury	EPA 324/1631	BRL	8/22/08	< 27.0	No	No	
TotalHg-ST5-8/20/08	0834048-04	Firehouse #10 (roof level)	8/20/08	0.60	Mercury	EPA 324/1631	BRL	8/22/08	< 25.0	No	No	
TotalHg-ST10-8/20/08	0834048-05	North Side Sidewalk Bridge	8/20/08	0.58	Mercury	EPA 324/1631	BRL	8/22/08	< 26.0	No	No	
TotalHg-ST11-8/20/08	0834048-06	90 Trinity Place (roof level)	8/20/08	0.57	Mercury	EPA 324/1631	BRL	8/22/08	< 26.0	No	No	
TotalHg-ST12-8/20/08	0834048-07	110 Greenwich Street (roof level)	8/20/08	0.54	Mercury	EPA 324/1631	BRL	8/22/08	< 28.0	No	No	
TotalHg-ST13-8/20/08	0834048-08	Marriott Hotel, 38th Floor (roof level)	8/20/08	0.56	Mercury	EPA 324/1631	BRL	8/22/08	< 27.0	No	No	
TotalHg-ST14-8/20/08	0834048-09	West Face - South end at corner (scaffolding level)	8/20/08	0.56	Mercury	EPA 324/1631	BRL	8/22/08	< 27.0	No	No	
TotalHg-ST15-8/20/08	0834048-10	South Face - East end at corner (scaffolding level)	8/20/08	0.59	Mercury	EPA 324/1631	BRL	8/22/08	< 25.0	No	No	
TotalHg-ST16-8/20/08	0834048-11	East Face - North end at corner (scaffolding level)	8/20/08	0.57	Mercury	EPA 324/1631	BRL	8/22/08	< 26.0	No	No	
TotalHg-ST17-8/20/08	0834048-12	North Face - West end at corner (scaffolding level)	8/20/08	0.57	Mercury	EPA 324/1631	BRL	8/22/08	< 26.0	No	No	
TotalHg-ST1-8/21/08	0834064-01	Southwest Area (sidewalk bridge level)	8/21/08	0.55	Mercury	EPA 324/1631	BRL	8/23/08	< 27.0	No	No	
TotalHg-ST2-8/21/08	0834064-02	Southeast Area (sidewalk bridge level)	8/21/08	0.56	Mercury	EPA 324/1631	BRL	8/23/08	< 27.0	No	No	
TotalHg-ST4-8/21/08	0834064-03	Northwest Area (street-level)	8/21/08	0.57	Mercury	EPA 324/1631	BRL	8/23/08	< 26.0	No	No	
TotalHg-ST5-8/21/08	0834064-04	Firehouse #10 (roof level)	8/21/08	0.54	Mercury	EPA 324/1631	BRL	8/23/08	< 28.0	No	No	
TotalHg-ST10-8/21/08	0834064-05	North Side Sidewalk Bridge	8/21/08	0.58	Mercury	EPA 324/1631	BRL	8/23/08	< 26.0	No	No	
TotalHg-ST11-8/21/08	0834064-06	90 Trinity Place (roof level)	8/21/08	0.53	Mercury	EPA 324/1631	BRL	8/23/08	< 28.0	No	No	
TotalHg-ST12-8/21/08	0834064-07	110 Greenwich Street (roof level)	8/21/08	0.56	Mercury	EPA 324/1631	BRL	8/23/08	< 27.0	No	No	
TotalHg-ST13-8/21/08	0834064-08	Marriott Hotel, 38th Floor (roof level)	8/21/08	0.58	Mercury	EPA 324/1631	BRL	8/23/08	< 26.0	No	No	
TotalHg-ST14-8/21/08	0834064-09	West Face - South end at corner (scaffolding level)	8/21/08	0.55	Mercury	EPA 324/1631	BRL	8/23/08	< 27.0	No	No	
TotalHg-ST15-8/21/08	0834064-10	South Face - East end at corner (scaffolding level)	8/21/08	0.54	Mercury	EPA 324/1631	BRL	8/23/08	< 28.0	No	No	
TotalHg-ST16-8/21/08	0834064-11	East Face - North end at corner (scaffolding level)	8/21/08	0.54	Mercury	EPA 324/1631	BRL	8/23/08	< 28.0	No	No	
TotalHg-ST17-8/21/08	0834064-12	North Face - West end at corner (scaffolding level)	8/21/08	0.53	Mercury	EPA 324/1631	BRL	8/23/08	< 28.0	No	No	
TotalHg-ST1-8/22/08	0835001-01	Southwest Area (sidewalk bridge level)	8/22/08	0.58	Mercury	EPA 324/1631	BRL	8/25/08	< 26.0	No	No	
TotalHg-ST2-8/22/08	0835001-02	Southeast Area (sidewalk bridge level)	8/22/08	0.58	Mercury	EPA 324/1631	BRL	8/25/08	< 26.0	No	No	
TotalHg-ST4-8/22/08	0835001-03	Northwest Area (street-level)	8/22/08	0.57	Mercury	EPA 324/1631	BRL	8/25/08	< 26.0	No	No	
TotalHg-ST5-8/22/08	0835001-04	Firehouse #10 (roof level)	8/22/08	0.56	Mercury	EPA 324/1631	BRL	8/25/08	< 27.0	No	No	
TotalHg-ST10-8/22/08	0835001-05	North Side Sidewalk Bridge	8/22/08	0.58	Mercury	EPA 324/1631	BRL	8/25/08	< 26.0	No	No	
TotalHg-ST11-8/22/08	0835001-06	90 Trinity Place (roof level)	8/22/08	0.57	Mercury	EPA 324/1631	BRL	8/25/08	< 26.0	No	No	
TotalHg-ST12-8/22/08	0835001-07	110 Greenwich Street (roof level)	8/22/08	0.55	Mercury	EPA 324/1631	BRL	8/25/08	< 27.0	No	No	
TotalHg-ST13-8/22/08	0835001-08	Marriott Hotel, 38th Floor (roof level)	8/22/08	0.55	Mercury	EPA 324/1631	BRL	8/25/08	< 27.0	No	No	
TotalHg-ST14-8/22/08	0835001-09	West Face - South end at corner (scaffolding level)	8/22/08	0.56	Mercury	EPA 324/1631	BRL	8/25/08	< 27.0	No	No	
TotalHg-ST15-8/22/08	0835001-10	South Face - East end at corner (scaffolding level)	8/22/08	0.52	Mercury	EPA 324/1631	BRL	8/25/08	< 29.0	No	No	
TotalHg-ST16-8/22/08	0835001-11	East Face - North end at corner (scaffolding level)	8/22/08	0.54	Mercury	EPA 324/1631	BRL	8/25/08	< 28.0	No	No	
TotalHg-ST17-8/22/08	0835001-12	North Face - West end at corner (scaffolding level)	8/22/08	0.51	Mercury	EPA 324/1631	BRL	8/25/08	< 29.0	No	No	