

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-9/8/07	0737006-01	Southwest Area (sidewalk bridge level)	9/8/07	0.56	Mercury	EPA 324/1631	BRL	9/11/07	< 27.0	No	No	
TotalHg-ST2-9/08/07	0737006-02	Southeast Area (sidewalk bridge level)	9/8/07	0.56	Mercury	EPA 324/1631	BRL	9/11/07	< 27.0	No	No	
TotalHg-ST4-9/08/07	0737006-03	Northwest Area (street-level)	9/8/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST5-9/08/07	0737006-04	Firehouse #10 (roof level)	9/8/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST10-9/08/07	0737006-05	North Side Sidewalk Bridge	9/8/07	0.53	Mercury	EPA 324/1631	BRL	9/11/07	< 28.0	No	No	
TotalHg-ST11-9/08/07	0737006-06	90 Trinity Place (roof level)	9/8/07	0.56	Mercury	EPA 324/1631	BRL	9/11/07	< 27.0	No	No	
TotalHg-ST12-9/08/07	0737006-07	110 Greenwich Street (roof level)	9/8/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST13-9/08/07	0737006-08	Marriott Hotel, 38th Floor (roof level)	9/8/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST14-9/08/07	0737006-09	West Face - South end at corner (scaffolding level)	9/8/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST15-9/08/07	0737006-10	South Face - East end at corner (scaffolding level)	9/8/07	0.58	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST16-9/08/07	0737006-11	East Face - North end at corner (scaffolding level)	9/8/07	0.56	Mercury	EPA 324/1631	BRL	9/11/07	< 27.0	No	No	
TotalHg-ST17-9/08/07	0737006-12	North Face - West end at corner (scaffolding level)	9/8/07	0.54	Mercury	EPA 324/1631	BRL	9/11/07	< 28.0	No	No	
TotalHg-ST1-9/9/07	0737010-01	Southwest Area (sidewalk bridge level)	9/9/07	0.56	Mercury	EPA 324/1631	BRL	9/11/07	< 27.0	No	No	
TotalHg-ST2-9/9/07	0737010-02	Southeast Area (sidewalk bridge level)	9/9/07	0.56	Mercury	EPA 324/1631	BRL	9/11/07	< 27.0	No	No	
TotalHg-ST4-9/9/07	0737010-03	Northwest Area (street-level)	9/9/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST5-9/9/07	0737010-04	Firehouse #10 (roof level)	9/9/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST10-9/9/07	0737010-05	North Side Sidewalk Bridge	9/9/07	0.53	Mercury	EPA 324/1631	BRL	9/11/07	< 28.0	No	No	
TotalHg-ST11-9/9/07	0737010-06	90 Trinity Place (roof level)	9/9/07	0.56	Mercury	EPA 324/1631	BRL	9/11/07	< 27.0	No	No	
TotalHg-ST12-9/9/07	0737010-07	110 Greenwich Street (roof level)	9/9/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST13-9/9/07	0737010-08	Marriott Hotel, 38th Floor (roof level)	9/9/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST14-9/9/07	0737010-09	West Face - South end at corner (scaffolding level)	9/9/07	0.57	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST15-9/9/07	0737010-10	South Face - East end at corner (scaffolding level)	9/9/07	0.58	Mercury	EPA 324/1631	BRL	9/11/07	< 26.0	No	No	
TotalHg-ST16-9/9/07	0737010-11	East Face - North end at corner (scaffolding level)	9/9/07	0.56	Mercury	EPA 324/1631	BRL	9/11/07	< 27.0	No	No	
TotalHg-ST17-9/9/07	0737010-12	North Face - West end at corner (scaffolding level)	9/9/07	0.54	Mercury	EPA 324/1631	BRL	9/11/07	< 28.0	No	No	