

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-9/17/07	0738012-01	Southwest Area (sidewalk bridge level)	9/17/07	0.54	Mercury	EPA 324/1631	BRL	9/19/07	< 28.0	No	No	
TotalHg-ST2-9/17/07	0738012-02	Southeast Area (sidewalk bridge level)	9/17/07	0.56	Mercury	EPA 324/1631	BRL	9/19/07	< 27.0	No	No	
TotalHg-ST4-9/17/07	0738012-03	Northwest Area (street-level)	9/17/07	0.58	Mercury	EPA 324/1631	BRL	9/19/07	< 26.0	No	No	
TotalHg-ST5-9/17/07	0738012-04	Firehouse #10 (roof level)	9/17/07	0.57	Mercury	EPA 324/1631	BRL	9/19/07	< 26.0	No	No	
TotalHg-ST10-9/17/07	0738012-05	North Side Sidewalk Bridge	9/17/07	0.62	Mercury	EPA 324/1631	BRL	9/19/07	< 24.0	No	No	
TotalHg-ST11-9/17/07	0738012-06	90 Trinity Place (roof level)	9/17/07	0.54	Mercury	EPA 324/1631	BRL	9/19/07	< 28.0	No	No	
TotalHg-ST12-9/17/07	0738012-07	110 Greenwich Street (roof level)	9/17/07	0.59	Mercury	EPA 324/1631	BRL	9/19/07	< 25.0	No	No	
TotalHg-ST13-9/17/07	0738012-08	Marriott Hotel, 38th Floor (roof level)	9/17/07	0.56	Mercury	EPA 324/1631	BRL	9/19/07	< 27.0	No	No	
TotalHg-ST14-9/17/07	0738012-09	West Face - South end at corner (scaffolding level)	9/17/07	0.56	Mercury	EPA 324/1631	BRL	9/19/07	< 27.0	No	No	
TotalHg-ST15-9/17/07	0738012-10	South Face - East end at corner (scaffolding level)	9/17/07	0.54	Mercury	EPA 324/1631	BRL	9/19/07	< 28.0	No	No	
TotalHg-ST16-9/17/07	0738012-11	East Face - North end at corner (scaffolding level)	9/17/07	0.55	Mercury	EPA 324/1631	BRL	9/19/07	< 27.0	No	No	
TotalHg-ST17-9/17/07	0738012-12	North Face - West end at corner (scaffolding level)	9/17/07	0.58	Mercury	EPA 324/1631	BRL	9/19/07	< 26.0	No	No	
TotalHg-ST1-9/18/07	0738015-01	Southwest Area (sidewalk bridge level)	9/18/07	0.57	Mercury	EPA 324/1631	BRL	9/20/07	< 26.0	No	No	
TotalHg-ST2-9/18/07	0738015-02	Southeast Area (sidewalk bridge level)	9/18/07	0.59	Mercury	EPA 324/1631	BRL	9/20/07	< 25.0	No	No	
TotalHg-ST4-9/18/07	0738015-03	Northwest Area (street-level)	9/18/07	0.54	Mercury	EPA 324/1631	BRL	9/20/07	< 28.0	No	No	
TotalHg-ST5-9/18/07	0738015-04	Firehouse #10 (roof level)	9/18/07	0.57	Mercury	EPA 324/1631	BRL	9/20/07	< 26.0	No	No	
TotalHg-ST10-9/18/07	0738015-05	North Side Sidewalk Bridge	9/18/07	0.55	Mercury	EPA 324/1631	BRL	9/20/07	< 27.0	No	No	
TotalHg-ST11-9/18/07	0738015-06	90 Trinity Place (roof level)	9/18/07	0.56	Mercury	EPA 324/1631	BRL	9/20/07	< 27.0	No	No	
TotalHg-ST12-9/18/07	0738015-07	110 Greenwich Street (roof level)	9/18/07	0.55	Mercury	EPA 324/1631	BRL	9/20/07	< 27.0	No	No	
TotalHg-ST13-9/18/07	0738015-08	Marriott Hotel, 38th Floor (roof level)	9/18/07	0.54	Mercury	EPA 324/1631	BRL	9/20/07	< 28.0	No	No	
TotalHg-ST14-9/18/07	0738015-09	West Face - South end at corner (scaffolding level)	9/18/07	0.57	Mercury	EPA 324/1631	BRL	9/20/07	< 26.0	No	No	
TotalHg-ST15-9/18/07	0738015-10	South Face - East end at corner (scaffolding level)	9/18/07	0.54	Mercury	EPA 324/1631	BRL	9/20/07	< 28.0	No	No	
TotalHg-ST16-9/18/07	0738015-11	East Face - North end at corner (scaffolding level)	9/18/07	0.59	Mercury	EPA 324/1631	BRL	9/20/07	< 25.0	No	No	
TotalHg-ST17-9/18/07	0738015-12	North Face - West end at corner (scaffolding level)	9/18/07	0.58	Mercury	EPA 324/1631	BRL	9/20/07	< 26.0	No	No	