

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-9/17/08	0838026-01	Southwest Area (sidewalk bridge level)	9/17/08	0.55	Mercury	EPA 324/1631	BRL	9/19/08	< 27.0	No	No	
TotalHg-ST2-9/17/08	0838026-02	Southeast Area (sidewalk bridge level)	9/17/08	0.55	Mercury	EPA 324/1631	BRL	9/19/08	< 27.0	No	No	
TotalHg-ST4-9/17/08	0838026-03	Northwest Area (street-level)	9/17/08	0.59	Mercury	EPA 324/1631	BRL	9/19/08	< 25.0	No	No	
TotalHg-ST5-9/17/08	0838026-04	Firehouse #10 (roof level)	9/17/08	0.57	Mercury	EPA 324/1631	BRL	9/19/08	< 26.0	No	No	
TotalHg-ST10-9/17/08	0838026-05	North Side Sidewalk Bridge	9/17/08	0.57	Mercury	EPA 324/1631	BRL	9/19/08	< 26.0	No	No	
TotalHg-ST11-9/17/08	0838026-06	90 Trinity Place (roof level)	9/17/08	0.60	Mercury	EPA 324/1631	BRL	9/19/08	< 25.0	No	No	
TotalHg-ST12-9/17/08	0838026-07	110 Greenwich Street (roof level)	9/17/08	0.55	Mercury	EPA 324/1631	BRL	9/19/08	< 27.0	No	No	
TotalHg-ST13-9/17/08	0838026-08	Marriott Hotel, 38th Floor (roof level)	9/17/08	0.56	Mercury	EPA 324/1631	BRL	9/19/08	< 27.0	No	No	
TotalHg-ST14-9/17/08	0838026-09	West Face - South end at corner (scaffolding level)	9/17/08	0.56	Mercury	EPA 324/1631	BRL	9/19/08	< 27.0	No	No	
TotalHg-ST15-9/17/08	0838026-10	South Face - East end at corner (scaffolding level)	9/17/08	0.55	Mercury	EPA 324/1631	BRL	9/19/08	< 27.0	No	No	
TotalHg-ST16-9/17/08	0838026-11	East Face - North end at corner (scaffolding level)	9/17/08	0.57	Mercury	EPA 324/1631	BRL	9/19/08	< 26.0	No	No	
TotalHg-ST17-9/17/08	0838026-12	North Face - West end at corner (scaffolding level)	9/17/08	0.54	Mercury	EPA 324/1631	BRL	9/19/08	< 28.0	No	No	
TotalHg-ST1-9/18/08	0838033-01	Southwest Area (sidewalk bridge level)	9/18/08	0.59	Mercury	EPA 324/1631	BRL	9/20/08	< 25.0	No	No	
TotalHg-ST2-9/18/08	0838033-02	Southeast Area (sidewalk bridge level)	9/18/08	0.58	Mercury	EPA 324/1631	BRL	9/20/08	< 26.0	No	No	
TotalHg-ST4-9/18/08	0838033-03	Northwest Area (street-level)	9/18/08	0.58	Mercury	EPA 324/1631	BRL	9/20/08	< 26.0	No	No	
TotalHg-ST5-9/18/08	0838033-04	Firehouse #10 (roof level)	9/18/08	0.55	Mercury	EPA 324/1631	BRL	9/20/08	< 27.0	No	No	
TotalHg-ST10-9/18/08	0838033-05	North Side Sidewalk Bridge	9/18/08	0.56	Mercury	EPA 324/1631	BRL	9/20/08	< 27.0	No	No	
TotalHg-ST11-9/18/08	0838033-06	90 Trinity Place (roof level)	9/18/08	0.54	Mercury	EPA 324/1631	BRL	9/20/08	< 28.0	No	No	
TotalHg-ST12-9/18/08	0838033-07	110 Greenwich Street (roof level)	9/18/08	0.55	Mercury	EPA 324/1631	BRL	9/20/08	< 27.0	No	No	
TotalHg-ST13-9/18/08	0838033-08	Marriott Hotel, 38th Floor (roof level)	9/18/08	0.57	Mercury	EPA 324/1631	BRL	9/20/08	< 26.0	No	No	
TotalHg-ST14-9/18/08	0838033-09	West Face - South end at corner (scaffolding level)	9/18/08	0.56	Mercury	EPA 324/1631	BRL	9/20/08	< 27.0	No	No	
TotalHg-ST15-9/18/08	0838033-10	South Face - East end at corner (scaffolding level)	9/18/08	0.53	Mercury	EPA 324/1631	BRL	9/20/08	< 28.0	No	No	
TotalHg-ST16-9/18/08	0838033-11	East Face - North end at corner (scaffolding level)	9/18/08	0.53	Mercury	EPA 324/1631	BRL	9/20/08	< 28.0	No	No	
TotalHg-ST17-9/18/08	0838033-12	North Face - West end at corner (scaffolding level)	9/18/08	0.56	Mercury	EPA 324/1631	BRL	9/20/08	< 27.0	No	No	
TotalHg-ST1-9/19/08	0839001-01	Southwest Area (sidewalk bridge level)	9/19/08	0.57	Mercury	EPA 324/1631	BRL	9/22/08	< 26.0	No	No	
TotalHg-ST2-9/19/08	0839001-02	Southeast Area (sidewalk bridge level)	9/19/08	0.58	Mercury	EPA 324/1631	BRL	9/22/08	< 26.0	No	No	
TotalHg-ST4-9/19/08	0839001-03	Northwest Area (street-level)	9/19/08	0.6	Mercury	EPA 324/1631	BRL	9/22/08	< 25.0	No	No	
TotalHg-ST5-9/19/08	0839001-04	Firehouse #10 (roof level)	9/19/08	0.57	Mercury	EPA 324/1631	BRL	9/22/08	< 26.0	No	No	
TotalHg-ST10-9/19/08	0839001-05	North Side Sidewalk Bridge	9/19/08	0.59	Mercury	EPA 324/1631	BRL	9/22/08	< 25.0	No	No	
TotalHg-ST11-9/19/08	0839001-06	90 Trinity Place (roof level)	9/19/08	0.55	Mercury	EPA 324/1631	BRL	9/22/08	< 27.0	No	No	
TotalHg-ST12-9/19/08	0839001-07	110 Greenwich Street (roof level)	9/19/08	0.55	Mercury	EPA 324/1631	BRL	9/22/08	< 27.0	No	No	
TotalHg-ST13-9/19/08	0839001-08	Marriott Hotel, 38th Floor (roof level)	9/19/08	0.61	Mercury	EPA 324/1631	BRL	9/22/08	< 25.0	No	No	
TotalHg-ST14-9/19/08	0839001-09	West Face - South end at corner (scaffolding level)	9/19/08	0.54	Mercury	EPA 324/1631	BRL	9/22/08	< 28.0	No	No	
TotalHg-ST15-9/19/08	0839001-10	South Face - East end at corner (scaffolding level)	9/19/08	0.56	Mercury	EPA 324/1631	BRL	9/22/08	< 27.0	No	No	
TotalHg-ST16-9/19/08	0839001-11	East Face - North end at corner (scaffolding level)	9/19/08	0.55	Mercury	EPA 324/1631	BRL	9/22/08	< 27.0	No	No	
TotalHg-ST17-9/19/08	0839001-12	North Face - West end at corner (scaffolding level)	9/19/08	0.55	Mercury	EPA 324/1631	BRL	9/22/08	< 27.0	No	No	