

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-9/27/06	06BR1561-01	Southwest Area (sidewalk bridge level)	9/27/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST2-9/27/06	06BR1561-02	Southeast Area (sidewalk bridge level)	9/27/06	0.58	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST4-9/27/06	06BR1561-03	Northwest Area (street-level)	9/27/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST5-9/27/06	06BR1561-04	Firehouse #10 (roof level)	9/27/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST10-9/27/06	06BR1561-05	North Side Sidewalk Bridge	9/27/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST11-9/27/06	06BR1561-06	90 Trinity Place (roof level)	9/27/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST12-9/27/06	06BR1561-07	110 Greenwich Street (roof level)	9/27/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST13-9/27/06	06BR1561-08	Marriott Hotel, 38th Floor (roof level)	9/27/06	0.60	Mercury	EPA 324/1631	BRL	9/30/06	< 25.0	No	No	
TotalHg-ST14-9/27/06	06BR1561-09	West Face - South end at corner (scaffolding level)	9/27/06	0.58	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST15-9/27/06	06BR1561-10	South Face - East end at corner (scaffolding level)	9/27/06	0.55	Mercury	EPA 324/1631	BRL	9/30/06	< 27.0	No	No	
TotalHg-ST16-9/27/06	06BR1561-11	East Face - North end at corner (scaffolding level)	9/27/06	0.54	Mercury	EPA 324/1631	BRL	9/30/06	< 28.0	No	No	
TotalHg-ST17-9/27/06	06BR1561-12	North Face - West end at corner (scaffolding level)	9/27/06	0.58	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST1-9/28/06	06BR1563-01	Southwest Area (sidewalk bridge level)	9/28/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST2-9/28/06	06BR1563-02	Southeast Area (sidewalk bridge level)	9/28/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST4-9/28/06	06BR1563-03	Northwest Area (street-level)	9/28/06	0.56	Mercury	EPA 324/1631	BRL	9/30/06	< 27.0	No	No	
TotalHg-ST5-9/28/06	06BR1563-04	Firehouse #10 (roof level)	9/28/06	0.58	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST10-9/28/06	06BR1563-05	North Side Sidewalk Bridge	9/28/06	0.58	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST11-9/28/06	06BR1563-06	90 Trinity Place (roof level)	9/28/06	0.60	Mercury	EPA 324/1631	BRL	9/30/06	< 25.0	No	No	
TotalHg-ST12-9/28/06	06BR1563-07	110 Greenwich Street (roof level)	9/28/06	0.56	Mercury	EPA 324/1631	BRL	9/30/06	< 27.0	No	No	
TotalHg-ST13-9/28/06	06BR1563-08	Marriott Hotel, 38th Floor (roof level)	9/28/06	0.58	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST14-9/28/06	06BR1563-09	West Face - South end at corner (scaffolding level)	9/28/06	0.57	Mercury	EPA 324/1631	BRL	9/30/06	< 26.0	No	No	
TotalHg-ST15-9/28/06	06BR1563-10	South Face - East end at corner (scaffolding level)	9/28/06	0.56	Mercury	EPA 324/1631	BRL	9/30/06	< 27.0	No	No	
TotalHg-ST16-9/28/06	06BR1563-11	East Face - North end at corner (scaffolding level)	9/28/06	0.56	Mercury	EPA 324/1631	BRL	9/30/06	< 27.0	No	No	
TotalHg-ST17-9/28/06	06BR1563-12	North Face - West end at corner (scaffolding level)	9/28/06	0.56	Mercury	EPA 324/1631	BRL	9/30/06	< 27.0	No	No	