

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-9/29/08	0840021-01	Southwest Area (sidewalk bridge level)	9/29/08	0.59	Mercury	EPA 324/1631	BRL	10/1/08	< 25.0	No	No	
TotalHg-ST2-9/29/08	0840021-02	Southeast Area (sidewalk bridge level)	9/29/08	0.56	Mercury	EPA 324/1631	BRL	10/1/08	< 27.0	No	No	
TotalHg-ST4-9/29/08	0840021-03	Northwest Area (street-level)	9/29/08	0.54	Mercury	EPA 324/1631	BRL	10/1/08	< 28.0	No	No	
TotalHg-ST5-9/29/08	0840021-04	Firehouse #10 (roof level)	9/29/08	0.56	Mercury	EPA 324/1631	BRL	10/1/08	< 27.0	No	No	
TotalHg-ST10-9/29/08	0840021-05	North Side Sidewalk Bridge	9/29/08	0.53	Mercury	EPA 324/1631	BRL	10/1/08	< 28.0	No	No	
TotalHg-ST11-9/29/08	0840021-06	90 Trinity Place (roof level)	9/29/08	0.55	Mercury	EPA 324/1631	BRL	10/1/08	< 27.0	No	No	
TotalHg-ST12-9/29/08	0840021-07	110 Greenwich Street (roof level)	9/29/08	0.56	Mercury	EPA 324/1631	BRL	10/1/08	< 27.0	No	No	
TotalHg-ST13-9/29/08	0840021-08	Marriott Hotel, 38th Floor (roof level)	9/29/08	0.58	Mercury	EPA 324/1631	BRL	10/1/08	< 26.0	No	No	
TotalHg-ST14-9/29/08	0840021-09	West Face - South end at corner (scaffolding level)	9/29/08	0.60	Mercury	EPA 324/1631	BRL	10/1/08	< 25.0	No	No	
TotalHg-ST15-9/29/08	0840021-10	South Face - East end at corner (scaffolding level)	9/29/08	0.56	Mercury	EPA 324/1631	BRL	10/1/08	< 27.0	No	No	
TotalHg-ST16-9/29/08	0840021-11	East Face - North end at corner (scaffolding level)	9/29/08	0.57	Mercury	EPA 324/1631	BRL	10/1/08	< 26.0	No	No	
TotalHg-ST17-9/29/08	0840021-12	North Face - West end at corner (scaffolding level)	9/29/08	0.57	Mercury	EPA 324/1631	BRL	10/1/08	< 26.0	No	No	
TotalHg-ST1-9/30/08	0840031-01	Southwest Area (sidewalk bridge level)	9/30/08	0.58	Mercury	EPA 324/1631	BRL	10/2/08	< 26.0	No	No	
TotalHg-ST2-9/30/08	0840031-02	Southeast Area (sidewalk bridge level)	9/30/08	0.56	Mercury	EPA 324/1631	BRL	10/2/08	< 27.0	No	No	
TotalHg-ST4-9/30/08	0840031-03	Northwest Area (street-level)	9/30/08	0.58	Mercury	EPA 324/1631	BRL	10/2/08	< 26.0	No	No	
TotalHg-ST5-9/30/08	0840031-04	Firehouse #10 (roof level)	9/30/08	0.53	Mercury	EPA 324/1631	BRL	10/2/08	< 28.0	No	No	
TotalHg-ST10-9/30/08	0840031-05	North Side Sidewalk Bridge	9/30/08	0.53	Mercury	EPA 324/1631	BRL	10/2/08	< 28.0	No	No	
TotalHg-ST11-9/30/08	0840031-06	90 Trinity Place (roof level)	9/30/08	0.53	Mercury	EPA 324/1631	BRL	10/2/08	< 28.0	No	No	
TotalHg-ST12-9/30/08	0840031-07	110 Greenwich Street (roof level)	9/30/08	0.54	Mercury	EPA 324/1631	BRL	10/2/08	< 28.0	No	No	
TotalHg-ST13-9/30/08	0840031-08	Marriott Hotel, 38th Floor (roof level)	9/30/08	0.58	Mercury	EPA 324/1631	BRL	10/2/08	< 26.0	No	No	
TotalHg-ST14-9/30/08	0840031-09	West Face - South end at corner (scaffolding level)	9/30/08	0.59	Mercury	EPA 324/1631	BRL	10/2/08	< 25.0	No	No	
TotalHg-ST15-9/30/08	0840031-10	South Face - East end at corner (scaffolding level)	9/30/08	0.53	Mercury	EPA 324/1631	BRL	10/2/08	< 28.0	No	No	
TotalHg-ST16-9/30/08	0840031-11	East Face - North end at corner (scaffolding level)	9/30/08	0.58	Mercury	EPA 324/1631	BRL	10/2/08	< 26.0	No	No	
TotalHg-ST17-9/30/08	0840031-12	North Face - West end at corner (scaffolding level)	9/30/08	0.53	Mercury	EPA 324/1631	BRL	10/2/08	< 28.0	No	No	