

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-10/2/09	0941003-01	Southwest Area (sidewalk bridge level)	10/2/09	0.58	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 25.9	No	No	
TotalHg-ST2-10/2/09	0941003-02	Southeast Area (sidewalk bridge level)	10/2/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.3	No	No	
TotalHg-ST4-10/2/09	0941003-03	Northwest Area (street-level)	10/2/09	0.55	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 27.3	No	No	
TotalHg-ST5-10/2/09	0941003-04	Firehouse #10 (roof level)	10/2/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.3	No	No	
TotalHg-ST10-10/2/09	0941003-05	North Side Sidewalk Bridge	10/2/09	0.53	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 28.3	No	No	
TotalHg-ST11-10/2/09	0941003-06	90 Trinity Place (roof level)	10/2/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.8	No	No	
TotalHg-ST12-10/2/09	0941003-07	110 Greenwich Street (roof level)	10/2/09	0.54	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 27.8	No	No	
TotalHg-ST13-10/2/09	0941003-08	Marriott Hotel, 38th Floor (roof level)	10/2/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.8	No	No	
TotalHg-ST1-10/3/09	0941002-01	Southwest Area (sidewalk bridge level)	10/3/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.3	No	No	
TotalHg-ST2-10/3/09	0941002-02	Southeast Area (sidewalk bridge level)	10/3/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.8	No	No	
TotalHg-ST4-10/3/09	0941002-03	Northwest Area (street-level)	10/3/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.8	No	No	
TotalHg-ST5-10/3/09	0941002-04	Firehouse #10 (roof level)	10/3/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.8	No	No	
TotalHg-ST10-10/3/09	0941002-05	North Side Sidewalk Bridge	10/3/09	0.59	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 25.4	No	No	
TotalHg-ST11-10/3/09	0941002-06	90 Trinity Place (roof level)	10/3/09	0.59	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 25.4	No	No	
TotalHg-ST12-10/3/09	0941002-07	110 Greenwich Street (roof level)	10/3/09	0.54	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 27.8	No	No	
TotalHg-ST13-10/3/09	0941002-08	Marriott Hotel, 38th Floor (roof level)	10/3/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.8	No	No	
TotalHg-ST1-10/4/09	0941001-01	Southwest Area (sidewalk bridge level)	10/4/09	0.60	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 25.0	No	No	
TotalHg-ST2-10/4/09	0941001-02	Southeast Area (sidewalk bridge level)	10/4/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 26.3	No	No	
TotalHg-ST4-10/4/09	0941001-03	Northwest Area (street-level)	10/4/09	0.59	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 25.4	No	No	
TotalHg-ST5-10/4/09	0941001-04	Firehouse #10 (roof level)	10/4/09	0.60	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 25.0	No	No	
TotalHg-ST10-10/4/09	0941001-05	North Side Sidewalk Bridge	10/4/09	0.59	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 25.4	No	No	
TotalHg-ST11-10/4/09	0941001-06	90 Trinity Place (roof level)	10/4/09	0.53	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 28.3	No	No	
TotalHg-ST12-10/4/09	0941001-07	110 Greenwich Street (roof level)	10/4/09	0.58	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 25.9	No	No	
TotalHg-ST13-10/4/09	0941001-08	Marriott Hotel, 38th Floor (roof level)	10/4/09	0.54	Mercury	EPA 324/1631 Auto	BRL	10/6/09	< 27.8	No	No	