

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-10/4/08	0841004-01	Southwest Area (sidewalk bridge level)	10/4/08	0.55	Mercury	EPA 324/1631	BRL	10/7/08	< 27.0	No	No	
TotalHg-ST2-10/4/08	0841004-02	Southeast Area (sidewalk bridge level)	10/4/08	0.53	Mercury	EPA 324/1631	BRL	10/7/08	< 28.0	No	No	
TotalHg-ST4-10/4/08	0841004-03	Northwest Area (street-level)	10/4/08	0.55	Mercury	EPA 324/1631	BRL	10/7/08	< 27.0	No	No	
TotalHg-ST5-10/4/08	0841004-04	Firehouse #10 (roof level)	10/4/08	0.54	Mercury	EPA 324/1631	BRL	10/7/08	< 28.0	No	No	
TotalHg-ST10-10/4/08	0841004-05	North Side Sidewalk Bridge	10/4/08	0.57	Mercury	EPA 324/1631	BRL	10/7/08	< 26.0	No	No	
TotalHg-ST11-10/4/08	0841004-06	90 Trinity Place (roof level)	10/4/08	0.57	Mercury	EPA 324/1631	BRL	10/7/08	< 26.0	No	No	
TotalHg-ST12-10/4/08	0841004-07	110 Greenwich Street (roof level)	10/4/08	0.56	Mercury	EPA 324/1631	BRL	10/7/08	< 27.0	No	No	
TotalHg-ST13-10/4/08	0841004-08	Marriott Hotel, 38th Floor (roof level)	10/4/08	0.54	Mercury	EPA 324/1631	BRL	10/7/08	< 28.0	No	No	
TotalHg-ST14-10/4/08	0841004-09	West Face - South end at corner (scaffolding level)	10/4/08	0.56	Mercury	EPA 324/1631	BRL	10/7/08	< 27.0	No	No	
TotalHg-ST15-10/4/08	0841004-10	South Face - East end at corner (scaffolding level)	10/4/08	0.58	Mercury	EPA 324/1631	BRL	10/7/08	< 26.0	No	No	
TotalHg-ST16-10/4/08	0841004-11	East Face - North end at corner (scaffolding level)	10/4/08	0.53	Mercury	EPA 324/1631	BRL	10/7/08	< 28.0	No	No	
TotalHg-ST17-10/4/08	0841004-12	North Face - West end at corner (scaffolding level)	10/4/08	0.57	Mercury	EPA 324/1631	BRL	10/7/08	< 26.0	No	No	
TotalHg-ST1-10/5/08	0841005-01	Southwest Area (sidewalk bridge level)	10/5/08	0.54	Mercury	EPA 324/1631	BRL	10/7/08	< 28.0	No	No	
TotalHg-ST2-10/5/08	0841005-02	Southeast Area (sidewalk bridge level)	10/5/08	0.57	Mercury	EPA 324/1631	BRL	10/7/08	< 26.0	No	No	
TotalHg-ST4-10/5/08	0841005-03	Northwest Area (street-level)	10/5/08	0.62	Mercury	EPA 324/1631	BRL	10/7/08	< 24.0	No	No	
TotalHg-ST5-10/5/08	0841005-04	Firehouse #10 (roof level)	10/5/08	0.59	Mercury	EPA 324/1631	BRL	10/7/08	< 25.0	No	No	
TotalHg-ST10-10/5/08	0841005-05	North Side Sidewalk Bridge	10/5/08	0.57	Mercury	EPA 324/1631	BRL	10/7/08	< 26.0	No	No	
TotalHg-ST11-10/5/08	0841005-06	90 Trinity Place (roof level)	10/5/08	0.55	Mercury	EPA 324/1631	BRL	10/7/08	< 27.0	No	No	
TotalHg-ST12-10/5/08	0841005-07	110 Greenwich Street (roof level)	10/5/08	0.58	Mercury	EPA 324/1631	BRL	10/7/08	< 26.0	No	No	
TotalHg-ST13-10/5/08	0841005-08	Marriott Hotel, 38th Floor (roof level)	10/5/08	0.56	Mercury	EPA 324/1631	BRL	10/7/08	< 27.0	No	No	
TotalHg-ST14-10/5/08	0841005-09	West Face - South end at corner (scaffolding level)	10/5/08	0.63	Mercury	EPA 324/1631	BRL	10/7/08	< 24.0	No	No	
TotalHg-ST15-10/5/08	0841005-10	South Face - East end at corner (scaffolding level)	10/5/08	0.58	Mercury	EPA 324/1631	BRL	10/7/08	< 26.0	No	No	
TotalHg-ST16-10/5/08	0841005-11	East Face - North end at corner (scaffolding level)	10/5/08	0.59	Mercury	EPA 324/1631	BRL	10/7/08	< 25.0	No	No	
TotalHg-ST17-10/5/08	0841005-12	North Face - West end at corner (scaffolding level)	10/5/08	0.59	Mercury	EPA 324/1631	BRL	10/7/08	< 25.0	No	No	