

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-10/7/08	0841023-01	Southwest Area (sidewalk bridge level)	10/7/08	0.56	Mercury	EPA 324/1631	BRL	10/9/08	< 27.0	No	No	
TotalHg-ST2-10/7/08	0841023-02	Southeast Area (sidewalk bridge level)	10/7/08	0.57	Mercury	EPA 324/1631	BRL	10/9/08	< 26.0	No	No	
TotalHg-ST4-10/7/08	0841023-03	Northwest Area (street-level)	10/7/08	0.60	Mercury	EPA 324/1631	BRL	10/9/08	< 25.0	No	No	
TotalHg-ST5-10/7/08	0841023-04	Firehouse #10 (roof level)	10/7/08	0.54	Mercury	EPA 324/1631	BRL	10/9/08	< 28.0	No	No	
TotalHg-ST10-10/7/08	0841023-05	North Side Sidewalk Bridge	10/7/08	0.54	Mercury	EPA 324/1631	BRL	10/9/08	< 28.0	No	No	
TotalHg-ST11-10/7/08	0841023-06	90 Trinity Place (roof level)	10/7/08	0.59	Mercury	EPA 324/1631	BRL	10/9/08	< 25.0	No	No	
TotalHg-ST12-10/7/08	0841023-07	110 Greenwich Street (roof level)	10/7/08	0.54	Mercury	EPA 324/1631	BRL	10/9/08	< 28.0	No	No	
TotalHg-ST13-10/7/08	0841023-08	Marriott Hotel, 38th Floor (roof level)	10/7/08	0.57	Mercury	EPA 324/1631	BRL	10/9/08	< 26.0	No	No	
TotalHg-ST14-10/7/08	0841023-09	West Face - South end at corner (scaffolding level)	10/7/08	0.58	Mercury	EPA 324/1631	BRL	10/9/08	< 26.0	No	No	
TotalHg-ST15-10/7/08	0841023-10	South Face - East end at corner (scaffolding level)	10/7/08	0.55	Mercury	EPA 324/1631	BRL	10/9/08	< 27.0	No	No	
TotalHg-ST16-10/7/08	0841023-11	East Face - North end at corner (scaffolding level)	10/7/08	0.55	Mercury	EPA 324/1631	BRL	10/9/08	< 27.0	No	No	
TotalHg-ST17-10/7/08	0841023-12	North Face - West end at corner (scaffolding level)	10/7/08	0.56	Mercury	EPA 324/1631	BRL	10/9/08	< 27.0	No	No	
TotalHg-ST1-10/8/08	0841031-01	Southwest Area (sidewalk bridge level)	10/8/08	0.55	Mercury	EPA 324/1631	BRL	10/10/08	< 27.0	No	No	
TotalHg-ST2-10/8/08	0841031-02	Southeast Area (sidewalk bridge level)	10/8/08	0.58	Mercury	EPA 324/1631	BRL	10/10/08	< 26.0	No	No	
TotalHg-ST4-10/8/08	0841031-03	Northwest Area (street-level)	10/8/08	0.56	Mercury	EPA 324/1631	BRL	10/10/08	< 27.0	No	No	
TotalHg-ST5-10/8/08	0841031-04	Firehouse #10 (roof level)	10/8/08	0.56	Mercury	EPA 324/1631	BRL	10/10/08	< 27.0	No	No	
TotalHg-ST10-10/8/08	0841031-05	North Side Sidewalk Bridge	10/8/08	0.55	Mercury	EPA 324/1631	BRL	10/10/08	< 27.0	No	No	
TotalHg-ST11-10/8/08	0841031-06	90 Trinity Place (roof level)	10/8/08	0.54	Mercury	EPA 324/1631	BRL	10/10/08	< 28.0	No	No	
TotalHg-ST12-10/8/08	0841031-07	110 Greenwich Street (roof level)	10/8/08	0.54	Mercury	EPA 324/1631	BRL	10/10/08	< 28.0	No	No	
TotalHg-ST13-10/8/08	0841031-08	Marriott Hotel, 38th Floor (roof level)	10/8/08	0.58	Mercury	EPA 324/1631	BRL	10/10/08	< 26.0	No	No	
TotalHg-ST14-10/8/08	0841031-09	West Face - South end at corner (scaffolding level)	10/8/08	0.59	Mercury	EPA 324/1631	BRL	10/10/08	< 25.0	No	No	
TotalHg-ST15-10/8/08	0841031-10	South Face - East end at corner (scaffolding level)	10/8/08	0.56	Mercury	EPA 324/1631	BRL	10/10/08	< 27.0	No	No	
TotalHg-ST16-10/8/08	0841031-11	East Face - North end at corner (scaffolding level)	10/8/08	0.60	Mercury	EPA 324/1631	BRL	10/10/08	< 25.0	No	No	
TotalHg-ST17-10/8/08	0841031-12	North Face - West end at corner (scaffolding level)	10/8/08	0.55	Mercury	EPA 324/1631	BRL	10/10/08	< 27.0	No	No	
TotalHg-ST1-10/9/08	0841039-01	Southwest Area (sidewalk bridge level)	10/9/08	0.55	Mercury	EPA 324/1631	BRL	10/11/08	< 27.0	No	No	
TotalHg-ST2-10/9/08	0841039-02	Southeast Area (sidewalk bridge level)	10/9/08	0.55	Mercury	EPA 324/1631	BRL	10/11/08	< 27.0	No	No	
TotalHg-ST4-10/9/08	0841039-03	Northwest Area (street-level)	10/9/08	0.54	Mercury	EPA 324/1631	BRL	10/11/08	< 28.0	No	No	
TotalHg-ST5-10/9/08	0841039-04	Firehouse #10 (roof level)	10/9/08	0.58	Mercury	EPA 324/1631	BRL	10/11/08	< 26.0	No	No	
TotalHg-ST10-10/9/08	0841039-05	North Side Sidewalk Bridge	10/9/08	0.53	Mercury	EPA 324/1631	BRL	10/11/08	< 28.0	No	No	
TotalHg-ST11-10/9/08	0841039-06	90 Trinity Place (roof level)	10/9/08	0.55	Mercury	EPA 324/1631	BRL	10/11/08	< 27.0	No	No	
TotalHg-ST12-10/9/08	0841039-07	110 Greenwich Street (roof level)	10/9/08	0.56	Mercury	EPA 324/1631	BRL	10/11/08	< 27.0	No	No	
TotalHg-ST13-10/9/08	0841039-08	Marriott Hotel, 38th Floor (roof level)	10/9/08	0.55	Mercury	EPA 324/1631	BRL	10/11/08	< 27.0	No	No	
TotalHg-ST14-10/9/08	0841039-09	West Face - South end at corner (scaffolding level)	10/9/08	0.60	Mercury	EPA 324/1631	BRL	10/11/08	< 25.0	No	No	
TotalHg-ST15-10/9/08	0841039-10	South Face - East end at corner (scaffolding level)	10/9/08	0.60	Mercury	EPA 324/1631	BRL	10/11/08	< 25.0	No	No	
TotalHg-ST16-10/9/08	0841039-11	East Face - North end at corner (scaffolding level)	10/9/08	0.57	Mercury	EPA 324/1631	BRL	10/11/08	< 26.0	No	No	
TotalHg-ST17-10/9/08	0841039-12	North Face - West end at corner (scaffolding level)	10/9/08	0.57	Mercury	EPA 324/1631	BRL	10/11/08	< 26.0	No	No	
TotalHg-ST1-10/10/08	0842001-01	Southwest Area (sidewalk bridge level)	10/10/08	0.55	Mercury	EPA 324/1631	BRL	10/13/08	< 27.0	No	No	
TotalHg-ST2-10/10/08	0842001-02	Southeast Area (sidewalk bridge level)	10/10/08	0.58	Mercury	EPA 324/1631	BRL	10/13/08	< 26.0	No	No	
TotalHg-ST4-10/10/08	0842001-03	Northwest Area (street-level)	10/10/08	0.55	Mercury	EPA 324/1631	BRL	10/13/08	< 27.0	No	No	
TotalHg-ST5-10/10/08	0842001-04	Firehouse #10 (roof level)	10/10/08	0.54	Mercury	EPA 324/1631	BRL	10/13/08	< 28.0	No	No	
TotalHg-ST10-10/10/08	0842001-05	North Side Sidewalk Bridge	10/10/08	0.56	Mercury	EPA 324/1631	BRL	10/13/08	< 27.0	No	No	
TotalHg-ST11-10/10/08	0842001-06	90 Trinity Place (roof level)	10/10/08	0.58	Mercury	EPA 324/1631	BRL	10/13/08	< 26.0	No	No	
TotalHg-ST12-10/10/08	0842001-07	110 Greenwich Street (roof level)	10/10/08	0.56	Mercury	EPA 324/1631	BRL	10/13/08	< 27.0	No	No	
TotalHg-ST13-10/10/08	0842001-08	Marriott Hotel, 38th Floor (roof level)	10/10/08	0.56	Mercury	EPA 324/1631	BRL	10/13/08	< 27.0	No	No	
TotalHg-ST14-10/10/08	0842001-09	South Face - East end at corner (scaffolding level)	10/10/08	0.49	Mercury	EPA 324/1631	BRL	10/13/08	< 31.0	No	No	
TotalHg-ST15-10/10/08	0842001-10	East Face - North end at corner (scaffolding level)	10/10/08	0.51	Mercury	EPA 324/1631	BRL	10/13/08	< 29.0	No	No	
TotalHg-ST16-10/10/08	0842001-11	East Face - North end at corner (scaffolding level)	10/10/08	0.52	Mercury	EPA 324/1631	BRL	10/13/08	< 29.0	No	No	
TotalHg-ST17-10/10/08	0842001-12	North Face - West end at corner (scaffolding level)	10/10/08	0.55	Mercury	EPA 324/1631	BRL	10/13/08	< 27.0	No	No	