

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-10/12/07	0742003-01	Southwest Area (sidewalk bridge level)	10/12/07	0.54	Mercury	EPA 324/1631	BRL	10/16/07	< 28.0	No	No	
TotalHg-ST2-10/12/07	0742003-02	Southeast Area (sidewalk bridge level)	10/12/07	0.61	Mercury	EPA 324/1631	BRL	10/16/07	< 25.0	No	No	
TotalHg-ST4-10/12/07	0742003-03	Northwest Area (street-level)	10/12/07	0.56	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST5-10/12/07	0742003-04	Firehouse #10 (roof level)	10/12/07	0.57	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST10-10/12/07	0742003-05	North Side Sidewalk Bridge	10/12/07	0.57	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST11-10/12/07	0742003-06	90 Trinity Place (roof level)	10/12/07	0.56	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST12-10/12/07	0742003-07	110 Greenwich Street (roof level)	10/12/07	0.55	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST13-10/12/07	0742003-08	Marriott Hotel, 38th Floor (roof level)	10/12/07	0.58	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST14-10/12/07	0742003-09	West Face - South end at corner (scaffolding level)	10/12/07	0.51	Mercury	EPA 324/1631	BRL	10/16/07	< 29.0	No	No	
TotalHg-ST15-10/12/07	0742003-10	South Face - East end at corner (scaffolding level)	10/12/07	0.54	Mercury	EPA 324/1631	BRL	10/16/07	< 28.0	No	No	
TotalHg-ST16-10/12/07	0742003-11	East Face - North end at corner (scaffolding level)	10/12/07	0.59	Mercury	EPA 324/1631	BRL	10/16/07	< 25.0	No	No	
TotalHg-ST17-10/12/07	0742003-12	North Face - West end at corner (scaffolding level)	10/12/07	0.55	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST1-10/13/07	0742004-01	Southwest Area (sidewalk bridge level)	10/13/07	0.55	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST2-10/13/07	0742004-02	Southeast Area (sidewalk bridge level)	10/13/07	0.58	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST4-10/13/07	0742004-03	Northwest Area (street-level)	10/13/07	0.58	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST5-10/13/07	0742004-04	Firehouse #10 (roof level)	10/13/07	0.54	Mercury	EPA 324/1631	BRL	10/16/07	< 28.0	No	No	
TotalHg-ST10-10/13/07	0742004-05	North Side Sidewalk Bridge	10/13/07	0.55	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST11-10/13/07	0742004-06	90 Trinity Place (roof level)	10/13/07	0.55	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST12-10/13/07	0742004-07	110 Greenwich Street (roof level)	10/13/07	0.58	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST13-10/13/07	0742004-08	Marriott Hotel, 38th Floor (roof level)	10/13/07	0.56	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST14-10/13/07	0742004-09	West Face - South end at corner (scaffolding level)	10/13/07	0.58	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST15-10/13/07	0742004-10	South Face - East end at corner (scaffolding level)	10/13/07	0.59	Mercury	EPA 324/1631	BRL	10/16/07	< 25.0	No	No	
TotalHg-ST16-10/13/07	0742004-11	East Face - North end at corner (scaffolding level)	10/13/07	0.59	Mercury	EPA 324/1631	BRL	10/16/07	< 25.0	No	No	
TotalHg-ST17-10/13/07	0742004-12	North Face - West end at corner (scaffolding level)	10/13/07	0.56	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST1-10/14/07	0742005-01	Southwest Area (sidewalk bridge level)	10/14/07	0.55	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST2-10/14/07	0742005-02	Southeast Area (sidewalk bridge level)	10/14/07	0.59	Mercury	EPA 324/1631	BRL	10/16/07	< 25.0	No	No	
TotalHg-ST4-10/14/07	0742005-03	Northwest Area (street-level)	10/14/07	0.60	Mercury	EPA 324/1631	BRL	10/16/07	< 25.0	No	No	
TotalHg-ST5-10/14/07	0742005-04	Firehouse #10 (roof level)	10/14/07	0.56	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST10-10/14/07	0742005-05	North Side Sidewalk Bridge	10/14/07	0.56	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST11-10/14/07	0742005-06	90 Trinity Place (roof level)	10/14/07	0.56	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST12-10/14/07	0742005-07	110 Greenwich Street (roof level)	10/14/07	0.57	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST13-10/14/07	0742005-08	Marriott Hotel, 38th Floor (roof level)	10/14/07	0.60	Mercury	EPA 324/1631	BRL	10/16/07	< 25.0	No	No	
TotalHg-ST14-10/14/07	0742005-09	West Face - South end at corner (scaffolding level)	10/14/07	0.57	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST15-10/14/07	0742005-10	South Face - East end at corner (scaffolding level)	10/14/07	0.58	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	
TotalHg-ST16-10/14/07	0742005-11	East Face - North end at corner (scaffolding level)	10/14/07	0.56	Mercury	EPA 324/1631	BRL	10/16/07	< 27.0	No	No	
TotalHg-ST17-10/14/07	0742005-12	North Face - West end at corner (scaffolding level)	10/14/07	0.58	Mercury	EPA 324/1631	BRL	10/16/07	< 26.0	No	No	