

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|-------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---------------------------------------|-----------------------------------|--|----------|
| | | | | | | | | | 300 | | | |
| | | | | | | | | | 3,000 | | | |
| Target Air Quality Levels | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | |
| TotalHg-ST1-11/1/06 | 06BR1759-01 | Southwest Area (sidewalk bridge level) | 11/1/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 26.0 | No | No | |
| TotalHg-ST2-11/1/06 | 06BR1759-02 | Southeast Area (sidewalk bridge level) | 11/1/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 27.0 | No | No | |
| TotalHg-ST4-11/1/06 | 06BR1759-03 | Northwest Area (street-level) | 11/1/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 26.0 | No | No | |
| TotalHg-ST5-11/1/06 | 06BR1759-04 | Firehouse #10 (roof level) | 11/1/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 27.0 | No | No | |
| TotalHg-ST10-11/1/06 | 06BR1759-05 | North Side Sidewalk Bridge | 11/1/06 | 0.60 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 25.0 | No | No | |
| TotalHg-ST11-11/1/06 | 06BR1759-06 | 90 Trinity Place (roof level) | 11/1/06 | 0.62 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 24.0 | No | No | |
| TotalHg-ST12-11/1/06 | 06BR1759-07 | 110 Greenwich Street (roof level) | 11/1/06 | 0.59 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 25.0 | No | No | |
| TotalHg-ST13-11/1/06 | 06BR1759-08 | Marriott Hotel, 38th Floor (roof level) | 11/1/06 | 0.62 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 24.0 | No | No | |
| TotalHg-ST14-11/1/06 | 06BR1759-09 | West Face - South end at corner (scaffolding level) | 11/1/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 27.0 | No | No | |
| TotalHg-ST15-11/1/06 | 06BR1759-10 | South Face - East end at corner (scaffolding level) | 11/1/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 27.0 | No | No | |
| TotalHg-ST16-11/1/06 | 06BR1759-11 | East Face - North end at corner (scaffolding level) | 11/1/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 26.0 | No | No | |
| TotalHg-ST17-11/1/06 | 06BR1759-12 | North Face - West end at corner (scaffolding level) | 11/1/06 | 0.54 | Mercury | EPA 324/1631 | BRL | 11/3/06 | < 28.0 | No | No | |
| TotalHg-ST1-11/2/06 | 06BR1767-01 | Southwest Area (sidewalk bridge level) | 11/2/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 26.0 | No | No | |
| TotalHg-ST2-11/2/06 | 06BR1767-02 | Southeast Area (sidewalk bridge level) | 11/2/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 27.0 | No | No | |
| TotalHg-ST4-11/2/06 | 06BR1767-03 | Northwest Area (street-level) | 11/2/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 27.0 | No | No | |
| TotalHg-ST5-11/2/06 | 06BR1767-04 | Firehouse #10 (roof level) | 11/2/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 27.0 | No | No | |
| TotalHg-ST10-11/2/06 | 06BR1767-05 | North Side Sidewalk Bridge | 11/2/06 | 0.59 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 25.0 | No | No | |
| TotalHg-ST11-11/2/06 | 06BR1767-06 | 90 Trinity Place (roof level) | 11/2/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 26.0 | No | No | |
| TotalHg-ST12-11/2/06 | 06BR1767-07 | 110 Greenwich Street (roof level) | 11/2/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 27.0 | No | No | |
| TotalHg-ST13-11/2/06 | 06BR1767-08 | Marriott Hotel, 38th Floor (roof level) | 11/2/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 26.0 | No | No | |
| TotalHg-ST14-11/2/06 | 06BR1767-09 | West Face - South end at corner (scaffolding level) | 11/2/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 26.0 | No | No | |
| TotalHg-ST15-11/2/06 | 06BR1767-10 | South Face - East end at corner (scaffolding level) | 11/2/06 | 0.61 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 25.0 | No | No | |
| TotalHg-ST16-11/2/06 | 06BR1767-11 | East Face - North end at corner (scaffolding level) | 11/2/06 | 0.55 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 27.0 | No | No | |
| TotalHg-ST17-11/2/06 | 06BR1767-12 | North Face - West end at corner (scaffolding level) | 11/2/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 11/4/06 | < 26.0 | No | No | |