

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-11/14/05	05BR1735-1	Southwest Area (street-level)	11/14/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST2-11/14/05	05BR1735-2	Southeast Area (sidewalk bridge level)	11/14/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST4-11/14/05	05BR1735-3	Northwest Area (street-level)	11/14/05	0.58	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST5-11/14/05	05BR1735-4	Firehouse #10 (roof level)	11/14/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST10-11/14/05	05BR1735-5	North Side Sidewalk Bridge	11/14/05	0.58	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST11-11/14/05	05BR1735-6	90 Trinity Place (roof level)	11/14/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST12-11/14/05	05BR1735-7	110 Greenwich Street (roof level)	11/14/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST13-11/14/05	05BR1735-8	Marriott Hotel, 38th Floor (roof level)	11/14/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST1-11/15/05	05BR1736-1	Southwest Area (street-level)	11/15/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST2-11/15/05	05BR1736-2	Southeast Area (sidewalk bridge level)	11/15/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST4-11/15/05	05BR1736-3	Northwest Area (street-level)	11/15/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST5-11/15/05	05BR1736-4	Firehouse #10 (roof level)	11/15/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST10-11/15/05	05BR1736-5	North Side Sidewalk Bridge	11/15/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST11-11/15/05	05BR1736-6	90 Trinity Place (roof level)	11/15/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST12-11/15/05	05BR1736-7	110 Greenwich Street (roof level)	11/15/05	0.57	Mercury	EPA 324/1631	BRL	11/17/05	< 26.0	No	No	
TotalHg-ST13-11/15/05	05BR1736-8	Marriott Hotel, 38th Floor (roof level)	11/15/05	0.53	Mercury	EPA 324/1631	BRL	11/17/05	< 28.0	No	No	
TotalHg-ST1-11/16/05	05BR1754-1	Southwest Area (street-level)	11/16/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST2-11/16/05	05BR1754-2	Southeast Area (sidewalk bridge level)	11/16/05	0.58	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST4-11/16/05	05BR1754-3	Northwest Area (street-level)	11/16/05	0.58	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST5-11/16/05	05BR1754-4	Firehouse #10 (roof level)	11/16/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST10-11/16/05	05BR1754-5	North Side Sidewalk Bridge	11/16/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST11-11/16/05	05BR1754-6	90 Trinity Place (roof level)	11/16/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST12-11/16/05	05BR1754-7	110 Greenwich Street (roof level)	11/16/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST13-11/16/05	05BR1754-8	Marriott Hotel, 38th Floor (roof level)	11/16/05	0.52	Mercury	EPA 324/1631	BRL	11/19/05	< 29.0	No	No	
TotalHg-ST1-11/17/05	05BR1755-1	Southwest Area (street-level)	11/17/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	Mercury samples at Station 5 and 11 not available for analyses on account of pump failure.
TotalHg-ST2-11/17/05	05BR1755-2	Southeast Area (sidewalk bridge level)	11/17/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST4-11/17/05	05BR1755-3	Northwest Area (street-level)	11/17/05	0.56	Mercury	EPA 324/1631	BRL	11/19/05	< 27.0	No	No	
TotalHg-ST10-11/17/05	05BR1755-5	North Side Sidewalk Bridge	11/17/05	0.58	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST100-11/17/05	05BR1755-9	Station 10 Field Duplicate	11/17/05	0.58	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST12-11/17/05	05BR1755-7	110 Greenwich Street (roof level)	11/17/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	
TotalHg-ST13-11/17/05	05BR1755-8	Marriott Hotel, 38th Floor (roof level)	11/17/05	0.57	Mercury	EPA 324/1631	BRL	11/19/05	< 26.0	No	No	