

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-12/13/06	06BR1965-01	Southwest Area (sidewalk bridge level)	12/13/06	0.57	Mercury	EPA 324/1631	BRL	12/15/06	< 26.0	No	No	
TotalHg-ST2-12/13/06	06BR1965-02	Southeast Area (sidewalk bridge level)	12/13/06	0.57	Mercury	EPA 324/1631	BRL	12/15/06	< 26.0	No	No	
TotalHg-ST4-12/13/06	06BR1965-03	Northwest Area (street-level)	12/13/06	0.54	Mercury	EPA 324/1631	BRL	12/15/06	< 28.0	No	No	
TotalHg-ST5-12/13/06	06BR1965-04	Firehouse #10 (roof level)	12/13/06	0.61	Mercury	EPA 324/1631	BRL	12/15/06	< 25.0	No	No	
TotalHg-ST10-12/13/06	06BR1965-05	North Side Sidewalk Bridge	12/13/06	0.61	Mercury	EPA 324/1631	BRL	12/15/06	< 25.0	No	No	
TotalHg-ST11-12/13/06	06BR1965-06	90 Trinity Place (roof level)	12/13/06	0.56	Mercury	EPA 324/1631	BRL	12/15/06	< 27.0	No	No	
TotalHg-ST12-12/13/06	06BR1965-07	110 Greenwich Street (roof level)	12/13/06	0.56	Mercury	EPA 324/1631	BRL	12/15/06	< 27.0	No	No	
TotalHg-ST13-12/13/06	06BR1965-08	Marriott Hotel, 38th Floor (roof level)	12/13/06	0.57	Mercury	EPA 324/1631	BRL	12/15/06	< 26.0	No	No	
TotalHg-ST14-12/13/06	06BR1965-09	West Face - South end at corner (scaffolding level)	12/13/06	0.59	Mercury	EPA 324/1631	BRL	12/15/06	< 25.0	No	No	
TotalHg-ST15-12/13/06	06BR1965-10	South Face - East end at corner (scaffolding level)	12/13/06	0.57	Mercury	EPA 324/1631	BRL	12/15/06	< 26.0	No	No	
TotalHg-ST16-12/13/06	06BR1965-11	East Face - North end at corner (scaffolding level)	12/13/06	0.57	Mercury	EPA 324/1631	BRL	12/15/06	< 26.0	No	No	
TotalHg-ST17-12/13/06	06BR1965-12	North Face - West end at corner (scaffolding level)	12/13/06	0.58	Mercury	EPA 324/1631	BRL	12/15/06	< 26.0	No	No	
TotalHg-ST1-12/14/06	06BR1966-01	Southwest Area (sidewalk bridge level)	12/14/06	0.57	Mercury	EPA 324/1631	BRL	12/16/06	< 26.0	No	No	
TotalHg-ST2-12/14/06	06BR1966-02	Southeast Area (sidewalk bridge level)	12/14/06	0.57	Mercury	EPA 324/1631	BRL	12/16/06	< 26.0	No	No	
TotalHg-ST4-12/14/06	06BR1966-03	Northwest Area (street-level)	12/14/06	0.58	Mercury	EPA 324/1631	BRL	12/16/06	< 26.0	No	No	
TotalHg-ST5-12/14/06	06BR1966-04	Firehouse #10 (roof level)	12/14/06	0.55	Mercury	EPA 324/1631	BRL	12/16/06	< 27.0	No	No	
TotalHg-ST10-12/14/06	06BR1966-05	North Side Sidewalk Bridge	12/14/06	0.57	Mercury	EPA 324/1631	BRL	12/16/06	< 26.0	No	No	
TotalHg-ST11-12/14/06	06BR1966-06	90 Trinity Place (roof level)	12/14/06	0.59	Mercury	EPA 324/1631	BRL	12/16/06	< 25.0	No	No	
TotalHg-ST12-12/14/06	06BR1966-07	110 Greenwich Street (roof level)	12/14/06	0.60	Mercury	EPA 324/1631	BRL	12/16/06	< 25.0	No	No	
TotalHg-ST13-12/14/06	06BR1966-08	Marriott Hotel, 38th Floor (roof level)	12/14/06	0.58	Mercury	EPA 324/1631	BRL	12/16/06	< 26.0	No	No	
TotalHg-ST14-12/14/06	06BR1966-09	West Face - South end at corner (scaffolding level)	12/14/06	0.62	Mercury	EPA 324/1631	BRL	12/16/06	< 24.0	No	No	
TotalHg-ST15-12/14/06	06BR1966-10	South Face - East end at corner (scaffolding level)	12/14/06	0.59	Mercury	EPA 324/1631	BRL	12/16/06	< 25.0	No	No	
TotalHg-ST16-12/14/06	06BR1966-11	East Face - North end at corner (scaffolding level)	12/14/06	0.59	Mercury	EPA 324/1631	BRL	12/16/06	< 25.0	No	No	
TotalHg-ST17-12/14/06	06BR1966-12	North Face - West end at corner (scaffolding level)	12/14/06	0.62	Mercury	EPA 324/1631	BRL	12/16/06	< 24.0	No	No	