

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-12/15/08	0851014-01	Southwest Area (sidewalk bridge level)	12/15/2008	0.56	Mercury	EPA 324/1631	BRL	12/17/2008	< 27.0	No	No	
TotalHg-ST2-12/15/08	0851014-02	Southeast Area (sidewalk bridge level)	12/15/2008	0.59	Mercury	EPA 324/1631	BRL	12/17/2008	< 25.0	No	No	
TotalHg-ST4-12/15/08	0851014-03	Northwest Area (street-level)	12/15/2008	0.58	Mercury	EPA 324/1631	BRL	12/17/2008	< 26.0	No	No	
TotalHg-ST5-12/15/08	0851014-04	Firehouse #10 (roof level)	12/15/2008	0.57	Mercury	EPA 324/1631	BRL	12/17/2008	< 26.0	No	No	
TotalHg-ST10-12/15/08	0851014-05	North Side Sidewalk Bridge	12/15/2008	0.59	Mercury	EPA 324/1631	BRL	12/17/2008	< 25.0	No	No	
TotalHg-ST11-12/15/08	0851014-06	90 Trinity Place (roof level)	12/15/2008	0.55	Mercury	EPA 324/1631	BRL	12/17/2008	< 27.0	No	No	
TotalHg-ST12-12/15/08	0851014-07	110 Greenwich Street (roof level)	12/15/2008	0.54	Mercury	EPA 324/1631	BRL	12/17/2008	< 28.0	No	No	
TotalHg-ST13-12/15/08	0851014-08	Marriott Hotel, 38th Floor (roof level)	12/15/2008	0.58	Mercury	EPA 324/1631	BRL	12/17/2008	< 26.0	No	No	
TotalHg-ST14-12/15/08	0851014-09	West Face - South end at corner (scaffolding level)	12/15/2008	0.59	Mercury	EPA 324/1631	BRL	12/17/2008	< 25.0	No	No	
TotalHg-ST15-12/15/08	0851014-10	South Face - East end at corner (scaffolding level)	12/15/2008	0.55	Mercury	EPA 324/1631	BRL	12/17/2008	< 27.0	No	No	
TotalHg-ST16-12/15/08	0851014-11	East Face - North end at corner (scaffolding level)	12/15/2008	0.56	Mercury	EPA 324/1631	BRL	12/17/2008	< 27.0	No	No	
TotalHg-ST17-12/15/08	0851014-12	North Face - West end at corner (scaffolding level)	12/15/2008	0.62	Mercury	EPA 324/1631	BRL	12/17/2008	< 24.0	No	No	
TotalHg-ST1-12/16/08	0851022-01	Southwest Area (sidewalk bridge level)	12/16/2008	0.59	Mercury	EPA 324/1631	BRL	12/18/2008	< 25.0	No	No	
TotalHg-ST2-12/16/08	0851022-02	Southeast Area (sidewalk bridge level)	12/16/2008	0.58	Mercury	EPA 324/1631	BRL	12/18/2008	< 26.0	No	No	
TotalHg-ST4-12/16/08	0851022-03	Northwest Area (street-level)	12/16/2008	0.58	Mercury	EPA 324/1631	BRL	12/18/2008	< 26.0	No	No	
TotalHg-ST5-12/16/08	0851022-04	Firehouse #10 (roof level)	12/16/2008	0.54	Mercury	EPA 324/1631	BRL	12/18/2008	< 28.0	No	No	
TotalHg-ST10-12/16/08	0851022-05	North Side Sidewalk Bridge	12/16/2008	0.59	Mercury	EPA 324/1631	BRL	12/18/2008	< 25.0	No	No	
TotalHg-ST11-12/16/08	0851022-06	90 Trinity Place (roof level)	12/16/2008	0.59	Mercury	EPA 324/1631	BRL	12/18/2008	< 25.0	No	No	
TotalHg-ST12-12/16/08	0851022-07	110 Greenwich Street (roof level)	12/16/2008	0.57	Mercury	EPA 324/1631	BRL	12/18/2008	< 26.0	No	No	
TotalHg-ST13-12/16/08	0851022-08	Marriott Hotel, 38th Floor (roof level)	12/16/2008	0.55	Mercury	EPA 324/1631	BRL	12/18/2008	< 27.0	No	No	
TotalHg-ST14-12/16/08	0851022-09	West Face - South end at corner (scaffolding level)	12/16/2008	0.59	Mercury	EPA 324/1631	BRL	12/18/2008	< 25.0	No	No	
TotalHg-ST15-12/16/08	0851022-10	South Face - East end at corner (scaffolding level)	12/16/2008	0.55	Mercury	EPA 324/1631	BRL	12/18/2008	< 27.0	No	No	
TotalHg-ST16-12/16/08	0851022-11	East Face - North end at corner (scaffolding level)	12/16/2008	0.55	Mercury	EPA 324/1631	BRL	12/18/2008	< 27.0	No	No	
TotalHg-ST17-12/16/08	0851022-12	North Face - West end at corner (scaffolding level)	12/16/2008	0.56	Mercury	EPA 324/1631	BRL	12/18/2008	< 27.0	No	No	
TotalHg-ST1-12/17/08	0851029-01	Southwest Area (sidewalk bridge level)	12/17/2008	0.55	Mercury	EPA 324/1631	BRL	12/19/2008	< 27.0	No	No	
TotalHg-ST2-12/17/08	0851029-02	Southeast Area (sidewalk bridge level)	12/17/2008	0.53	Mercury	EPA 324/1631	BRL	12/19/2008	< 28.0	No	No	
TotalHg-ST4-12/17/08	0851029-03	Northwest Area (street-level)	12/17/2008	0.56	Mercury	EPA 324/1631	BRL	12/19/2008	< 27.0	No	No	
TotalHg-ST5-12/17/08	0851029-04	Firehouse #10 (roof level)	12/17/2008	0.59	Mercury	EPA 324/1631	BRL	12/19/2008	< 25.0	No	No	
TotalHg-ST10-12/17/08	0851029-05	North Side Sidewalk Bridge	12/17/2008	0.57	Mercury	EPA 324/1631	BRL	12/19/2008	< 26.0	No	No	
TotalHg-ST100-12/17/08 FD	0851029-13	Station 10 Field Duplicate	12/17/2008	0.56	Mercury	EPA 324/1631	BRL	12/19/2008	< 27.0	No	No	
TotalHg-ST11-12/17/08	0851029-06	90 Trinity Place (roof level)	12/17/2008	0.55	Mercury	EPA 324/1631	BRL	12/19/2008	< 27.0	No	No	
TotalHg-ST12-12/17/08	0851029-07	110 Greenwich Street (roof level)	12/17/2008	0.57	Mercury	EPA 324/1631	BRL	12/19/2008	< 26.0	No	No	
TotalHg-ST13-12/17/08	0851029-08	Marriott Hotel, 38th Floor (roof level)	12/17/2008	0.54	Mercury	EPA 324/1631	BRL	12/19/2008	< 28.0	No	No	
TotalHg-ST14-12/17/08	0851029-09	West Face - South end at corner (scaffolding level)	12/17/2008	0.56	Mercury	EPA 324/1631	BRL	12/19/2008	< 27.0	No	No	
TotalHg-ST15-12/17/08	0851029-10	South Face - East end at corner (scaffolding level)	12/17/2008	0.60	Mercury	EPA 324/1631	BRL	12/19/2008	< 25.0	No	No	
TotalHg-ST16-12/17/08	0851029-11	East Face - North end at corner (scaffolding level)	12/17/2008	0.54	Mercury	EPA 324/1631	BRL	12/19/2008	< 28.0	No	No	
TotalHg-ST17-12/17/08	0851029-12	North Face - West end at corner (scaffolding level)	12/17/2008	0.55	Mercury	EPA 324/1631	BRL	12/19/2008	< 27.0	No	No	