

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
									300	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-12/29/07	0801003-01	Southwest Area (sidewalk bridge level)	12/29/07	0.58	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST2-12/29/07	0801003-02	Southeast Area (sidewalk bridge level)	12/29/07	0.57	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST4-12/29/07	0801003-03	Northwest Area (street-level)	12/29/07	0.56	Mercury	EPA 324/1631	BRL	1/2/08	< 27.0	No	No	
TotalHg-ST5-12/29/07	0801003-04	Firehouse #10 (roof level)	12/29/07	0.56	Mercury	EPA 324/1631	BRL	1/2/08	< 27.0	No	No	
TotalHg-ST10-12/29/07	0801003-05	North Side Sidewalk Bridge	12/29/07	0.58	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST11-12/29/07	0801003-06	90 Trinity Place (roof level)	12/29/07	0.60	Mercury	EPA 324/1631	BRL	1/2/08	< 25.0	No	No	
TotalHg-ST12-12/29/07	0801003-07	110 Greenwich Street (roof level)	12/29/07	0.56	Mercury	EPA 324/1631	BRL	1/2/08	< 27.0	No	No	
TotalHg-ST13-12/29/07	0801003-08	Marriott Hotel, 38th Floor (roof level)	12/29/07	0.60	Mercury	EPA 324/1631	BRL	1/2/08	< 25.0	No	No	
TotalHg-ST14-12/29/07	0801003-09	West Face - South end at corner (scaffolding level)	12/29/07	0.55	Mercury	EPA 324/1631	BRL	1/2/08	< 27.0	No	No	
TotalHg-ST15-12/29/07	0801003-10	South Face - East end at corner (scaffolding level)	12/29/07	0.57	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST16-12/29/07	0801003-11	East Face - North end at corner (scaffolding level)	12/29/07	0.60	Mercury	EPA 324/1631	BRL	1/2/08	< 25.0	No	No	
TotalHg-ST17-12/29/07	0801003-12	North Face - West end at corner (scaffolding level)	12/29/07	0.56	Mercury	EPA 324/1631	BRL	1/2/08	< 27.0	No	No	
TotalHg-ST1-12/30/07	0801004-01	Southwest Area (sidewalk bridge level)	12/30/07	0.58	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST2-12/30/07	0801004-02	Southeast Area (sidewalk bridge level)	12/30/07	0.58	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST4-12/30/07	0801004-03	Northwest Area (street-level)	12/30/07	0.54	Mercury	EPA 324/1631	BRL	1/2/08	< 28.0	No	No	
TotalHg-ST5-12/30/07	0801004-04	Firehouse #10 (roof level)	12/30/07	0.55	Mercury	EPA 324/1631	BRL	1/2/08	< 27.0	No	No	
TotalHg-ST10-12/30/07	0801004-05	North Side Sidewalk Bridge	12/30/07	0.57	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST11-12/30/07	0801004-06	90 Trinity Place (roof level)	12/30/07	0.54	Mercury	EPA 324/1631	BRL	1/2/08	< 28.0	No	No	
TotalHg-ST12-12/30/07	0801004-07	110 Greenwich Street (roof level)	12/30/07	0.60	Mercury	EPA 324/1631	BRL	1/2/08	< 25.0	No	No	
TotalHg-ST13-12/30/07	0801004-08	Marriott Hotel, 38th Floor (roof level)	12/30/07	0.56	Mercury	EPA 324/1631	BRL	1/2/08	< 27.0	No	No	
TotalHg-ST14-12/30/07	0801004-09	West Face - South end at corner (scaffolding level)	12/30/07	0.58	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST15-12/30/07	0801004-10	South Face - East end at corner (scaffolding level)	12/30/07	0.58	Mercury	EPA 324/1631	BRL	1/2/08	< 26.0	No	No	
TotalHg-ST16-12/30/07	0801004-11	East Face - North end at corner (scaffolding level)	12/30/07	0.55	Mercury	EPA 324/1631	BRL	1/2/08	< 27.0	No	No	
TotalHg-ST17-12/30/07	0801004-12	North Face - West end at corner (scaffolding level)	12/30/07	0.59	Mercury	EPA 324/1631	BRL	1/2/08	< 25.0	No	No	
TotalHg-ST1-12/31/07	0801006-01	Southwest Area (sidewalk bridge level)	12/31/07	0.58	Mercury	EPA 324/1631	BRL	1/3/08	< 26.0	No	No	
TotalHg-ST2-12/31/07	0801006-02	Southeast Area (sidewalk bridge level)	12/31/07	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST4-12/31/07	0801006-03	Northwest Area (street-level)	12/31/07	0.57	Mercury	EPA 324/1631	BRL	1/3/08	< 26.0	No	No	
TotalHg-ST5-12/31/07	0801006-04	Firehouse #10 (roof level)	12/31/07	0.59	Mercury	EPA 324/1631	BRL	1/3/08	< 25.0	No	No	
TotalHg-ST10-12/31/07	0801006-05	North Side Sidewalk Bridge	12/31/07	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST11-12/31/07	0801006-06	90 Trinity Place (roof level)	12/31/07	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST12-12/31/07	0801006-07	110 Greenwich Street (roof level)	12/31/07	0.53	Mercury	EPA 324/1631	BRL	1/3/08	< 28.0	No	No	
TotalHg-ST13-12/31/07	0801006-08	Marriott Hotel, 38th Floor (roof level)	12/31/07	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST14-12/31/07	0801006-09	West Face - South end at corner (scaffolding level)	12/31/07	0.58	Mercury	EPA 324/1631	BRL	1/3/08	< 26.0	No	No	
TotalHg-ST15-12/31/07	0801006-10	South Face - East end at corner (scaffolding level)	12/31/07	0.59	Mercury	EPA 324/1631	BRL	1/3/08	< 25.0	No	No	
TotalHg-ST16-12/31/07	0801006-11	East Face - North end at corner (scaffolding level)	12/31/07	0.57	Mercury	EPA 324/1631	BRL	1/3/08	< 26.0	No	No	
TotalHg-ST17-12/31/07	0801006-12	North Face - West end at corner (scaffolding level)	12/31/07	0.57	Mercury	EPA 324/1631	BRL	1/3/08	< 26.0	No	No	
TotalHg-ST1-1/1/08	0801007-01	Southwest Area (sidewalk bridge level)	1/1/08	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST2-1/1/08	0801007-02	Southeast Area (sidewalk bridge level)	1/1/08	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST4-1/1/08	0801007-03	Northwest Area (street-level)	1/1/08	0.53	Mercury	EPA 324/1631	BRL	1/3/08	< 28.0	No	No	
TotalHg-ST5-1/1/08	0801007-04	Firehouse #10 (roof level)	1/1/08	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST10-1/1/08	0801007-05	North Side Sidewalk Bridge	1/1/08	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST11-1/1/08	0801007-06	90 Trinity Place (roof level)	1/1/08	0.55	Mercury	EPA 324/1631	BRL	1/3/08	< 27.0	No	No	
TotalHg-ST12-1/1/08	0801007-07	110 Greenwich Street (roof level)	1/1/08	0.60	Mercury	EPA 324/1631	BRL	1/3/08	< 25.0	No	No	
TotalHg-ST13-1/1/08	0801007-08	Marriott Hotel, 38th Floor (roof level)	1/1/08	0.58	Mercury	EPA 324/1631	BRL	1/3/08	< 26.0	No	No	
TotalHg-ST14-1/1/08	0801007-09	West Face - South end at corner (scaffolding level)	1/1/08	0.63	Mercury	EPA 324/1631	BRL	1/3/08	< 24.0	No	No	
TotalHg-ST15-1/1/08	0801007-10	South Face - East end at corner (scaffolding level)	1/1/08	0.61	Mercury	EPA 324/1631	BRL	1/3/08	< 25.0	No	No	
TotalHg-ST16-1/1/08	0801007-11	East Face - North end at corner (scaffolding level)	1/1/08	0.59	Mercury	EPA 324/1631	BRL	1/3/08	< 25.0	No	No	
TotalHg-ST17-1/1/08	0801007-12	North Face - West end at corner (scaffolding level)	1/1/08	0.60	Mercury	EPA 324/1631	BRL	1/3/08	< 25.0	No	No	