

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments	
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000				
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments	
									Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels
METALS-ST1-2/20/06	G6B220237001	Southwest Area (sidewalk bridge level)	2/20/06	1705.26	Metals	6020	STL-SAC	2/22/06	5.2	< 70.4	< 0.70	< 0.70	< 7.0	391	32.7	32.4	14.8	87.5	No	No		
METALS-ST2-2/20/06	G6B220237002	Southeast Area (sidewalk bridge level)	2/20/06	1702.23	Metals	6020	STL-SAC	2/22/06	5.6	< 70.5	< 0.70	< 0.70	< 7.0	193	24.6	26.2	16.0	87.5	No	No		
METALS-ST4-2/20/06	G6B220237003	Northwest Area (street-level)	2/20/06	1758.2	Metals	6020	STL-SAC	2/22/06	4.6	< 68.2	< 0.68	< 0.68	< 6.8	528	90.4	27.6	16.0	124	No	No		
METALS-ST5-2/20/06	G6B220237004	Firehouse #10 (roof level)	2/20/06	1753.99	Metals	6020	STL-SAC	2/22/06	4.5	< 68.4	< 0.68	< 0.68	< 6.8	345	16.4	27.1	15.6	54.2	No	No		
METALS-ST10-2/20/06	G6B220237005	North Side Sidewalk Bridge	2/20/06	1752.04	Metals	6020	STL-SAC	2/22/06	4.6	< 68.5	< 0.68	< 0.68	< 6.8	50.6	24.7	16.3	58.1	No	No			
METALS-ST11-2/20/06	G6B220237006	90 Trinity Place (roof level)	2/20/06	1787.85	Metals	6020	STL-SAC	2/22/06	4.4	< 67.1	< 0.67	< 0.67	< 6.7	65.7	13.5	21.5	14.7	52.3	No	No		
METALS-ST12-2/20/06	G6B220237007	110 Greenwich Street (roof level)	2/20/06	1672.54	Metals	6020	STL-SAC	2/22/06	4.6	< 71.7	< 0.72	< 0.72	< 7.2	72.5	13.5	22.7	17.4	53.1	No	No		
METALS-ST13-2/20/06	G6B220237008	Mariotti Hotel, 38th Floor (roof level)	2/20/06	1698.09	Metals	6020	STL-SAC	2/22/06	4.6	< 70.7	< 0.71	< 0.71	< 7.1	69.3	12.0	20.6	17.4	49.3	No	No		
METALS-ST14-2/20/06	G6B220237009	West Face - South end at corner (scaffolding level)	2/20/06	1838.37	Metals	6020	STL-SAC	2/22/06	4.1	< 65.3	< 0.65	< 0.65	< 6.5	24.6	18.5	11.4	13.6	42.0	No	No		
METALS-ST15-2/20/06	G6B220237010	South Face - East end at corner (scaffolding level)	2/20/06	1822.65	Metals	6020	STL-SAC	2/22/06	3.6	< 65.6	< 0.66	< 0.66	< 6.6	43.0	10.4	16.9	12.8	40.0	No	No		
METALS-ST16-2/20/06	G6B220237011	East Face - North end at corner (scaffolding level)	2/20/06	1814.55	Metals	6020	STL-SAC	2/22/06	3.7	< 66.1	< 0.66	< 0.66	< 6.6	92.0	13.2	21.9	14.3	48.0	No	No		
METALS-ST17-2/20/06	G6B220237012	North Face - West end at corner (scaffolding level)	2/20/06	1828.51	Metals	6020	STL-SAC	2/22/06	3.8	< 65.6	< 0.66	< 0.66	< 6.6	66.5	12.3	20.6	14.0	44.9	No	No		
METALS-ST1-2/21/06	G6B230204001	Southwest Area (sidewalk bridge level)	2/21/06	1649.32	Metals	6020	STL-SAC	2/23/06	2.6	< 72.8	< 0.73	< 0.73	< 7.3	359	65.3	37.3	9.3	104	No	No		
METALS-ST2-2/21/06	G6B230204002	Southeast Area (sidewalk bridge level)	2/21/06	1636.79	Metals	6020	STL-SAC	2/23/06	2.7	< 73.3	< 0.73	< 0.73	< 7.3	304	34.9	37.6	8.9	103	No	No		
METALS-ST4-2/21/06	G6B230204003	Northwest Area (street-level)	2/21/06	1578.63	Metals	6020	STL-SAC	2/23/06	2.0	< 76.0	< 0.76	< 0.76	< 7.6	479	112	20.7	6.8	95.3	No	No		
METALS-ST5-2/21/06	G6B230204004	Firehouse #10 (roof level)	2/21/06	1811.26	Metals	6020	STL-SAC	2/23/06	2.1	< 66.2	< 0.66	< 0.66	< 6.6	411	26.4	36.1	7.9	64.1	No	No		
METALS-ST10-2/21/06	G6B230204005	North Side Sidewalk Bridge	2/21/06	1591	Metals	6020	STL-SAC	2/23/06	1.9	< 75.4	< 0.75	< 0.75	< 7.5	56.3	28.3	24.1	6.5	58.1	No	No		
METALS-ST11-2/21/06	G6B230204006	90 Trinity Place (roof level)	2/21/06	1811.2	Metals	6020	STL-SAC	2/23/06	1.7	< 66.2	< 0.66	< 0.66	< 6.6	53.0	14.8	20.4	8.1	49.6	No	No		
METALS-ST12-2/21/06	G6B230204007	110 Greenwich Street (roof level)	2/21/06	1657.08	Metals	6020	STL-SAC	2/23/06	2.2	< 72.4	< 0.72	< 0.72	< 7.2	81.4	17.5	23.3	9.0	59.9	No	No		
METALS-ST13-2/21/06	G6B230204008	Mariotti Hotel, 38th Floor (roof level)	2/21/06	1591.64	Metals	6020	STL-SAC	2/23/06	< 1.5	< 75.4	< 0.75	< 0.75	< 7.5	46.3	8.9	14.5	7.5	31.7	No	No		
METALS-ST14-2/21/06	G6B230204009	West Face - South end at corner (scaffolding level)	2/21/06	1813.63	Metals	6020	STL-SAC	2/23/06	< 1.3	< 66.2	< 0.66	< 0.66	< 6.6	38.6	9.0	11.6	5.6	34.4	No	No		
METALS-ST15-2/21/06	G6B230204010	South Face - East end at corner (scaffolding level)	2/21/06	1793.42	Metals	6020	STL-SAC	2/23/06	< 1.3	< 66.9	< 0.67	< 0.67	< 6.7	55.0	9.3	12.5	7.0	36.5	No	No		
METALS-ST16-2/21/06	G6B230204011	East Face - North end at corner (scaffolding level)	2/21/06	1799.91	Metals	6020	STL-SAC	2/23/06	1.7	< 66.7	< 0.67	< 0.67	< 6.7	81.9	16.0	20.2	8.0	51.1	No	No		
METALS-ST17-2/21/06	G6B230204012	North Face - West end at corner (scaffolding level)	2/21/06	1809.14	Metals	6020	STL-SAC	2/23/06	1.5	< 66.3	< 0.66	< 0.66	< 6.6	53.1	13.8	16.8	6.8	46.6	No	No		