

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m3)	Barium Concentration (ng/m3)	Beryllium Concentration (ng/m3)	Cadmium Concentration (ng/m3)	Chromium (Total) Concentration (ng/m3)	Copper Concentration (ng/m3)	Lead Concentration (ng/m3)	Manganese Concentration (ng/m3)	Nickel Concentration (ng/m3)	Zinc Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments	
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000				
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments	
									Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels
METALS-ST11-5/30/09	G9F020148001	Southwest Area (sidewalk bridge level)	5/30/09	1735.3	Metals	6020	STL-SAC	6/2/09	3.3	< 69.2	< 0.69	< 0.69	< 6.9	111	8.9	20.0	5.7	79.7	No	No		
METALS-ST2-5/30/09	G9F020148002	Southwest Area (sidewalk bridge level)	5/30/09	1752.6	Metals	6020	STL-SAC	6/2/09	3.1	< 68.5	< 0.68	< 0.68	< 6.8	79.1	9.4	29.3	6.6	76.1	No	No		
METALS-ST4-5/30/09	G9F020148003	Northwest Area (street-level)	5/30/09	1745.7	Metals	6020	STL-SAC	6/2/09	3.9	< 68.7	< 0.69	< 0.69	< 6.9	134	16.4	23.4	6.5	574	No	No		
METALS-ST5-5/30/09	G9F020148004	Firehouse #10 (roof level)	5/30/09	1741.2	Metals	6020	STL-SAC	6/2/09	2.8	136	< 0.69	< 0.69	< 6.9	108	6.8	34.3	8.1	73.3	No	No		
METALS-ST10-5/30/09	G9F020148005	North Side Sidewalk Bridge	5/30/09	1764.9	Metals	6020	STL-SAC	6/2/09	2.7	166	< 0.68	< 0.68	< 6.8	60.8	6.1	28.4	7.4	78.1	No	No		
METALS-ST11-5/30/09	G9F020148006	90 Trinity Place (roof level)	5/30/09	1759.4	Metals	6020	STL-SAC	6/2/09	2.2	< 68.2	< 0.68	< 0.68	< 6.8	68.8	5.5	14.6	5.2	36.9	No	No		
METALS-ST12-5/30/09	G9F020148007	110 Greenwich Street (roof level)	5/30/09	1783.4	Metals	6020	STL-SAC	6/2/09	2.3	< 67.3	< 0.67	< 0.67	< 6.7	46.9	5.2	13.0	4.9	34.9	No	No		
METALS-ST13-5/30/09	G9F020148008	Marriott Hotel, 38th Floor (roof level)	5/30/09	1732.7	Metals	6020	STL-SAC	6/2/09	1.9	< 69.2	< 0.69	< 0.69	< 6.9	76.0	4.0	10.6	5.2	21.1	No	No		
METALS-ST14-5/30/09	G9F020148009	West Face - South end at corner (scaffolding level)	5/30/09	1705	Metals	6020	STL-SAC	6/2/09	2.3	< 70.4	< 0.70	< 0.70	< 7.0	68.4	5.0	13.0	5.9	33.4	No	No		
METALS-ST15-5/30/09	G9F020148010	South Face - East end at corner (scaffolding level)	5/30/09	1706.5	Metals	6020	STL-SAC	6/2/09	2.3	< 70.3	< 0.70	< 0.70	< 7.0	66.7	5.0	14.2	5.7	37.3	No	No		
METALS-ST16-5/30/09	G9F020148011	East Face - North end at corner (scaffolding level)	5/30/09	1708.3	Metals	6020	STL-SAC	6/2/09	2.2	< 70.2	< 0.70	< 0.70	< 7.0	473	4.8	18.4	5.7	45.3	No	No		
METALS-ST17-5/30/09	G9F020148012	North Face - West end at corner (scaffolding level)	5/30/09	1695.4	Metals	6020	STL-SAC	6/2/09	2.1	< 70.8	< 0.71	< 0.71	< 7.1	69.3	4.6	12.9	5.5	38.7	No	No		
METALS-ST1-5/31/09	G9F020153001	Southwest Area (sidewalk bridge level)	5/31/09	1808.6	Metals	6020	STL-SAC	6/2/09	2.3	< 66.3	< 0.66	< 0.66	< 6.6	142	14.8	26.4	4.6	118	No	No		
METALS-ST2-5/31/09	G9F020153002	Southeast Area (sidewalk bridge level)	5/31/09	1860.1	Metals	6020	STL-SAC	6/2/09	2.9	< 64.5	< 0.64	< 0.64	< 6.4	71.1	14.8	43.9	5.7	109	No	No		
METALS-ST4-5/31/09	G9F020153003	Northwest Area (street-level)	5/31/09	1776.1	Metals	6020	STL-SAC	6/2/09	2.1	< 67.6	< 0.68	< 0.68	< 6.8	114	20.4	30.6	4.5	190	No	No		
METALS-ST5-5/31/09	G9F020153004	Firehouse #10 (roof level)	5/31/09	1760.1	Metals	6020	STL-SAC	6/2/09	2.5	87.9	< 0.68	< 0.68	< 6.8	79.9	12.1	37.6	5.1	97.0	No	No		
METALS-ST10-5/31/09	G9F020153005	North Side Sidewalk Bridge	5/31/09	1831.8	Metals	6020	STL-SAC	6/2/09	2.0	266	< 0.66	< 0.66	< 6.6	67.3	10.9	50.4	6.9	102	No	No		
METALS-ST11-5/31/09	G9F020153006	90 Trinity Place (roof level)	5/31/09	1771.5	Metals	6020	STL-SAC	6/2/09	2.3	< 67.7	< 0.68	< 0.68	< 6.8	46.8	9.3	16.0	< 3.4	38.8	No	No		
METALS-ST12-5/31/09	G9F020153007	110 Greenwich Street (roof level)	5/31/09	1786.8	Metals	6020	STL-SAC	6/2/09	1.9	< 67.2	< 0.67	< 0.67	< 6.7	29.2	7.8	16.2	< 3.4	41.9	No	No		

- Note:
- As of May 31, 2009, scaffolding stations ceased operation in accordance with Amendment #7, dated February 6, 2008, to the Ambient Air Monitoring Program Plan.
 - The metals sample from Station 13 (Marriott Hotel, 38th Floor [roof level]) was shipped one day later than remaining samples due to error; results will be posted when available.