

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target Air Quality	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-7/3/09	G9G070163001	Southwest Area (sidewalk bridge leve	7/3/09	1828.8	Metals	6020	STL-SAC	7/7/09	2.5	77.3	< 0.66	< 0.66	< 6.6	36.6	9.4	20.1	3.9	56.3	No	No	
METALS-ST12-7/3/09	G9G070163002	Southeast Area (sidewalk bridge leve	7/3/09	1808.2	Metals	6020	STL-SAC	7/7/09	2.8	66.9	< 0.66	< 0.66	< 6.6	59.9	9.8	28.4	4.3	70.5	No	No	
METALS-ST14-7/3/09	G9G070163003	Northwest Area (street-level	7/3/09	1880.4	Metals	6020	STL-SAC	7/7/09	1.9	165	< 0.64	< 0.64	< 6.4	59.1	6.4	34.0	4.4	60.4	No	No	
METALS-ST15-7/3/09	G9G070163004	Firehouse #10 (roof level	7/3/09	1834.2	Metals	6020	STL-SAC	7/7/09	2.0	151	< 0.65	< 0.65	< 6.5	70.1	7.3	26.5	4.1	61.7	No	No	
METALS-ST10-7/3/09	G9G070163005	North Side Sidewalk Bridgr	7/3/09	1847.7	Metals	6020	STL-SAC	7/7/09	1.8	232	< 0.65	< 0.65	< 6.5	31.3	6.2	36.6	5.5	84.4	No	No	
METALS-ST11-7/3/09	G9G070163006	90 Trinity Place (roof level	7/3/09	1810	Metals	6020	STL-SAC	7/7/09	1.8	80.0	< 0.66	< 0.66	< 6.6	54.9	5.2	13.1	< 3.3	35.5	No	No	
METALS-ST12-7/3/09	G9G070163007	110 Greenwich Street (roof level	7/3/09	1817.2	Metals	6020	STL-SAC	7/7/09	1.7	< 66.0	< 0.66	< 0.66	< 6.6	36.4	4.7	7.3	< 3.3	25.6	No	No	
METALS-ST13-7/3/09	G9G070163008	Mariott Hotel, 38th Floor (roof leve	7/3/09	1833.3	Metals	6020	STL-SAC	7/7/09	1.5	< 65.4	< 0.65	< 0.65	< 6.5	84.8	4.8	9.2	< 3.3	27.2	No	No	
METALS-ST11-7/4/09	G9G070162001	Southwest Area (sidewalk bridge leve	7/4/09	1835.6	Metals	6020	STL-SAC	7/7/09	1.5	< 65.4	< 0.65	< 0.65	< 6.5	44.8	7.4	11.5	< 3.3	37.3	No	No	
METALS-ST12-7/4/09	G9G070162002	Southeast Area (sidewalk bridge leve	7/4/09	1815.3	Metals	6020	STL-SAC	7/7/09	2.0	< 66.1	< 0.66	< 0.66	< 6.6	82.4	8.2	20.9	< 3.3	44.4	No	No	
METALS-ST14-7/4/09	G9G070162003	Northwest Area (street-level	7/4/09	1821.7	Metals	6020	STL-SAC	7/7/09	1.3	< 65.9	< 0.66	< 0.66	< 6.6	49.2	5.1	6.6	< 3.3	21.1	No	No	
METALS-ST15-7/4/09	G9G070162004	Firehouse #10 (roof level	7/4/09	1819.6	Metals	6020	STL-SAC	7/7/09	1.5	< 65.9	< 0.66	< 0.66	< 6.6	52.6	5.3	11.4	< 3.3	26.2	No	No	
METALS-ST10-7/4/09	G9G070162005	North Side Sidewalk Bridgr	7/4/09	1848.3	Metals	6020	STL-SAC	7/7/09	1.3	< 64.9	< 0.65	< 0.65	< 6.5	26.9	5.0	8.8	< 3.2	23.8	No	No	
METALS-ST11-7/4/09	G9G070162006	90 Trinity Place (roof level	7/4/09	1807.9	Metals	6020	STL-SAC	7/7/09	1.4	< 66.4	< 0.66	< 0.66	< 6.6	57.7	4.1	5.1	< 3.3	15.1	No	No	
METALS-ST12-7/4/09	G9G070162007	110 Greenwich Street (roof level	7/4/09	1816.1	Metals	6020	STL-SAC	7/7/09	1.4	< 66.1	< 0.66	< 0.66	< 6.6	31.5	4.1	8.1	< 3.3	16.2	No	No	
METALS-ST13-7/4/09	G9G070162008	Mariott Hotel, 38th Floor (roof leve	7/4/09	1828.1	Metals	6020	STL-SAC	7/7/09	< 1.3	< 65.6	< 0.66	< 0.66	< 6.6	71.1	4.0	3.8	< 3.3	22.3	No	No	
METALS-ST11-7/5/09	G9G070164001	Southwest Area (sidewalk bridge leve	7/5/09	1849.9	Metals	6020	STL-SAC	7/7/09	3.8	71.0	< 0.65	< 0.65	< 6.5	58.8	11.4	20.6	5.3	93.2	No	No	
METALS-ST12-7/5/09	G9G070164002	Southeast Area (sidewalk bridge leve	7/5/09	1840.2	Metals	6020	STL-SAC	7/7/09	4.0	83.3	< 0.65	< 0.65	< 6.5	94.7	11.7	34.4	6.8	90.6	No	No	
METALS-ST14-7/5/09	G9G070164003	Northwest Area (street-level	7/5/09	1848.1	Metals	6020	STL-SAC	7/7/09	2.8	< 64.9	< 0.65	< 0.65	< 6.5	62.8	7.5	17.5	4.6	70.3	No	No	
METALS-ST15-7/5/09	G9G070164004	Firehouse #10 (roof level	7/5/09	1817.3	Metals	6020	STL-SAC	7/7/09	2.6	< 66.0	< 0.66	< 0.66	< 6.6	57.4	6.8	14.6	4.6	35.7	No	No	
METALS-ST10-7/5/09	G9G070164005	North Side Sidewalk Bridgr	7/5/09	1854.9	Metals	6020	STL-SAC	7/7/09	2.4	< 64.7	< 0.65	< 0.65	< 6.5	31.8	6.4	34.6	4.6	26.1	No	No	
METALS-ST11-7/5/09	G9G070164006	90 Trinity Place (roof level	7/5/09	1808.1	Metals	6020	STL-SAC	7/7/09	2.4	< 66.4	< 0.66	< 0.66	< 6.6	92.6	6.1	7.6	3.8	28.6	No	No	
METALS-ST12-7/5/09	G9G070164007	110 Greenwich Street (roof level	7/5/09	1823.9	Metals	6020	STL-SAC	7/7/09	2.4	< 65.8	< 0.66	< 0.66	< 6.6	39.1	5.8	8.4	3.8	34.2	No	No	
METALS-ST13-7/5/09	G9G070164008	Mariott Hotel, 38th Floor (roof leve	7/5/09	1812.1	Metals	6020	STL-SAC	7/7/09	2.2	< 66.2	< 0.66	< 0.66	< 6.6	70.9	5.4	7.6	4.0	24.0	No	No	