

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-1/22/07	030702216-0001	Southwest Area (sidewalk bridge level)	1/22/07	1	3.050	Asbestos	PCME	EMSL	1/23/07	< 0.00081	No	No	
ASBESTOS-ST2-1/22/07	030702216-0002	Southeast Area (sidewalk bridge level)	1/22/07	1	3.230	Asbestos	PCME	EMSL	1/23/07	< 0.00076	No	No	
ASBESTOS-ST4-1/22/07	030702216-0003	Northwest Area (street-level)	1/22/07	1	3.140	Asbestos	PCME	EMSL	1/23/07	< 0.00079	No	No	
ASBESTOS-ST5-1/22/07	030702216-0004	Firehouse #10 (roof level)	1/22/07	1	3.020	Asbestos	PCME	EMSL	1/23/07	< 0.00082	No	No	
ASBESTOS-ST10-1/22/07	030702216-0005	North Side Sidewalk Bridge	1/22/07	1	2.980	Asbestos	PCME	EMSL	1/23/07	< 0.00083	No	No	
ASBESTOS-ST11-1/22/07	030702216-0006	90 Trinity Place (roof level)	1/22/07	1	3.020	Asbestos	PCME	EMSL	1/23/07	< 0.00082	No	No	
ASBESTOS-ST12-1/22/07	030702216-0007	110 Greenwich Street (roof level)	1/22/07	1	3.050	Asbestos	PCME	EMSL	1/23/07	< 0.00081	No	No	
ASBESTOS-ST13-1/22/07	030702216-0008	Marriott Hotel, 38th Floor (roof level)	1/22/07	1	3.040	Asbestos	PCME	EMSL	1/23/07	< 0.00081	No	No	
ASBESTOS-ST14-1/22/07	030702216-0009	West Face - South end at corner (scaffolding level)	1/22/07	1	3.030	Asbestos	PCME	EMSL	1/23/07	< 0.00081	No	No	
ASBESTOS-ST15-1/22/07	030702216-0010	South Face - East end at corner (scaffolding level)	1/22/07	1	3.040	Asbestos	PCME	EMSL	1/23/07	< 0.00081	No	No	
ASBESTOS-ST16-1/22/07	030702216-0011	East Face - North end at corner (scaffolding level)	1/22/07	1	3.040	Asbestos	PCME	EMSL	1/23/07	< 0.00081	No	No	
ASBESTOS-ST17-1/22/07	030702216-0012	North Face - West end at corner (scaffolding level)	1/22/07	1	3.040	Asbestos	PCME	EMSL	1/23/07	< 0.00081	No	No	
ASBESTOS-ST1-1/23/07	030702383-0001	Southwest Area (sidewalk bridge level)	1/23/07	1	3.040	Asbestos	PCME	EMSL	1/24/07	< 0.00081	No	No	
ASBESTOS-ST2-1/23/07	030702383-0002	Southeast Area (sidewalk bridge level)	1/23/07	1	3.030	Asbestos	PCME	EMSL	1/24/07	< 0.00081	No	No	
ASBESTOS-ST4-1/23/07	030702383-0003	Northwest Area (street-level)	1/23/07	1	3.020	Asbestos	PCME	EMSL	1/24/07	< 0.00082	No	No	
ASBESTOS-ST5-1/23/07	030702383-0004	Firehouse #10 (roof level)	1/23/07	1	2.890	Asbestos	PCME	EMSL	1/24/07	< 0.00085	No	No	
ASBESTOS-ST10-1/23/07	030702383-0005	North Side Sidewalk Bridge	1/23/07	1	3.120	Asbestos	PCME	EMSL	1/24/07	< 0.00079	No	No	
ASBESTOS-ST100-1/23/07	030702383-0013	Station 10 Field Duplicate	1/23/07	1	3.000	Asbestos	PCME	EMSL	1/24/07	< 0.00082	No	No	
ASBESTOS-ST11-1/23/07	030702383-0006	90 Trinity Place (roof level)	1/23/07	1	3.040	Asbestos	PCME	EMSL	1/24/07	< 0.00081	No	No	
ASBESTOS-ST12-1/23/07	030702383-0007	110 Greenwich Street (roof level)	1/23/07	1	3.030	Asbestos	PCME	EMSL	1/24/07	< 0.00081	No	No	
ASBESTOS-ST13-1/23/07	030702383-0008	Marriott Hotel, 38th Floor (roof level)	1/23/07	1	3.020	Asbestos	PCME	EMSL	1/24/07	< 0.00082	No	No	
ASBESTOS-ST14-1/23/07	030702383-0009	West Face - South end at corner (scaffolding level)	1/23/07	1	3.050	Asbestos	PCME	EMSL	1/24/07	< 0.00081	No	No	
ASBESTOS-ST15-1/23/07	030702383-0010	South Face - East end at corner (scaffolding level)	1/23/07	1	3.110	Asbestos	PCME	EMSL	1/24/07	< 0.00079	No	No	
ASBESTOS-ST16-1/23/07	030702383-0011	East Face - North end at corner (scaffolding level)	1/23/07	1	3.020	Asbestos	PCME	EMSL	1/24/07	< 0.00082	No	No	
ASBESTOS-ST17-1/23/07	030702383-0012	North Face - West end at corner (scaffolding level)	1/23/07	1	3.040	Asbestos	PCME	EMSL	1/24/07	< 0.00081	No	No	