

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-3/5/07	030706882-0001	Southwest Area (sidewalk bridge level)	3/5/07	1	3.020	Asbestos	PCME	EMSL	3/6/07	< 0.00082	No	No	
ASBESTOS-ST2-3/5/07	030706882-0002	Southeast Area (sidewalk bridge level)	3/5/07	1	3.040	Asbestos	PCME	EMSL	3/6/07	< 0.00081	No	No	
ASBESTOS-ST4-3/5/07	030706882-0003	Northwest Area (street-level)	3/5/07	1	2.800	Asbestos	PCME	EMSL	3/6/07	< 0.00088	No	No	
ASBESTOS-ST5-3/5/07	030706882-0004	Firehouse #10 (roof level)	3/5/07	1	3.020	Asbestos	PCME	EMSL	3/6/07	< 0.00082	No	No	
ASBESTOS-ST10-3/5/07	030706882-0005	North Side Sidewalk Bridge	3/5/07	1	2.970	Asbestos	PCME	EMSL	3/6/07	< 0.00083	No	No	
ASBESTOS-ST11-3/5/07	030706882-0006	90 Trinity Place (roof level)	3/5/07	1	3.050	Asbestos	PCME	EMSL	3/6/07	< 0.00081	No	No	
ASBESTOS-ST12-3/5/07	030706882-0007	110 Greenwich Street (roof level)	3/5/07	1	3.040	Asbestos	PCME	EMSL	3/6/07	< 0.00081	No	No	
ASBESTOS-ST13-3/5/07	030706882-0008	Marriott Hotel, 38th Floor (roof level)	3/5/07	1	3.020	Asbestos	PCME	EMSL	3/6/07	< 0.00082	No	No	
ASBESTOS-ST1-3/6/07	030707009-0001	Southwest Area (sidewalk bridge level)	3/6/07	1	3.020	Asbestos	PCME	EMSL	3/7/07	< 0.00082	No	No	
ASBESTOS-ST2-3/6/07	030707009-0002	Southeast Area (sidewalk bridge level)	3/6/07	1	3.040	Asbestos	PCME	EMSL	3/7/07	< 0.00081	No	No	
ASBESTOS-ST4-3/6/07	030707009-0003	Northwest Area (street-level)	3/6/07	1	2.890	Asbestos	PCME	EMSL	3/7/07	< 0.00085	No	No	
ASBESTOS-ST5-3/6/07	030707009-0004	Firehouse #10 (roof level)	3/6/07	1	3.050	Asbestos	PCME	EMSL	3/7/07	< 0.00081	No	No	
ASBESTOS-ST10-3/6/07	030707009-0005	North Side Sidewalk Bridge	3/6/07	1	3.030	Asbestos	PCME	EMSL	3/7/07	< 0.00081	No	No	
ASBESTOS-ST100-3/6/07	030707009-0009	Station 10 Field Duplicate	3/6/07	1	3.020	Asbestos	PCME	EMSL	3/7/07	< 0.00082	No	No	
ASBESTOS-ST11-3/6/07	030707009-0006	90 Trinity Place (roof level)	3/6/07	1	2.980	Asbestos	PCME	EMSL	3/7/07	< 0.00083	No	No	
ASBESTOS-ST12-3/6/07	030707009-0007	110 Greenwich Street (roof level)	3/6/07	1	3.040	Asbestos	PCME	EMSL	3/7/07	< 0.00081	No	No	
ASBESTOS-ST13-3/6/07	030707009-0008	Marriott Hotel, 38th Floor (roof level)	3/6/07	1	3.030	Asbestos	PCME	EMSL	3/7/07	< 0.00081	No	No	
ASBESTOS-ST1-3/7/07	030707161-0001	Southwest Area (sidewalk bridge level)	3/7/07	1	3.030	Asbestos	PCME	EMSL	3/8/07	< 0.00081	No	No	
ASBESTOS-ST2-3/7/07	030707161-0002	Southeast Area (sidewalk bridge level)	3/7/07	1	3.030	Asbestos	PCME	EMSL	3/8/07	< 0.00081	No	No	
ASBESTOS-ST4-3/7/07	030707161-0003	Northwest Area (street-level)	3/7/07	1	3.220	Asbestos	PCME	EMSL	3/8/07	< 0.00077	No	No	
ASBESTOS-ST5-3/7/07	030707161-0004	Firehouse #10 (roof level)	3/7/07	1	3.020	Asbestos	PCME	EMSL	3/8/07	< 0.00082	No	No	
ASBESTOS-ST10-3/7/07	030707161-0005	North Side Sidewalk Bridge	3/7/07	1	2.970	Asbestos	PCME	EMSL	3/8/07	< 0.00083	No	No	
ASBESTOS-ST11-3/7/07	030707161-0006	90 Trinity Place (roof level)	3/7/07	1	3.050	Asbestos	PCME	EMSL	3/8/07	< 0.00081	No	No	
ASBESTOS-ST12-3/7/07	030707161-0007	110 Greenwich Street (roof level)	3/7/07	1	3.040	Asbestos	PCME	EMSL	3/8/07	< 0.00081	No	No	
ASBESTOS-ST13-3/7/07	030707161-0008	Marriott Hotel, 38th Floor (roof level)	3/7/07	1	3.020	Asbestos	PCME	EMSL	3/8/07	< 0.00082	No	No	

Note:

- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on March 5 and 6, 2007 were not available for analysis. Strong winds made the scaffolding stations inaccessible.
- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on March 7, 2007 were not available for analysis. Snow and ice on the scaffolding made the stations inaccessible.