

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										<b>Target Air Quality Levels</b>			
										<b>EPA Site Specific Trigger Levels</b>			
ASBESTOS-ST1-3/23/08	030808091-0001	Southwest Area (sidewalk bridge level)	3/23/08	1	2.760	Asbestos	PCME	EMSL	3/24/08	< 0.00089	No	No	
ASBESTOS-ST2-3/23/08	030808091-0002	Southeast Area (sidewalk bridge level)	3/23/08	1	3.030	Asbestos	PCME	EMSL	3/24/08	< 0.00081	No	No	
ASBESTOS-ST4-3/23/08	030808091-0003	Northwest Area (street-level)	3/23/08	1	3.050	Asbestos	PCME	EMSL	3/24/08	< 0.00081	No	No	
ASBESTOS-ST5-3/23/08	030808091-0004	Firehouse #10 (roof level)	3/23/08	1	3.040	Asbestos	PCME	EMSL	3/24/08	< 0.00081	No	No	
ASBESTOS-ST10-3/23/08	030808091-0005	North Side Sidewalk Bridge	3/23/08	1	2.920	Asbestos	PCME	EMSL	3/24/08	< 0.00085	No	No	
ASBESTOS-ST11-3/23/08	030808091-0006	90 Trinity Place (roof level)	3/23/08	1	3.000	Asbestos	PCME	EMSL	3/24/08	< 0.00082	No	No	
ASBESTOS-ST12-3/23/08	030808091-0007	110 Greenwich Street (roof level)	3/23/08	1	2.990	Asbestos	PCME	EMSL	3/24/08	< 0.00083	No	No	
ASBESTOS-ST13-3/23/08	030808091-0008	Marriott Hotel, 38th Floor (roof level)	3/23/08	1	3.010	Asbestos	PCME	EMSL	3/24/08	< 0.00082	No	No	
ASBESTOS-ST14-3/23/08	030808091-0009	West Face - South end at corner (scaffolding level)	3/23/08	1	2.980	Asbestos	PCME	EMSL	3/24/08	< 0.00083	No	No	
ASBESTOS-ST15-3/23/08	030808091-0010	South Face - East end at corner (scaffolding level)	3/23/08	1	2.990	Asbestos	PCME	EMSL	3/24/08	< 0.00008	No	No	
ASBESTOS-ST16-3/23/08	030808091-0011	East Face - North end at corner (scaffolding level)	3/23/08	1	3.020	Asbestos	PCME	EMSL	3/24/08	< 0.00082	No	No	
ASBESTOS-ST17-3/23/08	030808091-0012	North Face - West end at corner (scaffolding level)	3/23/08	1	3.020	Asbestos	PCME	EMSL	3/24/08	< 0.00082	No	No	
ASBESTOS-ST1-3/24/08	030808271-0001	Southwest Area (sidewalk bridge level)	3/24/08	1	3.020	Asbestos	PCME	EMSL	3/25/08	< 0.00082	No	No	
ASBESTOS-ST2-3/24/08	030808271-0002	Southeast Area (sidewalk bridge level)	3/24/08	1	3.060	Asbestos	PCME	EMSL	3/25/08	< 0.00081	No	No	
ASBESTOS-ST4-3/24/08	030808271-0003	Northwest Area (street-level)	3/24/08	1	3.090	Asbestos	PCME	EMSL	3/25/08	< 0.00080	No	No	
ASBESTOS-ST5-3/24/08	030808271-0004	Firehouse #10 (roof level)	3/24/08	1	3.000	Asbestos	PCME	EMSL	3/25/08	< 0.00082	No	No	
ASBESTOS-ST10-3/24/08	030808271-0005	North Side Sidewalk Bridge	3/24/08	1	3.200	Asbestos	PCME	EMSL	3/25/08	< 0.00077	No	No	
ASBESTOS-ST11-3/24/08	030808271-0006	90 Trinity Place (roof level)	3/24/08	1	3.070	Asbestos	PCME	EMSL	3/25/08	< 0.00080	No	No	
ASBESTOS-ST12-3/24/08	030808271-0007	110 Greenwich Street (roof level)	3/24/08	1	3.010	Asbestos	PCME	EMSL	3/25/08	< 0.00082	No	No	
ASBESTOS-ST13-3/24/08	030808271-0008	Marriott Hotel, 38th Floor (roof level)	3/24/08	1	3.030	Asbestos	PCME	EMSL	3/25/08	< 0.00081	No	No	
ASBESTOS-ST14-3/24/08	030808271-0009	West Face - South end at corner (scaffolding level)	3/24/08	1	3.090	Asbestos	PCME	EMSL	3/25/08	< 0.00080	No	No	
ASBESTOS-ST15-3/24/08	030808271-0010	South Face - East end at corner (scaffolding level)	3/24/08	1	3.040	Asbestos	PCME	EMSL	3/25/08	< 0.00081	No	No	
ASBESTOS-ST16-3/24/08	030808271-0011	East Face - North end at corner (scaffolding level)	3/24/08	1	3.010	Asbestos	PCME	EMSL	3/25/08	< 0.00082	No	No	
ASBESTOS-ST17-3/24/08	030808271-0012	North Face - West end at corner (scaffolding level)	3/24/08	1	3.000	Asbestos	PCME	EMSL	3/25/08	< 0.00082	No	No	