

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>										<b>0.0009</b>			
<b>EPA Site Specific Trigger Levels</b>										<b>NA</b>			
ASBESTOS-ST1-6/13/09	030914752-0001	Southwest Area (sidewalk bridge level)	6/13/09	1	3.040	Asbestos	PCME	EMSL	6/15/09	< 0.00081	No	No	
ASBESTOS-ST2-6/13/09	030914752-0002	Southeast Area (sidewalk bridge level)	6/13/09	1	3.040	Asbestos	PCME	EMSL	6/15/09	< 0.00081	No	No	
ASBESTOS-ST4-6/13/09	030914752-0003	Northwest Area (street-level)	6/13/09	1	3.010	Asbestos	PCME	EMSL	6/15/09	< 0.00082	No	No	
ASBESTOS-ST5-6/13/09	030914752-0004	Firehouse #10 (roof level)	6/13/09	1	3.110	Asbestos	PCME	EMSL	6/15/09	< 0.00079	No	No	
ASBESTOS-ST10-6/13/09	030914752-0005	North Side Sidewalk Bridge	6/13/09	1	3.010	Asbestos	PCME	EMSL	6/15/09	< 0.00082	No	No	
ASBESTOS-ST11-6/13/09	030914752-0006	90 Trinity Place (roof level)	6/13/09	1	2.970	Asbestos	PCME	EMSL	6/15/09	< 0.00083	No	No	
ASBESTOS-ST12-6/13/09	030914752-0007	110 Greenwich Street (roof level)	6/13/09	1	2.990	Asbestos	PCME	EMSL	6/15/09	< 0.00083	No	No	
ASBESTOS-ST13-6/13/09	030914752-0008	Marriott Hotel, 38th Floor (roof level)	6/13/09	1	3.010	Asbestos	PCME	EMSL	6/15/09	< 0.00082	No	No	
ASBESTOS-ST1-6/14/09	030914753-0001	Southwest Area (sidewalk bridge level)	6/14/09	1	3.060	Asbestos	PCME	EMSL	6/15/09	< 0.00081	No	No	
ASBESTOS-ST2-6/14/09	030914753-0002	Southeast Area (sidewalk bridge level)	6/14/09	1	3.140	Asbestos	PCME	EMSL	6/15/09	< 0.00079	No	No	
ASBESTOS-ST4-6/14/09	030914753-0003	Northwest Area (street-level)	6/14/09	1	3.180	Asbestos	PCME	EMSL	6/15/09	< 0.00078	No	No	
ASBESTOS-ST5-6/14/09	030914753-0004	Firehouse #10 (roof level)	6/14/09	1	3.060	Asbestos	PCME	EMSL	6/15/09	< 0.00081	No	No	
ASBESTOS-ST10-6/14/09	030914753-0005	North Side Sidewalk Bridge	6/14/09	1	3.280	Asbestos	PCME	EMSL	6/15/09	< 0.00082	No	No	
ASBESTOS-ST11-6/14/09	030914753-0006	90 Trinity Place (roof level)	6/14/09	1	3.040	Asbestos	PCME	EMSL	6/15/09	< 0.00081	No	No	
ASBESTOS-ST12-6/14/09	030914753-0007	110 Greenwich Street (roof level)	6/14/09	1	3.030	Asbestos	PCME	EMSL	6/15/09	< 0.00081	No	No	
ASBESTOS-ST13-6/14/09	030914753-0008	Marriott Hotel, 38th Floor (roof level)	6/14/09	1	3.080	Asbestos	PCME	EMSL	6/15/09	< 0.00080	No	No	
ASBESTOS-ST1-6/15/09	030914822-0001	Southwest Area (sidewalk bridge level)	6/15/09	1	2.950	Asbestos	PCME	EMSL	6/16/09	< 0.00084	No	No	
ASBESTOS-ST2-6/15/09	030914822-0002	Southeast Area (sidewalk bridge level)	6/15/09	1	2.870	Asbestos	PCME	EMSL	6/16/09	< 0.00079	No	No	
ASBESTOS-ST4-6/15/09	030914822-0003	Northwest Area (street-level)	6/15/09	1	2.940	Asbestos	PCME	EMSL	6/16/09	< 0.00084	No	No	
ASBESTOS-ST5-6/15/09	030914822-0004	Firehouse #10 (roof level)	6/15/09	1	2.980	Asbestos	PCME	EMSL	6/16/09	< 0.00083	No	No	
ASBESTOS-ST100-6/15/09	030914822-0008	Station 10 Field Duplicate	6/15/09	1	3.010	Asbestos	PCME	EMSL	6/16/09	< 0.00082	No	No	
ASBESTOS-ST11-6/15/09	030914822-0005	90 Trinity Place (roof level)	6/15/09	1	2.990	Asbestos	PCME	EMSL	6/16/09	< 0.00083	No	No	
ASBESTOS-ST12-6/15/09	030914822-0006	110 Greenwich Street (roof level)	6/15/09	1	3.080	Asbestos	PCME	EMSL	6/16/09	< 0.00080	No	No	
ASBESTOS-ST13-6/15/09	030914822-0007	Marriott Hotel, 38th Floor (roof level)	6/15/09	1	3.080	Asbestos	PCME	EMSL	6/16/09	< 0.00080	No	No	

Note:

1. The asbestos sample from Station 10 (North Side Sidewalk Bridge) on June 15, 2009 was not available for analysis as the collection media was found disconnected from the sampling pump.