

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments | |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|--------------------|------------------------------|----------|--|
| | | | | | | | | | | 0.0009 | Air Quality Levels | Site Specific Trigger Levels | | |
| | | | | | | | | | | NA | | | | |
| Target Air Quality Levels | | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | | |
| ASBESTOS-ST1-6/20/06 | 030618912-0001 | Southwest Area (sidewalk bridge level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST2-6/20/06 | 030618912-0002 | Southeast Area (sidewalk bridge level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST4-6/20/06 | 030618912-0003 | Northwest Area (street-level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST5-6/20/06 | 030618912-0004 | Firehouse #10 (roof level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST10-6/20/06 | 030618912-0005 | North Side Sidewalk Bridge | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST11-6/20/06 | 030618912-0006 | 90 Trinity Place (roof level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST12-6/20/06 | 030618912-0007 | 110 Greenwich Street (roof level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST13-6/20/06 | 030618912-0008 | Marriott Hotel, 38th Floor (roof level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST14-6/20/06 | 030618912-0009 | West Face - South end at corner (scaffolding level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST15-6/20/06 | 030618912-0010 | South Face - East end at corner (scaffolding level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST16-6/20/06 | 030618912-0011 | East Face - North end at corner (scaffolding level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST17-6/20/06 | 030618912-0012 | North Face - West end at corner (scaffolding level) | 6/20/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/21/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST1-6/21/06 | 030619076-0001 | Southwest Area (sidewalk bridge level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST2-6/21/06 | 030619076-0002 | Southeast Area (sidewalk bridge level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST4-6/21/06 | 030619076-0003 | Northwest Area (street-level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST5-6/21/06 | 030619076-0004 | Firehouse #10 (roof level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST10-6/21/06 | 030619076-0005 | North Side Sidewalk Bridge | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST11-6/21/06 | 030619076-0006 | 90 Trinity Place (roof level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST12-6/21/06 | 030619076-0007 | 110 Greenwich Street (roof level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST13-6/21/06 | 030619076-0008 | Marriott Hotel, 38th Floor (roof level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST14-6/21/06 | 030619076-0009 | West Face - South end at corner (scaffolding level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST15-6/21/06 | 030619076-0010 | South Face - East end at corner (scaffolding level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST16-6/21/06 | 030619076-0011 | East Face - North end at corner (scaffolding level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |
| ASBESTOS-ST17-6/21/06 | 030619076-0012 | North Face - West end at corner (scaffolding level) | 6/21/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/22/06 | < 0.00084 | No | No | | |