

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-7/23/07	030724623-0001	Southwest Area (sidewalk bridge level)	7/23/07	1	2.960	Asbestos	PCME	EMSL	7/24/07	< 0.00083	No	No	
ASBESTOS-ST2- 7/23/07	030724623-0002	Southeast Area (sidewalk bridge level)	7/23/07	1	3.020	Asbestos	PCME	EMSL	7/24/07	< 0.00082	No	No	
ASBESTOS-ST4- 7/23/07	030724623-0003	Northwest Area (street-level)	7/23/07	1	3.050	Asbestos	PCME	EMSL	7/24/07	< 0.00081	No	No	
ASBESTOS-ST5- 7/23/07	030724623-0004	Firehouse #10 (roof level)	7/23/07	1	3.040	Asbestos	PCME	EMSL	7/24/07	< 0.00081	No	No	
ASBESTOS-ST10- 7/23/07	030724623-0005	North Side Sidewalk Bridge	7/23/07	1	3.040	Asbestos	PCME	EMSL	7/24/07	< 0.00081	No	No	
ASBESTOS-ST100- 7/23/07	030724623-0012	Station 10 Field Duplicate	7/23/07	1	3.000	Asbestos	PCME	EMSL	7/24/07	< 0.00082	No	No	
ASBESTOS-ST11- 7/23/07	030724623-0006	90 Trinity Place (roof level)	7/23/07	1	2.920	Asbestos	PCME	EMSL	7/24/07	< 0.00085	No	No	
ASBESTOS-ST12- 7/23/07	030724623-0007	110 Greenwich Street (roof level)	7/23/07	1	2.960	Asbestos	PCME	EMSL	7/24/07	< 0.00083	No	No	
ASBESTOS-ST13- 7/23/07	030724623-0008	Marriott Hotel, 38th Floor (roof level)	7/23/07	1	3.000	Asbestos	PCME	EMSL	7/24/07	< 0.00082	No	No	
ASBESTOS-ST15- 7/23/07	030724623-0009	South Face - East end at corner (scaffolding level)	7/23/07	1	3.020	Asbestos	PCME	EMSL	7/24/07	< 0.00082	No	No	
ASBESTOS-ST16- 7/23/07	030724623-0010	East Face - North end at corner (scaffolding level)	7/23/07	1	3.040	Asbestos	PCME	EMSL	7/24/07	< 0.00081	No	No	
ASBESTOS-ST17- 7/23/07	030724623-0011	North Face - West end at corner (scaffolding level)	7/23/07	1	3.020	Asbestos	PCME	EMSL	7/24/07	< 0.00082	No	No	
ASBESTOS-ST1-7/24/07	030724855-0001	Southwest Area (sidewalk bridge level)	7/24/07	1	2.960	Asbestos	PCME	EMSL	7/25/07	< 0.00083	No	No	
ASBESTOS-ST2-7/24/07	030724855-0002	Southeast Area (sidewalk bridge level)	7/24/07	1	2.960	Asbestos	PCME	EMSL	7/25/07	< 0.00083	No	No	
ASBESTOS-ST4-7/24/07	030724855-0003	Northwest Area (street-level)	7/24/07	1	2.840	Asbestos	PCME	EMSL	7/25/07	< 0.00087	No	No	
ASBESTOS-ST5-7/24/07	030724855-0004	Firehouse #10 (roof level)	7/24/07	1	2.960	Asbestos	PCME	EMSL	7/25/07	< 0.00083	No	No	
ASBESTOS-ST10-7/24/07	030724855-0005	North Side Sidewalk Bridge	7/24/07	1	2.900	Asbestos	PCME	EMSL	7/25/07	< 0.00085	No	No	
ASBESTOS-ST11-7/24/07	030724855-0006	90 Trinity Place (roof level)	7/24/07	1	2.940	Asbestos	PCME	EMSL	7/25/07	< 0.00084	No	No	
ASBESTOS-ST12-7/24/07	030724855-0007	110 Greenwich Street (roof level)	7/24/07	1	3.070	Asbestos	PCME	EMSL	7/25/07	< 0.00080	No	No	
ASBESTOS-ST13-7/24/07	030724855-0008	Marriott Hotel, 38th Floor (roof level)	7/24/07	1	3.150	Asbestos	PCME	EMSL	7/25/07	< 0.00078	No	No	
ASBESTOS-ST14-7/24/07	030724855-0009	West Face - South end at corner (scaffolding level)	7/24/07	1	2.400	Asbestos	PCME	EMSL	7/25/07	< 0.00088	No	No	
ASBESTOS-ST15-7/24/07	030724855-0010	South Face - East end at corner (scaffolding level)	7/24/07	1	3.010	Asbestos	PCME	EMSL	7/25/07	< 0.00082	No	No	
ASBESTOS-ST16-7/24/07	030724855-0011	East Face - North end at corner (scaffolding level)	7/24/07	1	3.040	Asbestos	PCME	EMSL	7/25/07	< 0.00081	No	No	
ASBESTOS-ST17-7/24/07	030724855-0012	North Face - West end at corner (scaffolding level)	7/24/07	1	2.900	Asbestos	PCME	EMSL	7/25/07	< 0.00085	No	No	

Note:

1. Asbestos sample at Station 14 (West Face - South end at corner [scaffolding level]) on July 23, 2007 was not available for analysis on account of power failure.