

| TRC Field Sample No.                    | Sample No.     | Sampling Location                                   | Collection Start Date | Work Shift | Sample Volume (m <sup>3</sup> ) | Analyte  | Analytical Method | Lab  | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|-----------------------------------|--|----------|
| <b>Target Air Quality Levels</b>        |                |   |                       |            |                                 |          |                   |      |                         | <b>0.0009</b>                       |                                   |  |          |
| <b>EPA Site Specific Trigger Levels</b> |                |   |                       |            |                                 |          |                   |      |                         | <b>NA</b>                           |                                   |  |          |
| ASBESTOS-ST1-7/28/08                    | 030825449-0001 | Southwest Area (sidewalk bridge level)              | 7/28/08               | 1          | 3.440                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00078                           | No                                | No                                       | Note 1   |
| ASBESTOS-ST2-7/28/08                    | 030825449-0002 | Southeast Area (sidewalk bridge level)              | 7/28/08               | 1          | 3.150                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00085                           | No                                | No                                       |          |
| ASBESTOS-ST4-7/28/08                    | 030825449-0003 | Northwest Area (street-level)                       | 7/28/08               | 1          | 3.090                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00087                           | No                                | No                                       |          |
| ASBESTOS-ST5-7/28/08                    | 030825449-0004 | Firehouse #10 (roof level)                          | 7/28/08               | 1          | 3.120                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00086                           | No                                | No                                       |          |
| ASBESTOS-ST10-7/28/08                   | 030825449-0005 | North Side Sidewalk Bridge                          | 7/28/08               | 1          | 3.240                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00083                           | No                                | No                                       |          |
| ASBESTOS-ST11-7/28/08                   | 030825449-0006 | 90 Trinity Place (roof level)                       | 7/28/08               | 1          | 2.980                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00083                           | No                                | No                                       |          |
| ASBESTOS-ST12-7/28/08                   | 030825449-0007 | 110 Greenwich Street (roof level)                   | 7/28/08               | 1          | 3.100                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00087                           | No                                | No                                       |          |
| ASBESTOS-ST13-7/28/08                   | 030825449-0008 | Marriott Hotel, 38th Floor (roof level)             | 7/28/08               | 1          | 3.020                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00082                           | No                                | No                                       |          |
| ASBESTOS-ST14-7/28/08                   | 030825449-0009 | West Face - South end at corner (scaffolding level) | 7/28/08               | 1          | 3.010                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00082                           | No                                | No                                       |          |
| ASBESTOS-ST15-7/28/08                   | 030825449-0010 | South Face - East end at corner (scaffolding level) | 7/28/08               | 1          | 3.040                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00081                           | No                                | No                                       |          |
| ASBESTOS-ST16-7/28/08                   | 030825449-0011 | East Face - North end at corner (scaffolding level) | 7/28/08               | 1          | 3.040                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00081                           | No                                | No                                       |          |
| ASBESTOS-ST17-7/28/08                   | 030825449-0012 | North Face - West end at corner (scaffolding level) | 7/28/08               | 1          | 2.900                           | Asbestos | PCME              | EMSL | 7/29/08                 | < 0.00085                           | No                                | No                                       |          |
| ASBESTOS-ST1-7/29/08                    | 030825648-0001 | Southwest Area (sidewalk bridge level)              | 7/29/08               | 1          | 3.300                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00075                           | No                                | No                                       |          |
| ASBESTOS-ST2-7/29/08                    | 030825648-0002 | Southeast Area (sidewalk bridge level)              | 7/29/08               | 1          | 3.010                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00082                           | No                                | No                                       |          |
| ASBESTOS-ST4-7/29/08                    | 030825648-0003 | Northwest Area (street-level)                       | 7/29/08               | 1          | 3.120                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00079                           | No                                | No                                       |          |
| ASBESTOS-ST5-7/29/08                    | 030825648-0004 | Firehouse #10 (roof level)                          | 7/29/08               | 1          | 3.030                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00081                           | No                                | No                                       |          |
| ASBESTOS-ST10-7/29/08                   | 030825648-0005 | North Side Sidewalk Bridge                          | 7/29/08               | 1          | 3.000                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00082                           | No                                | No                                       |          |
| ASBESTOS-ST11-7/29/08                   | 030825648-0006 | 90 Trinity Place (roof level)                       | 7/29/08               | 1          | 3.050                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00081                           | No                                | No                                       |          |
| ASBESTOS-ST12-7/29/08                   | 030825648-0007 | 110 Greenwich Street (roof level)                   | 7/29/08               | 1          | 3.040                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00081                           | No                                | No                                       |          |
| ASBESTOS-ST13-7/29/08                   | 030825648-0008 | Marriott Hotel, 38th Floor (roof level)             | 7/29/08               | 1          | 3.230                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00076                           | No                                | No                                       |          |
| ASBESTOS-ST14-7/29/08                   | 030825648-0009 | West Face - South end at corner (scaffolding level) | 7/29/08               | 1          | 3.120                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00079                           | No                                | No                                       |          |
| ASBESTOS-ST15-7/29/08                   | 030825648-0010 | South Face - East end at corner (scaffolding level) | 7/29/08               | 1          | 3.000                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00082                           | No                                | No                                       |          |
| ASBESTOS-ST16-7/29/08                   | 030825648-0011 | East Face - North end at corner (scaffolding level) | 7/29/08               | 1          | 3.010                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00082                           | No                                | No                                       |          |
| ASBESTOS-ST17-7/29/08                   | 030825648-0012 | North Face - West end at corner (scaffolding level) | 7/29/08               | 1          | 3.190                           | Asbestos | PCME              | EMSL | 7/30/08                 | < 0.00077                           | No                                | No                                       |          |

Note:

1. Due to flow rate RPD exceedance (24.2%) for asbestos at Station 1 (Southwest Area Sidewalk Bridge Level) on July 28, 2008, the sample volume and subsequent sample result are estimated.