

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-8/7/06	030625346-0001	Southwest Area (sidewalk bridge level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST2-8/7/06	030625346-0002	Southeast Area (sidewalk bridge level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST4-8/7/06	030625346-0003	Northwest Area (street-level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST5-8/7/06	030625346-0004	Firehouse #10 (roof level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST6-8/7/06	030625349-0001	Southwest Area (roof level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST7-8/7/06	030625349-0002	Southeast Area (roof level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST8-8/7/06	030625349-0003	Northeast Area (roof level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST9-8/7/06	030625349-0004	Northwest Area (roof level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST10-8/7/06	030625346-0005	North Side Sidewalk Bridge	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST11-8/7/06	030625346-0006	90 Trinity Place (roof level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST12-8/7/06	030625346-0007	110 Greenwich Street (roof level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST13-8/7/06	030625346-0008	Marriott Hotel, 38th Floor (roof level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST14-8/7/06	030625346-0009	West Face - South end at corner (scaffolding level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST15-8/7/06	030625346-0010	South Face - East end at corner (scaffolding level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST16-8/7/06	030625346-0011	East Face - North end at corner (scaffolding level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST17-8/7/06	030625346-0012	North Face - West end at corner (scaffolding level)	8/7/06	1	2.970	Asbestos	PCME	EMSL	8/8/06	< 0.00083	No	No	
ASBESTOS-ST1-8/8/06	030625493-0001	Southwest Area (sidewalk bridge level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST2-8/8/06	030625493-0002	Southeast Area (sidewalk bridge level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST4-8/8/06	030625493-0003	Northwest Area (street-level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST5-8/8/06	030625493-0004	Firehouse #10 (roof level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST6-8/8/06	030625491-0001	Southwest Area (roof level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST7-8/8/06	030625491-0002	Southeast Area (roof level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST8-8/8/06	030625491-0003	Northeast Area (roof level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST9-8/8/06	030625491-0004	Northwest Area (roof level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST10-8/8/06	030625493-0005	North Side Sidewalk Bridge	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST100-8/8/06	030625493-0013	Station 10 Field Duplicate	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST11-8/8/06	030625493-0006	90 Trinity Place (roof level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST12-8/8/06	030625493-0007	110 Greenwich Street (roof level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST13-8/8/06	030625493-0008	Marriott Hotel, 38th Floor (roof level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST14-8/8/06	030625493-0009	West Face - South end at corner (scaffolding level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST15-8/8/06	030625493-0010	South Face - East end at corner (scaffolding level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST16-8/8/06	030625493-0011	East Face - North end at corner (scaffolding level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	
ASBESTOS-ST17-8/8/06	030625493-0012	North Face - West end at corner (scaffolding level)	8/8/06	1	2.970	Asbestos	PCME	EMSL	8/9/06	< 0.00083	No	No	