

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
<b>Target Air Quality Levels</b>													
<b>EPA Site Specific Trigger Levels</b>													
ASBESTOS-ST1-8/14/06	030626368-0001	Southwest Area (sidewalk bridge level)	8/14/06	1	3.060	Asbestos	PCME	EMSL	8/15/06	< 0.00081	No	No	
ASBESTOS-ST2-8/14/06	030626368-0002	Southeast Area (sidewalk bridge level)	8/14/06	1	3.020	Asbestos	PCME	EMSL	8/15/06	< 0.00082	No	No	
ASBESTOS-ST4-8/14/06	030626368-0003	Northwest Area (street-level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST5-8/14/06	030626368-0004	Firehouse #10 (roof level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST6-8/14/06	030626371-0001	Southwest Area (roof level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST7-8/14/06	030626371-0002	Southeast Area (roof level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST8-8/14/06	030626371-0003	Northeast Area (roof level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST9-8/14/06	030626371-0004	Northwest Area (roof level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST10-8/14/06	030626368-0005	North Side Sidewalk Bridge	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST11-8/14/06	030626368-0006	90 Trinity Place (roof level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST12-8/14/06	030626368-0007	110 Greenwich Street (roof level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST13-8/14/06	030626368-0008	Marriott Hotel, 38th Floor (roof level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST14-8/14/06	030626368-0009	West Face - South end at corner (scaffolding level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST15-8/14/06	030626368-0010	South Face - East end at corner (scaffolding level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST16-8/14/06	030626368-0011	East Face - North end at corner (scaffolding level)	8/14/06	1	2.970	Asbestos	PCME	EMSL	8/15/06	< 0.00083	No	No	
ASBESTOS-ST17-8/14/06	030626368-0012	North Face - West end at corner (scaffolding level)	8/14/06	1	3.060	Asbestos	PCME	EMSL	8/15/06	< 0.00081	No	No	
ASBESTOS-ST1-8/15/06	030626602-0001	Southwest Area (sidewalk bridge level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST2-8/15/06	030626602-0002	Southeast Area (sidewalk bridge level)	8/15/06	1	3.020	Asbestos	PCME	EMSL	8/16/06	< 0.00082	No	No	
ASBESTOS-ST4-8/15/06	030626602-0003	Northwest Area (street-level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST5-8/15/06	030626602-0004	Firehouse #10 (roof level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST6-8/15/06	030626607-0001	Southwest Area (roof level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST7-8/15/06	030626607-0002	Southeast Area (roof level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST8-8/15/06	030626607-0003	Northeast Area (roof level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST9-8/15/06	030626607-0004	Northwest Area (roof level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST10-8/15/06	030626602-0005	North Side Sidewalk Bridge	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST11-8/15/06	030626602-0006	90 Trinity Place (roof level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST12-8/15/06	030626602-0007	110 Greenwich Street (roof level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST13-8/15/06	030626602-0008	Marriott Hotel, 38th Floor (roof level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST14-8/15/06	030626602-0009	West Face - South end at corner (scaffolding level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST15-8/15/06	030626602-0010	South Face - East end at corner (scaffolding level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST16-8/15/06	030626602-0011	East Face - North end at corner (scaffolding level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	
ASBESTOS-ST17-8/15/06	030626602-0012	North Face - West end at corner (scaffolding level)	8/15/06	1	2.970	Asbestos	PCME	EMSL	8/16/06	< 0.00083	No	No	