

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-9/13/06	030630117-0001	Southwest Area (sidewalk bridge level)	9/13/06	1	2.900	Asbestos	PCME	EMSL	9/14/06	< 0.00085	No	No	
ASBESTOS-ST2-9/13/06	030630117-0002	Southeast Area (sidewalk bridge level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST4-9/13/06	030630117-0003	Northwest Area (street-level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST5-9/13/06	030630117-0004	Firehouse #10 (roof level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST6-9/13/06	030630113-0001	Southwest Area (roof level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST7-9/13/06	030630113-0002	Southeast Area (roof level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST8-9/13/06	030630113-0003	Northeast Area (roof level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST9-9/13/06	030630113-0004	Northwest Area (roof level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST10-9/13/06	030630117-0005	North Side Sidewalk Bridge	9/13/06	1	3.090	Asbestos	PCME	EMSL	9/14/06	< 0.00080	No	No	
ASBESTOS-ST11-9/13/06	030630117-0006	90 Trinity Place (roof level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST12-9/13/06	030630117-0007	110 Greenwich Street (roof level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST13-9/13/06	030630117-0008	Marriott Hotel, 38th Floor (roof level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST14-9/13/06	030630117-0009	West Face - South end at corner (scaffolding level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST15-9/13/06	030630117-0010	South Face - East end at corner (scaffolding level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST16-9/13/06	030630117-0011	East Face - North end at corner (scaffolding level)	9/13/06	1	2.840	Asbestos	PCME	EMSL	9/14/06	< 0.00087	No	No	
ASBESTOS-ST17-9/13/06	030630117-0012	North Face - West end at corner (scaffolding level)	9/13/06	1	3.020	Asbestos	PCME	EMSL	9/14/06	< 0.00082	No	No	
ASBESTOS-ST1-9/14/06	030630313-0001	Southwest Area (sidewalk bridge level)	9/14/06	1	3.150	Asbestos	PCME	EMSL	9/15/06	< 0.00078	No	No	
ASBESTOS-ST2-9/14/06	030630313-0002	Southeast Area (sidewalk bridge level)	9/14/06	1	3.340	Asbestos	PCME	EMSL	9/15/06	< 0.00074	No	No	
ASBESTOS-ST4-9/14/06	030630313-0003	Northwest Area (street-level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST5-9/14/06	030630313-0004	Firehouse #10 (roof level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST6-9/14/06	030630314-0001	Southwest Area (roof level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST7-9/14/06	030630314-0002	Southeast Area (roof level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST8-9/14/06	030630314-0003	Northeast Area (roof level)	9/14/06	1	2.990	Asbestos	PCME	EMSL	9/15/06	< 0.00083	No	No	
ASBESTOS-ST9-9/14/06	030630314-0004	Northwest Area (roof level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST10-9/14/06	030630313-0005	North Side Sidewalk Bridge	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST11-9/14/06	030630313-0006	90 Trinity Place (roof level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST12-9/14/06	030630313-0007	110 Greenwich Street (roof level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST13-9/14/06	030630313-0008	Marriott Hotel, 38th Floor (roof level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST14-9/14/06	030630313-0009	West Face - South end at corner (scaffolding level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST15-9/14/06	030630313-0010	South Face - East end at corner (scaffolding level)	9/14/06	1	3.020	Asbestos	PCME	EMSL	9/15/06	< 0.00082	No	No	
ASBESTOS-ST16-9/14/06	030630313-0011	East Face - North end at corner (scaffolding level)	9/14/06	1	2.960	Asbestos	PCME	EMSL	9/15/06	< 0.00083	No	No	
ASBESTOS-ST17-9/14/06	030630313-0012	North Face - West end at corner (scaffolding level)	9/14/06	1	3.060	Asbestos	PCME	EMSL	9/15/06	< 0.00081	No	No	