

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-9/27/07	030732456-0001	Southwest Area (sidewalk bridge level)	9/27/07	1	3.090	Asbestos	PCME	EMSL	9/28/07	< 0.00080	No	No	
ASBESTOS-ST2-9/27/07	030732456-0002	Southeast Area (sidewalk bridge level)	9/27/07	1	3.020	Asbestos	PCME	EMSL	9/28/07	< 0.00082	No	No	
ASBESTOS-ST4-9/27/07	030732456-0003	Northwest Area (street-level)	9/27/07	1	3.060	Asbestos	PCME	EMSL	9/28/07	< 0.00081	No	No	
ASBESTOS-ST5-9/27/07	030732456-0004	Firehouse #10 (roof level)	9/27/07	1	3.010	Asbestos	PCME	EMSL	9/28/07	< 0.00082	No	No	
ASBESTOS-ST10-9/27/07	030732456-0005	North Side Sidewalk Bridge	9/27/07	1	2.990	Asbestos	PCME	EMSL	9/28/07	< 0.00083	No	No	
ASBESTOS-ST11-9/27/07	030732456-0006	90 Trinity Place (roof level)	9/27/07	1	3.000	Asbestos	PCME	EMSL	9/28/07	< 0.00082	No	No	
ASBESTOS-ST12-9/27/07	030732456-0007	110 Greenwich Street (roof level)	9/27/07	1	3.020	Asbestos	PCME	EMSL	9/28/07	< 0.00082	No	No	
ASBESTOS-ST13-9/27/07	030732456-0008	Marriott Hotel, 38th Floor (roof level)	9/27/07	1	3.010	Asbestos	PCME	EMSL	9/28/07	< 0.00082	No	No	
ASBESTOS-ST14-9/27/07	030732456-0009	West Face - South end at corner (scaffolding level)	9/27/07	1	2.970	Asbestos	PCME	EMSL	9/28/07	< 0.00083	No	No	
ASBESTOS-ST15-9/27/07	030732456-0010	South Face - East end at corner (scaffolding level)	9/27/07	1	3.040	Asbestos	PCME	EMSL	9/28/07	< 0.00081	No	No	
ASBESTOS-ST16-9/27/07	030732456-0011	East Face - North end at corner (scaffolding level)	9/27/07	1	3.000	Asbestos	PCME	EMSL	9/28/07	< 0.00082	No	No	
ASBESTOS-ST17-9/27/07	030732456-0012	North Face - West end at corner (scaffolding level)	9/27/07	1	2.970	Asbestos	PCME	EMSL	9/28/07	< 0.00083	No	No	
ASBESTOS-ST1-9/28/07	030732536-0001	Southwest Area (sidewalk bridge level)	9/28/07	1	3.040	Asbestos	PCME	EMSL	9/29/07	< 0.00081	No	No	
ASBESTOS-ST2-9/28/07	030732536-0002	Southeast Area (sidewalk bridge level)	9/28/07	1	3.020	Asbestos	PCME	EMSL	9/29/07	< 0.00082	No	No	
ASBESTOS-ST4-9/28/07	030732536-0003	Northwest Area (street-level)	9/28/07	1	3.010	Asbestos	PCME	EMSL	9/29/07	< 0.00082	No	No	
ASBESTOS-ST5-9/28/07	030732536-0004	Firehouse #10 (roof level)	9/28/07	1	3.040	Asbestos	PCME	EMSL	9/29/07	< 0.00081	No	No	
ASBESTOS-ST10-9/28/07	030732536-0005	North Side Sidewalk Bridge	9/28/07	1	3.010	Asbestos	PCME	EMSL	9/29/07	< 0.00082	No	No	
ASBESTOS-ST100-9/28/07	030732536-0012	Station 10 Field Duplicate	9/28/07	1	2.970	Asbestos	PCME	EMSL	9/29/07	< 0.00083	No	No	
ASBESTOS-ST12-9/28/07	030732536-0006	110 Greenwich Street (roof level)	9/28/07	1	2.960	Asbestos	PCME	EMSL	9/29/07	< 0.00083	No	No	
ASBESTOS-ST13-9/28/07	030732536-0007	Marriott Hotel, 38th Floor (roof level)	9/28/07	1	3.000	Asbestos	PCME	EMSL	9/29/07	< 0.00082	No	No	
ASBESTOS-ST14-9/28/07	030732536-0008	West Face - South end at corner (scaffolding level)	9/28/07	1	2.980	Asbestos	PCME	EMSL	9/29/07	< 0.00083	No	No	
ASBESTOS-ST15-9/28/07	030732536-0009	South Face - East end at corner (scaffolding level)	9/28/07	1	3.030	Asbestos	PCME	EMSL	9/29/07	< 0.00081	No	No	
ASBESTOS-ST16-9/28/07	030732536-0010	East Face - North end at corner (scaffolding level)	9/28/07	1	3.020	Asbestos	PCME	EMSL	9/29/07	< 0.00082	No	No	
ASBESTOS-ST17-9/28/07	030732536-0011	North Face - West end at corner (scaffolding level)	9/28/07	1	2.970	Asbestos	PCME	EMSL	9/29/07	< 0.00083	No	No	

Note:

1. Asbestos sample at Station 11 (90 Trinity Place [roof level]) on September 28, 2007 was not available for analysis on account of operator error.