

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-11/24/08	030841760-0001	Southwest Area (sidewalk bridge level)	11/24/08	1	3.010	Asbestos	PCME	EMSL	11/25/08	< 0.00082	No	No	
ASBESTOS-ST2-11/24/08	030841760-0002	Southeast Area (sidewalk bridge level)	11/24/08	1	3.000	Asbestos	PCME	EMSL	11/25/08	< 0.00082	No	No	
ASBESTOS-ST4-11/24/08	030841760-0003	Northwest Area (street-level)	11/24/08	1	3.050	Asbestos	PCME	EMSL	11/25/08	< 0.00081	No	No	
ASBESTOS-ST5-11/24/08	030841760-0004	Firehouse #10 (roof level)	11/24/08	1	3.100	Asbestos	PCME	EMSL	11/25/08	< 0.00080	No	No	
ASBESTOS-ST10-11/24/08	030841760-0005	North Side Sidewalk Bridge	11/24/08	1	2.980	Asbestos	PCME	EMSL	11/25/08	< 0.00083	No	No	
ASBESTOS-ST11-11/24/08	030841760-0006	90 Trinity Place (roof level)	11/24/08	1	3.040	Asbestos	PCME	EMSL	11/25/08	< 0.00081	No	No	
ASBESTOS-ST12-11/24/08	030841760-0007	110 Greenwich Street (roof level)	11/24/08	1	3.030	Asbestos	PCME	EMSL	11/25/08	< 0.00081	No	No	
ASBESTOS-ST13-11/24/08	030841760-0008	Marriott Hotel, 38th Floor (roof level)	11/24/08	1	3.060	Asbestos	PCME	EMSL	11/25/08	< 0.00081	No	No	
ASBESTOS-ST14-11/24/08	030841760-0009	West Face - South end at corner (scaffolding level)	11/24/08	1	3.090	Asbestos	PCME	EMSL	11/25/08	< 0.00080	No	No	
ASBESTOS-ST15-11/24/08	030841760-0010	South Face - East end at corner (scaffolding level)	11/24/08	1	3.030	Asbestos	PCME	EMSL	11/25/08	< 0.00081	No	No	
ASBESTOS-ST16-11/24/08	030841760-0011	East Face - North end at corner (scaffolding level)	11/24/08	1	3.040	Asbestos	PCME	EMSL	11/25/08	< 0.00081	No	No	
ASBESTOS-ST17-11/24/08	030841760-0012	North Face - West end at corner (scaffolding level)	11/24/08	1	3.070	Asbestos	PCME	EMSL	11/25/08	< 0.00080	No	No	
ASBESTOS-ST1-11/25/08	030841884-0001	Southwest Area (sidewalk bridge level)	11/25/08	1	3.120	Asbestos	PCME	EMSL	11/26/08	< 0.00079	No	No	
ASBESTOS-ST2-11/25/08	030841884-0002	Southeast Area (sidewalk bridge level)	11/25/08	1	3.090	Asbestos	PCME	EMSL	11/26/08	< 0.00080	No	No	
ASBESTOS-ST4-11/25/08	030841884-0003	Northwest Area (street-level)	11/25/08	1	3.040	Asbestos	PCME	EMSL	11/26/08	< 0.00081	No	No	
ASBESTOS-ST5-11/25/08	030841884-0004	Firehouse #10 (roof level)	11/25/08	1	2.970	Asbestos	PCME	EMSL	11/26/08	< 0.00083	No	No	
ASBESTOS-ST10-11/25/08	030841884-0005	North Side Sidewalk Bridge	11/25/08	1	3.050	Asbestos	PCME	EMSL	11/26/08	< 0.00088	No	No	
ASBESTOS-ST11-11/25/08	030841884-0006	90 Trinity Place (roof level)	11/25/08	1	3.050	Asbestos	PCME	EMSL	11/26/08	< 0.00088	No	No	
ASBESTOS-ST12-11/25/08	030841884-0007	110 Greenwich Street (roof level)	11/25/08	1	2.970	Asbestos	PCME	EMSL	11/26/08	< 0.00083	No	No	
ASBESTOS-ST13-11/25/08	030841884-0008	Marriott Hotel, 38th Floor (roof level)	11/25/08	1	3.090	Asbestos	PCME	EMSL	11/26/08	< 0.00087	No	No	
ASBESTOS-ST14-11/25/08	030841884-0009	West Face - South end at corner (scaffolding level)	11/25/08	1	2.950	Asbestos	PCME	EMSL	11/26/08	< 0.00084	No	No	
ASBESTOS-ST15-11/25/08	030841884-0010	South Face - East end at corner (scaffolding level)	11/25/08	1	2.960	Asbestos	PCME	EMSL	11/26/08	< 0.00083	No	No	
ASBESTOS-ST16-11/25/08	030841884-0011	East Face - North end at corner (scaffolding level)	11/25/08	1	2.880	Asbestos	PCME	EMSL	11/26/08	< 0.00086	No	No	
ASBESTOS-ST17-11/25/08	030841884-0012	North Face - West end at corner (scaffolding level)	11/25/08	1	3.040	Asbestos	PCME	EMSL	11/26/08	< 0.00081	No	No	
ASBESTOS-ST1-11/26/08	030841985-0001	Southwest Area (sidewalk bridge level)	11/26/08	1	3.070	Asbestos	PCME	EMSL	11/28/08	< 0.00080	No	No	
ASBESTOS-ST2-11/26/08	030841985-0002	Southeast Area (sidewalk bridge level)	11/26/08	1	3.080	Asbestos	PCME	EMSL	11/28/08	< 0.00080	No	No	
ASBESTOS-ST4-11/26/08	030841985-0003	Northwest Area (street-level)	11/26/08	1	3.040	Asbestos	PCME	EMSL	11/28/08	< 0.00081	No	No	
ASBESTOS-ST5-11/26/08	030841985-0004	Firehouse #10 (roof level)	11/26/08	1	3.020	Asbestos	PCME	EMSL	11/28/08	< 0.00082	No	No	
ASBESTOS-ST10-11/26/08	030841985-0005	North Side Sidewalk Bridge	11/26/08	1	2.880	Asbestos	PCME	EMSL	11/28/08	< 0.00086	No	No	
ASBESTOS-ST11-11/26/08	030841985-0006	90 Trinity Place (roof level)	11/26/08	1	3.070	Asbestos	PCME	EMSL	11/28/08	< 0.00080	No	No	
ASBESTOS-ST12-11/26/08	030841985-0007	110 Greenwich Street (roof level)	11/26/08	1	3.020	Asbestos	PCME	EMSL	11/28/08	< 0.00082	No	No	
ASBESTOS-ST13-11/26/08	030841985-0008	Marriott Hotel, 38th Floor (roof level)	11/26/08	1	3.020	Asbestos	PCME	EMSL	11/28/08	< 0.00082	No	No	
ASBESTOS-ST14-11/26/08	030841985-0009	West Face - South end at corner (scaffolding level)	11/26/08	1	2.900	Asbestos	PCME	EMSL	11/28/08	< 0.00085	No	No	
ASBESTOS-ST15-11/26/08	030841985-0010	South Face - East end at corner (scaffolding level)	11/26/08	1	2.870	Asbestos	PCME	EMSL	11/28/08	< 0.00086	No	No	
ASBESTOS-ST16-11/26/08	030841985-0011	East Face - North end at corner (scaffolding level)	11/26/08	1	2.910	Asbestos	PCME	EMSL	11/28/08	< 0.00085	No	No	
ASBESTOS-ST17-11/26/08	030841985-0012	North Face - West end at corner (scaffolding level)	11/26/08	1	2.870	Asbestos	PCME	EMSL	11/28/08	< 0.00086	No	No	
ASBESTOS-ST1-11/27/08	030841980-0001	Southwest Area (sidewalk bridge level)	11/27/08	1	3.120	Asbestos	PCME	EMSL	11/28/08	< 0.00086	No	No	
ASBESTOS-ST2-11/27/08	030841980-0002	Southeast Area (sidewalk bridge level)	11/27/08	1	3.100	Asbestos	PCME	EMSL	11/28/08	< 0.00087	No	No	
ASBESTOS-ST4-11/27/08	030841980-0003	Northwest Area (street-level)	11/27/08	1	3.030	Asbestos	PCME	EMSL	11/28/08	< 0.00081	No	No	
ASBESTOS-ST5-11/27/08	030841980-0004	Firehouse #10 (roof level)	11/27/08	1	3.010	Asbestos	PCME	EMSL	11/28/08	< 0.00082	No	No	
ASBESTOS-ST10-11/27/08	030841980-0005	North Side Sidewalk Bridge	11/27/08	1	2.990	Asbestos	PCME	EMSL	11/28/08	< 0.00083	No	No	
ASBESTOS-ST11-11/27/08	030841980-0006	90 Trinity Place (roof level)	11/27/08	1	3.090	Asbestos	PCME	EMSL	11/28/08	< 0.00087	No	No	
ASBESTOS-ST12-11/27/08	030841980-0007	110 Greenwich Street (roof level)	11/27/08	1	3.080	Asbestos	PCME	EMSL	11/28/08	< 0.00087	No	No	
ASBESTOS-ST13-11/27/08	030841980-0008	Marriott Hotel, 38th Floor (roof level)	11/27/08	1	3.080	Asbestos	PCME	EMSL	11/28/08	< 0.00087	No	No	
ASBESTOS-ST14-11/27/08	030841980-0009	West Face - South end at corner (scaffolding level)	11/27/08	1	3.060	Asbestos	PCME	EMSL	11/28/08	< 0.00081	No	No	
ASBESTOS-ST15-11/27/08	030841980-0010	South Face - East end at corner (scaffolding level)	11/27/08	1	3.030	Asbestos	PCME	EMSL	11/28/08	< 0.00081	No	No	
ASBESTOS-ST16-11/27/08	030841980-0011	East Face - North end at corner (scaffolding level)	11/27/08	1	3.060	Asbestos	PCME	EMSL	11/28/08	< 0.00081	No	No	
ASBESTOS-ST17-11/27/08	030841980-0012	North Face - West end at corner (scaffolding level)	11/27/08	1	3.030	Asbestos	PCME	EMSL	11/28/08	< 0.00081	No	No	
ASBESTOS-ST1-11/28/08	030842068-0001	Southwest Area (sidewalk bridge level)	11/28/08	1	3.100	Asbestos	PCME	EMSL	11/29/08	< 0.00087	No	No	
ASBESTOS-ST2-11/28/08	030842068-0002	Southeast Area (sidewalk bridge level)	11/28/08	1	3.110	Asbestos	PCME	EMSL	11/29/08	< 0.00087	No	No	
ASBESTOS-ST4-11/28/08	030842068-0003	Northwest Area (street-level)	11/28/08	1	3.080	Asbestos	PCME	EMSL	11/29/08	< 0.00087	No	No	
ASBESTOS-ST5-11/28/08	030842068-0004	Firehouse #10 (roof level)	11/28/08	1	3.100	Asbestos	PCME	EMSL	11/29/08	< 0.00087	No	No	
ASBESTOS-ST10-11/28/08	030842068-0005	North Side Sidewalk Bridge	11/28/08	1	3.130	Asbestos	PCME	EMSL	11/29/08	< 0.00086	No	No	
ASBESTOS-ST11-11/28/08	030842068-0006	90 Trinity Place (roof level)	11/28/08	1	3.050	Asbestos	PCME	EMSL	11/29/08	< 0.00081	No	No	
ASBESTOS-ST12-11/28/08	030842068-0007	110 Greenwich Street (roof level)	11/28/08	1	2.980	Asbestos	PCME	EMSL	11/29/08	< 0.00083	No	No	
ASBESTOS-ST13-11/28/08	030842068-0008	Marriott Hotel, 38th Floor (roof level)	11/28/08	1	3.040	Asbestos	PCME	EMSL	11/29/08	< 0.00081	No	No	
ASBESTOS-ST14-11/28/08	030842068-0009	West Face - South end at corner (scaffolding level)	11/28/08	1	3.070	Asbestos	PCME	EMSL	11/29/08	< 0.00088	No	No	
ASBESTOS-ST15-11/28/08	030842068-0010	South Face - East end at corner (scaffolding level)	11/28/08	1	3.020	Asbestos	PCME	EMSL	11/29/08	< 0.00082	No	No	
ASBESTOS-ST16-11/28/08	030842068-0011	East Face - North end at corner (scaffolding level)	11/28/08	1	3.080	Asbestos	PCME	EMSL	11/29/08	< 0.00087	No	No	
ASBESTOS-ST17-11/28/08	030842068-0012	North Face - West end at corner (scaffolding level)	11/28/08	1	3.120	Asbestos	PCME	EMSL	11/29/08	< 0.00086	No	No	