

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-12/27/05	030538582-0001	Southwest Area (sidewalk bridge level)	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST2-12/27/05	030538582-0002	Southeast Area (sidewalk bridge level)	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST4-12/27/05	030538582-0003	Northwest Area (street-level)	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST5-12/27/05	030538582-0004	Firehouse #10 (roof level)	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST10-12/27/05	030538582-0005	North Side Sidewalk Bridge	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST11-12/27/05	030538582-0006	90 Trinity Place (roof level)	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST12-12/27/05	030538582-0007	110 Greenwich Street (roof level)	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST14-12/27/05	030538582-0009	West Face - South end at corner	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST15-12/27/05	030538582-0010	South Face - East end at corner	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST16-12/27/05	030538582-0011	East Face - North end at corner	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST17-12/27/05	030538582-0012	North Face - West end at corner	12/27/05	1	2.97	Asbestos	PCME	EMSL	12/28/05	< 0.00083	No	No	
ASBESTOS-ST1-12/28/05	030538768-0001	Southwest Area (sidewalk bridge level)	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST2-12/28/05	030538768-0002	Southeast Area (sidewalk bridge level)	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST4-12/28/05	030538768-0003	Northwest Area (street-level)	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST5-12/28/05	030538768-0004	Firehouse #10 (roof level)	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST10-12/28/05	030538768-0005	North Side Sidewalk Bridge	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST11-12/28/05	030538768-0006	90 Trinity Place (roof level)	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST12-12/28/05	030538768-0007	110 Greenwich Street (roof level)	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST13-12/28/05	030538768-0008	Marriott Hotel, 38th Floor (roof level)	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST14-12/28/05	030538768-0009	West Face - South end at corner	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST15-12/28/05	030538768-0010	South Face - East end at corner	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST16-12/28/05	030538768-0011	East Face - North end at corner	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	
ASBESTOS-ST17-12/28/05	030538768-0012	North Face - West end at corner	12/28/05	1	2.97	Asbestos	PCME	EMSL	12/29/05	< 0.00083	No	No	

Note:

1. Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on December 27, 2005 was not available for analysis due to damage to the sample filter.