

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-1/29/2010	Southwest Area (sidewalk bridge level)	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST2-1/29/2010	Southeast Area (sidewalk bridge level)	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST4-1/29/2010	Northwest Area (street-level)	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST5-1/29/2010	Firehouse #10 (roof level)	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST11-1/29/2010	90 Trinity Place (roof level)	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM10-ST12-1/29/2010	110 Greenwich Street (roof level)	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST13-1/29/2010	Marriott Hotel, 38th Floor (roof level)	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST20-1/29/2010	Northeast Area, Sidewalk Bridge	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST200-1/29/2010	Station 20 Field Duplicate	1/29/10	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST1-1/30/2010	Southwest Area (sidewalk bridge level)	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST2-1/30/2010	Southeast Area (sidewalk bridge level)	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST4-1/30/2010	Northwest Area (street-level)	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST5-1/30/2010	Firehouse #10 (roof level)	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST11-1/30/2010	90 Trinity Place (roof level)	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST12-1/30/2010	110 Greenwich Street (roof level)	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST13-1/30/2010	Marriott Hotel, 38th Floor (roof level)	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST20-1/30/2010	Northeast Area, Sidewalk Bridge	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST200-1/30/2010	Station 20 Field Duplicate	1/30/10	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST1-1/31/2010	Southwest Area (sidewalk bridge level)	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST2-1/31/2010	Southeast Area (sidewalk bridge level)	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST4-1/31/2010	Northwest Area (street-level)	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST5-1/31/2010	Firehouse #10 (roof level)	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST11-1/31/2010	90 Trinity Place (roof level)	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST12-1/31/2010	110 Greenwich Street (roof level)	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-1/31/2010	Marriott Hotel, 38th Floor (roof level)	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST20-1/31/2010	Northeast Area, Sidewalk Bridge	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST200-1/31/2010	Station 20 Field Duplicate	1/31/10	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	