TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-2/19/2007	Southwest Area (sidewalk bridge level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST2-2/19/2007	Southeast Area (sidewalk bridge level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST4-2/19/2007	Northwest Area (street-level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST5-2/19/2007	Firehouse #10 (roof level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST10-2/19/2007	North Side Sidewalk Bridge	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST100-2/19/2007	Station 10 Field Duplicate	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST11-2/19/2007	90 Trinity Place (roof level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST12-2/19/2007	110 Greenwich Street (roof level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST13-2/19/2007	Marriott Hotel, 38th Floor (roof level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-2/19/2007	West Face - South end at corner (scaffolding level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST15-2/19/2007	South Face - East end at corner (scaffolding level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST16-2/19/2007	East Face - North end at corner (scaffolding level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST17-2/19/2007	North Face - West end at corner (scaffolding level)	2/19/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST1-2/20/2007	Southwest Area (sidewalk bridge level)	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST2-2/20/2007	Southeast Area (sidewalk bridge level)	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST4-2/20/2007	Northwest Area (street-level)	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST5-2/20/2007	Firehouse #10 (roof level)	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST10-2/20/2007	North Side Sidewalk Bridge	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST100-2/20/2007	Station 10 Field Duplicate	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST11-2/20/2007	90 Trinity Place (roof level)	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST12-2/20/2007	110 Greenwich Street (roof level)	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST13-2/20/2007	Marriott Hotel, 38th Floor (roof level)	2/20/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	

Note:

^{1.} The PM 10 readings at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on February 20, 2007 were not available on account of power failure.