

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-3/20/2009	Southwest Area (sidewalk bridge level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST2-3/20/2009	Southeast Area (sidewalk bridge level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST4-3/20/2009	Northwest Area (street-level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST5-3/20/2009	Firehouse #10 (roof level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST10-3/20/2009	North Side Sidewalk Bridge	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST100-3/20/2009	Station 10 Field Duplicate	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST11-3/20/2009	90 Trinity Place (roof level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST12-3/20/2009	110 Greenwich Street (roof level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST13-3/20/2009	Marriott Hotel, 38th Floor (roof level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST15-3/20/2009	South Face - East end at corner (scaffolding level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST16-3/20/2009	East Face - North end at corner (scaffolding level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST17-3/20/2009	North Face - West end at corner (scaffolding level)	3/20/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-3/21/2009	Southwest Area (sidewalk bridge level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST2-3/21/2009	Southeast Area (sidewalk bridge level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST4-3/21/2009	Northwest Area (street-level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST5-3/21/2009	Firehouse #10 (roof level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST10-3/21/2009	North Side Sidewalk Bridge	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST11-3/21/2009	90 Trinity Place (roof level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST12-3/21/2009	110 Greenwich Street (roof level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST13-3/21/2009	Marriott Hotel, 38th Floor (roof level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST14-3/21/2009	West Face - South end at corner (scaffolding level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST16-3/21/2009	East Face - North end at corner (scaffolding level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-3/21/2009	North Face - West end at corner (scaffolding level)	3/21/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST1-3/22/2009	Southwest Area (sidewalk bridge level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-3/22/2009	Southeast Area (sidewalk bridge level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST4-3/22/2009	Northwest Area (street-level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST5-3/22/2009	Firehouse #10 (roof level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST10-3/22/2009	North Side Sidewalk Bridge	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST11-3/22/2009	90 Trinity Place (roof level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-3/22/2009	110 Greenwich Street (roof level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST13-3/22/2009	Marriott Hotel, 38th Floor (roof level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST14-3/22/2009	West Face - South end at corner (scaffolding level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST15-3/22/2009	South Face - East end at corner (scaffolding level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-3/22/2009	East Face - North end at corner (scaffolding level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST17-3/22/2009	North Face - West end at corner (scaffolding level)	3/22/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	

Note:

1. The PM10 reading from Station 14 (West Face - South end at corner [scaffolding level]) on March 20, 2009 was not available on account of power failure.
2. The PM10 reading from Station 15 (South Face - East end at corner [scaffolding level]) on March 21, 2009 was not available on account of instrument malfunction.
3. The PM10 readings from Station 100 (Station 10 Field Duplicate) on March 21 and 22, 2009 were not available on account of instrument malfunction.